

## Inspection Summary

inopeoelon ourinnary	
Object Inspected	FLEETEQUIPMENT 4706
Location	80197
Status	Overall Pass
Inspected By	SINCLAIR, TAYLOR
Date	6/16/2023 10:00:00 AM
Summary	Overall pass. Unit has a cracked rear left side bumper, it is missing paint on the driver's door, there is surface rust on the roof.
Repairs Made	
Recommendations	

## Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	white	
Colour - Interior	grey/black	
Wheel Drive	2x4	
Body Style	Hatch Back	
Engine Size		
Damage		
Declaration over		
\$2,000		
Estimated		
Damage Amount		
Body Condition	Fair	
Body Damage	Yes	
Mechanical	Unknown	
Transmission	No	
Operable		
Interior	Good	
Interior Dirty	Yes	
Tires	Good	
Windshield	Good	
Jack Assembly	Yes	
Spare Tire	Yes	
Check all Vehicle	Rear Wiper	
Options that		

apply		
Check all Vehicle	Air	
Options that	Conditioning	
apply		
Check all Vehicle	Alarm	
Options that	System	
apply		
Check all Vehicle	Power Door	
Options that	Locks	
apply		
Check all Vehicle	AM/FM	
Options that	Radio	
apply		
Hours or	107728	
Odometer (Blank		
if N/A)		

## Add Signature and Date Fields Here?

## Work Order Details

Assigned To:	Location:			
Supervisor:	80197			
	[Instructions: [WOInstruction	s]Accomplishment Units to		
Work Status: WORK IN	be recorded as Requested By	: Project Name: Account:		
PROGRESS	7401Receiving Account (IPTs): Asset Details:			
Scheduled	FLEETEQUIPMENT			
Start: 5/9/2023	Name	Value		
3:26:52 PM	OBJECTID	2		
Scheduled Finish: 5/9/2023 3:26:52 PM	ASSETID	4706		
	UNITNO	80197		
	MAKE	ΤΟΥΟΤΑ		
	MODEL	PRIUS		
	MODELYEAR	2010		
	VIN	JTDKN3DU4A0116215		
	DESCRIPTION	HYBRID CAR		
	EQUIPMENTTYPE	PASSENGER		
	EQUITMENTITIE	VEHICLE		
	FUELTYPE	GASOLINE		
	METERTYPE	KILOMETERS		
	FLEETSTATUS	OUT OF SERVICE		
		(SALE PENDING)		
	NSCCLASSIFICATION	NON NSC		
	LINKEDUNITNO			
	AXELCOUNT			
	LICENSEPLATE	CK151E		
	GVW			
	LICENSEDGVW			
	ACQUIREDATE	3/1/2010 12:00:00 AM		
	ACQUIRECOST	32100		
	DEPARTMENT	COMMUNITY & PROTECTIVE		

https://cwprodsvr.kamloops.ca/cityworks/Workmanagement/Printing/PrintPreview.aspx?lightenform=true&InspectionId=24002

Print Preview - Cityworks

	SERVICES
DIVISION	COMMUNITY SERVICES
SUBDIVISION	UNKNOWN
LOCATION	80197
ADDRESS	
WARRANTYDATE	
WARRANTYODOMETERHRS	
WARRANTYNOTES	
CONDITION	6
CONDITIONDATE	
CONDITIONCOMMENT	Move to disposa
SECURELINK	
DOCUMENTATIONLINK	
ODOMETER	
HOURSMETER	
AGE	12
USEFULLIFE	10
REMAININGLIFE	-2
DISPOSALDATE	
DISPOSALVALUE	
DEPRECIATIONLIFE	10
REPLACEMENTYEAR	0
CURRENTREPLACEMENTCOST	65000