

City of Kamloops Inspection: 21596 FLEET_Decommission Inspection

Parent Work Order _

409017

Inspection Summary

inspection summary	
Object Inspected	FLEETEQUIPMENT 84081
Location	84081
Status	Overall Pass
Inspected By	SINCLAIR, TAYLOR
Date	6/16/2023 10:00:00 AM
Summary	Conventional cab tandem axle automated side load refuse truck. Left rear side dent and surface rust. Right side door seal coming off. Front bumper missing.
Repairs Made	
Recommendations	

Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	white	
Colour - Interior	grey/black	
Wheel Drive	2x4	
Body Style	2 Door	
Engine Size	Navistar N9	
Damage	No	
Declaration over		
\$2,000		
Estimated		
Damage Amount		
Body Condition	Fair	
Body Damage	Yes	
Mechanical	Unknown	
Transmission	No	
Operable		
Interior	Fair	
Interior Dirty	Yes	
Tires	Fair	
Windshield	Good	
Jack Assembly	No	
Spare Tire	No	

Check all Vehicle		
Options that		
apply		
Hours or	9384	
Odometer (Blank		
if N/A)		

Add Signature and Date Fields Here?

Location:

Work Order Details

Assigned To: Supervisor:

Work Status: WORK

IN PROGRESS

Scheduled Start: 4/4/2023 1:46:21 PM Scheduled Finish: 4/4/2023 1:46:21 PM

84081 [Instructions: [WOInstructions]Accomplishment Units to be recorded as Requested By: Project Name: Account: 7401Receiving Account (IPTs): Asset Details:

FLEETEQUII Name	Value	
OBJECTID	302	
ASSETID	84081	
UNITNO	84081	
MAKE	INTERNATIONAL	
MODEL		
MODELYEAR	2016	
VIN	1HTWGSTT7GH10535	
DESCRIPTION	SIDE LOAD	
DESCRIPTION	GARBAGE TRUCK	
EQUIPMENTTYPE	HEAVY DUTY TRUCK	
FUELTYPE	DIESEL	
METERTYPE	HOURS	
FLEETSTATUS	OUT OF SERVICE	
TLEETSTATUS	(SALE PENDING)	
NSCCLASSIFICATION	NSC CVIP	
LINKEDUNITNO		
AXELCOUNT		
LICENSEPLATE	JT7276	
GVW		
LICENSEDGVW	26100	
ACQUIREDATE	8/6/2015 12:00:00 AM	
ACQUIRECOST	301625	
DEPARTMENT	CIVIC OPERATIONS	
DIVISION	STREETS &	
DIVISION	ENVIRONMENT	
SUBDIVISION	SOLID WASTE	
LOCATION	84081	
ADDRESS		
WARRANTYDATE		
WARRANTYODOMETERHRS		
WARRANTYNOTES		
CONDITION	6	
CONDITIONDATE		
CONDITIONCOMMENT		

SECURELINK	
DOCUMENTATIONLINK	
DDOMETER	
HOURSMETER	
AGE	7
USEFULLIFE	8
REMAININGLIFE	1
DISPOSALDATE	
DISPOSALVALUE	
DEPRECIATIONLIFE	8
REPLACEMENTYEAR	2023
CURRENTREPLACEMENTCOST	500000