



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-01611WO

Closing Date

Account:

,

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours: 3,003

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 65,922

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	New Unit Rig Up: De rig unit	0.25		CA\$ 0.00
Repair Story: Punch #1 (Line 1) - 08/24/2026: -checked for keys,not in the board -checked yard for unit, unit not here				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-01147WO

Closing Date Jun 30, 2026

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours: 2,995

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 105,527

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - GPS Tracking Service: Install Geo tech GPS	0.5		CA\$ 0.00
Repair Story: Adam Kohler - 06/25/2026: Made WO				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-01147WO

Closing Date Jun 30, 2026



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00461WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours: 2,983

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 105,164

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Service / PM - Rental Return Inspection: Post rental	1		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00461WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01244WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours: 1

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 64,230

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Battery Replace: battery dead in morning.	3.5		CA\$ 0.00

Repair Story: Scott Dancy - 07/22/2025: found battery draining out of the top of battery. replaced battery.

Cory Thorburn - 07/23/2025: install battery disconnect, had to make wires longer

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
82-2103	BATTERY DISCONNECT	1	\$34.3

Parts Total for Line: \$34.30

Labour Billed:CA\$ 0.00

Parts Total: \$34.3

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 34.30

Work Order Total after GST: CA\$ 36.02



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01244WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01936WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours: 2,809

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 100,937

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Engine - Spark Plug Replace: unit requires tune up	4.5		CA\$ 0.00

Repair Story: remove air box and intake, remove coils, plugs and wires, extract pill from coil, rebuild coils, install new plugs and wires, reinstall coils, install intake and air box, install new headlights right side

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	: Spark plugs for unit			CA\$ 0.00

Repair Story: Purchased from Lamb Ford

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Drivetrain - Hub / Drum Service: Fix 4x4 not engaging in auto	4		CA\$ 0.00

Repair Story: Found vacuum seals in front hubs were leaking, removed wheels, brakes and hubs removed axle, changed seal and reassembled, torqued wheels to spec



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01936WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Brakes - Brake Shoe / Pad Replace: Front brake pads low	1.5		CA\$ 0.00
Repair Story: installed new pads while doing vac seals				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01886WO

Closing Date

Account:

CN Railways Fleet management
PO box 8100
Montreal, Quebec Canada H3C3N4

Customer PO:

Unit:	10101010	Serial Number:	1FT7W3B61LEE998211FT7W 3B61LEE99821
Manufacturer:	FordFord	Model:	F350F-350
Year:	20202020		
Hours:	2,809	KM's:	100,937

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Service / PM - Rental Return Inspection: post rental inspection	1.5	CA\$ 150.00	CA\$ 225.00

Repair Story: pull unit in and go through

could use a tune up, right side low beams not working top and bottom, needs tires rotated for front right having abnormal wear, front bumper is damaged due to rail gear raising too high and hitting bottom, chipped windshield, 2way radio laying loose on floor, overdue on service, could use a detail, front brakes about 30% left

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Drivetrain - Hub / Drum Service: diagnose 4X4 issue	1.5	CA\$ 150.00	CA\$ 225.00

Repair Story: test 4X4, check vacuum, lock and unlock hubs, found vacuum seals leaking and pushing through hubs

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Electrical - Headlight Replace: diagnose right side low beams not working	1	CA\$ 150.00	CA\$ 150.00

Repair Story: pull air box, test power and ground, found both top and bottom bulbs to be burnt out



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01886WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	: service and inspection	1	CA\$ 150.00	CA\$ 150.00

Repair Story: change oil and oil filter, needs new air filter, top up all fluids, check lights, grease unit

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Tires - Tire Rotation: rotate tires	1	CA\$ 150.00	CA\$ 150.00

Repair Story: pull wheels and rotate, reinstall, torque, tag, mark and pics

Parts:

Labour Billed:CA\$ 900.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 1,087.70

Work Order Total after GST: CA\$ 1,142.09



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01126WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours: 2,617

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 94,592

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Service / PM - Rental Return Inspection: Rental inspection	1		CA\$ 0.00
Repair Story: Completed inspection				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01126WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00941WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours: 2,602

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 94,382

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Service / PM - Rental Return Inspection: rental inspection	1		CA\$ 0.00
Repair Story: completed inspection				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00941WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00512WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours:

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Ordered tonneau cover for this unit.			CA\$ 0.00
Repair Story: Purchased from Lamb Ford.				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 703.50

Work Order Total after GST: CA\$ 738.68



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00512WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00129WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours:

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 88,700

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Ordered wiper blades, air filter, and u joint.			CA\$ 0.00
Repair Story: Purchased from Lamb Ford.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Diagnose and Advise - General Inspection / Walkaround: Inspection	1		CA\$ 0.00
Repair Story: same				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Electrical - Wiper Blade Replace: Change wiper blades	0.25		CA\$ 0.00
Repair Story: same				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00129WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Intake - Air Filter Replace - Primary: Change Air filter	0.25		CA\$ 0.00
Repair Story: same				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Drivetrain - U-Joint Replace: Change u-joint(Transfer case to rear)	1.5		CA\$ 0.00
Repair Story: Removed u-joint installed				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 217.39

Work Order Total after GST: CA\$ 228.26



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023845

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours:

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 80,733

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Service / PM - Rental Return Inspection: service and rental inspection	1.5		CA\$ 0.00
Repair Story: oil and filter changed cabin filter changed rental inspection complete				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023845

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023080

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Serial Number:

Manufacturer:

Model:

Year:

Hours:

KM's: 67,987

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: SERVICE AND LEVEL 1			CA\$ 0.00
Repair Story:				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	General - Other (Specify in Detail): REPLACE FIRE EXT			CA\$ 0.00
Repair Story:				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Electrical - Gauge Cluster Repair: REPAIR FUEL GAUGE			CA\$ 0.00
Repair Story:				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023080

Closing Date

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-01647WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1010

Manufacturer: Ford

Year: 2020

Hours: 30,012

Serial Number: 1FT7W3B61LEE99821

Model: F350

KM's: 66,334

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	General - Other (Specify in Detail): Low on coolant and windshield washer	0.5		CA\$ 0.00

Repair Story: Punch #1 (Line 1) - 08/28/2026: Tooped up coolant and washer fluid checked for leaks

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	General - Other (Specify in Detail): Remove All RTRC gear, LEAVE BEACON!!!	2.5		CA\$ 0.00

Repair Story: Punch #2 (Line 2) - 08/28/2026:

Punch #3 (Line 2) - 08/28/2026: Pulled out radio, gps

Punch #4 (Line 2) - 08/28/2026: Removed fire extinguisher and bracket.

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-01647WO

Closing Date

Work Order Total after GST: CA\$ 0.00