



Vossler Mechanical

1797 6 Avenue SW
Medicine Hat, AB T1A 8B1
403-526-2443
vmech@shaw.ca

Invoice

Bill To Holt, Richard

Cell (306) 490-2338
Brenda +1 4035044983
Email Winterholt@shaw.ca

Invoice # 9747
Work Order # 24231
Service Advisor Ryan M
Technician Kris C

Plate AB CKV-9988
Description 2007 Ford Expedition Limited V8 5.4L 330CID
VIN 5
VIN 1FMFK20567LA18194
Odometer 273,640
Invoice Date 3/24/2022 12:34 PM
Appointment 2/28/2022 12:00 PM
Promised 2/28/2022 5:00 PM

Service

Insurance Inspection

Insurance Inspection \$120.00 G
Insurance Inspection

Scanned Vehicle For Codes

- P0113 Intake Air Temp Sensor Circuit Input High
- P0128 Coolant Thermostat Stuck Open
- P0300 Random Misfire
- P0304 Cylinder 4 Misfire Detected
- P0305 Cylinder 5 Misfire Detected
- P0316 Misfire Detected First 1000 Rev
- P0430 Cat Efficiency Below Threshold Bank 2
- Idler Pulley Has Play And Is Causing Noise, TPMS Light On
- ,Right Front Brake Caliper Seized On, RR Brake Pad Separated From Backing Plate,

Sub \$120.00

Disc Brake Pads, Rotors & Calipers (Front)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$204.00 G
Disc Brake Pad	1 Unit	\$180.28 / Unit	\$180.28 G
Disc Brake Rotor	2 Unit	\$176.88 / Unit	\$353.76 G
Disc Brake Caliper Right Front	1 Unit	\$207.57 / Unit	\$207.57 G
Disc Brake Caliper Left Front	1 Unit	\$207.57 / Unit	\$207.57 G
Wheel Nut M14-2.0	1 Unit	\$8.74 / Unit	\$8.74 G
		Sub	\$1,161.92

Disc Brake Pads & Rotors (Rear)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$132.00 G
Disc Brake Pad	1 Unit	\$66.48 / Unit	\$66.48 G
Disc Brake Rotor	2 Unit	\$90.42 / Unit	\$180.84 G
		Sub	\$379.32

Spark Plug(s)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor \$385.00 G

GST # 830155651

Changed Worn Out Spark Plugs, Got Cylinder Misfires To
 Stop Vehicle Still Has Slight Stumble Found Cam Phasers
 Causing Slight Stumble
 Spark Plug

8 Unit	\$30.57 / Unit	\$244.56 G
	Sub	\$629.56

Provincial Safety Inspection
 Out Of Province Inspection

1 Unit	\$172.49 / Unit	\$172.49 G
	Sub	\$172.49

Fuel
 Fuel Added

1 Unit	\$25.00 / Unit	\$25.00 G
	Sub	\$25.00

Total Parts		\$1,474.80
Total Labor		\$841.00
Total Sublet		\$172.49
Total Before Taxes & Miscellaneous Charges		\$2,488.29
(*) Shop Supplies / Environmental Compliance Fees / Hazardous Waste		\$42.05 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$126.52
Grand Total		\$2,656.86

Holt, Richard paid \$2,656.86 by Visa Card

Thanks for the Business!
 I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: _____