JT Repair 227 Meadowbrook Dr E		INVOICE	MAY 1 6 2012
Brooks, Alberta T1R 1N6		Invoice No.:	168 24/04/2012
		Date:	
		Unit	457
		PO	457
		Hours	6321
Sold to:	Ship to:	<b>D</b> ( 11-1	
Eastern Irrigation District	Eastern Irrigati P.O. Bag 8	on District	
P.O. Bag 8 550 Industrial Road West Brooks, AB_T1R 1B2	550 Industrial I Brooks, AB_T	Road West IR 1B2	

#### Business No.:

а

Business No.: Item No.	Unit	Quantity	Description	Тах	Unit Price	Amount
Shop Rate Shop Rate Shop Rate	Hour Hour Hour	37.0	R&R transmission and reseal clutch packs, replace MFWD shaft, checkover and assemble. Replace leaking outrigger hose Repair engine oil leak		115.00 115.00 115.00	4,255.00 57.50 57.50
			Subtotal:			4,370.00
			GST Number: 814066809RT0001			
hipped By:	Tracking Nur	mber:				
comment: Tha	nk you for your busine	ess!			Total Amount	4,370.00
old By:						



•

Brandt Tractor Ltd. 3555 - 46th Ave. S.E. Calgary, AB T2B 3B3 (403) 248-0018



S				PAGE				
õ	EASTERN	IRRIGATIO	N DIST	PAGE	S H	EASTERN	IRRIGA	IN DIST
Ĺ	C/O AAM	D & C		1		EASTERN	IRRIGA	IN DIST
D		ARROW DRIV	'E	CASH CHG. OTHER	P		JSTRIAL F	
		AB T9E 8N5				BROOKS	AB T1R 1	
Т				ACCT. NO	Т	BROOMS		, _
0				40000185	ο			
SALESMAN	ORDER NO.	RO. NO.	PHONE	INVOICE DATE	TIME	INVOICE NO		
492		0.0000000	700 426 0275	08MAY12	05:21		04	1410044
	UNIT 457	00052200	780-436-9375	UOMATIZ	05.21			1419344 EXEMPTION FOR THE PARTY OF THE PARTY
	SHIPPED B/O	PAR	INUMBER	DESCRIPTION	BIN	LIST		XTENSION
VINCENED	STUDDECHRO/CAR						12	
		MAKE: .			ERNO:	T0410EX83		1RS :
	1	N T158744		CY		20.56	20.5;	20.56
	1	N T158749	5 Ring	CY		15.95	15.9;	15.95
	5	N T158742	2 Ring		VGF3	4.48	4.4}	22.40
	1	N T161181	l O-Rin	ıg	VEE6	5.96	5.9;	5.96
	1	N T26955	_ Clamp	C Y		6.73	6.73	6.73
	2	N R26906	- 0-Rin		V D H 3	4.72	4.7 ?	9.44
	2	N R27474	Drain	•	VFH7	9.63	9.63	19.26
	1	N T141689	0-Rin		VEE5	4.90	4.9)	4.90
	1	N_T19854	0-Rin	5	VEF2	4.40	4.4)	4.40
	2	N T19854	0-Rin	•	VEF2	4.40	4.4)	8.80
	1	N T162446		-	FILE8	9.57	9.57	
	1	N T162935		-	FILE8			9.57
	1			-		21.99	21.9}	21.99
	2				C602	36.67	31.156	31.15
· · · ·	_	N T158739	5	CY		11.32	11.32	22.64
	2	N T158743	5	CY		4.78	4.73	9.56
	1	N AT10156			B 2 0 4	6.96	5.9LI	5.91
	1	N AT18420		ilte	B301	57.32	48.7)	48.70
			) BY JOSH					
		Tax ID:						
		TRAN Onive	OUTPUT SHA	TO REPA	ein Bi	ROKUN	#FRONT	w Hore
					DECC	RIPTION	ACCOUN	
	ET 30 DAYS FR( INVOICE					TIPTION	ACCOUN	
RETURNED BY ACCORDING TO ON THIS INVOL OF GOODS.	N BE RETURNED WI (PERMISSION WHI ORDER ARE SUBJECT ICE WILL BE CONSIL	THOUT OUR PERMISSI H WERE FURNISHED TOA HANDLING CHARGE DERED AFTER 30 DAYS DNTH (18% ANNUM).	CORRECTLY BRANDT TRA	ITEMS REMAIN WITH CTOR LTD. UNTIL ICE, INTEREST AND IES ARE FULLY PAID.	PARTS SALES TA	١x		
SIGNATURE	3		DATE		PLEASE P	PAY THIS TOT		CONTINUE
						DA	CKING SU	LF-11

PACKING SLI

LF-1137C Ver. 501





S O	EASTERN	IRRIGATIO	N DIST	PAGE	S	EASTERN	IRRIGATI	N DIST	
ĩ	C/O AAM			1	н		IRRIGATI		
D		ARROW DRIV	F	CASH CHG. OTHER	P		ISTRIAL R		
_		AB T9E 8N5		x	•		AB T1R 1		
т			on on	ACCT. NO	Т	DROOKO			
0				40000185	0	, specific to ward the	- 50	a fill a second a	
SALESMAN	ORDER NO.	RO. NO.	PHONE	INVOICE DATE	TIME	INVOICE NO			
	UNIT 457	00651361	780-436-9375	26APR12	13:38		04	448773	
THESE CONTRACTOR STREET, NO.	QUANTITIES						PRICE		
ORDERED	SHIPPED B/O	PAR	TNUMBER	DESCRIPTION	BIN	LIST	NET	ECTENSION	
		MAKE:	JD MODEL:	S	ERNO:			IIRS :	
	2	N T69938	Half	Clam	VHB2	4.98	4.98	9.96	
	4	N T11312			VCG1	3.55	3.5	14.20	
	1	N AT1827	35 Univ	ersal	D703	562.94	562.94	562.94	
	1	N T15107	2 Flan		H502	411.51	411.5:	411.51	
	1	N T15957	-	Shie	VBE4	5.23	5.2	5.23	
	1	N AT1794	66 Seal		VAD5	23.03	23.0	23.03	
	1	N AT1794	<b>~ ~</b>	red R	VDJ3	141.72	141.7;	141.72	
	1	N T15885				852.80	852.8		
8	1 -	N AT1794		red RCY				64.83	
	1	N AT1794			E411	28.32			
	1	N AT1793	16 Seal		VAD5	50.67			
	1	N F37030			FILE2	6.59			
	1	N FREIGH				15.00		15.00	
		Tax ID	):		2	15.00	15.07	15.00	
			****	*******	******	*****	******	**	
		**	PARTS HOURS:				7AM - 4P 1		
		** 24	HOUR EMERGENC						
		** A	LL ELECTRICAL	COMPONEN	TS ARE	NON DETH	a SALE)	**	
		** ALL	RETURNS ARE	SUBJECT T		DESTOCK	TNC FEE	**	
			L FABRICATED					**	
		*****	****						
		10	400 56330						
		10	100 10 3 30	p An	49 1-	2			
1					· .				
TERMS:	NET 30 DAYS F				DES	SCRIPTION	ACCOUN'	AMOUNT	-
DATE O	<b>OF INVOICE</b>	SHIP VIA			PARTS	TAXABLE			
NO GOODS	CAN BE RETURNED	WITHOUT OUR PERMIS	SSION. GOODS TITLES TO A	LL ITEMS REMAIN WI	TH		4	2171.80	
ACCORDING	TO ORDER ARE SUBJEC	HICH WERE FURNISHE	CE NOCLARE PURCHASE	RACTOR LTD. UNT PRICE, INTEREST A			4	21/1.80	
ON THIS IN OF GOODS.	VOICE WILL BE CON	SIDERED AFTER 30 DA'	YS OF RECEIPT OTHER CHA	RGES ARE FULLY PA			e e	15 00	
PAST DUE I	NTEREST   1/2% PER	MONTH (18% ANNUM).			MISC SALES	NONTAXABL	<b>c</b>	15.00	
MINIMUM	CHARGE OF \$1.50				SALED				
0.0								2196 00	-
SIGNATU	JRE		DATE		PLEASE	PAY THIS TO	TAL 🕨	2186.80	
						P/	ACKING SL	LF	-1137C Ver. 501



Brandt Tractor Ltd. 10121 Batlow Trail NE Calgary, Alberta T3J 3C6 PH: (403) 248-0018



JOHN DEERE

S O L D	EASTERN C/O RMA 2510 SP	ARF	XOW DRI	VE		PAGE 1 CASH CHG. OTHER	S H I P	EASTERN 550 INDU	IRRIGATI IRRIGATI STRIAL R AB T1R 1	ON DIST OAD
т 0	NISKU	A B	T9E 8N!	5 C	A	ACCT. NO 4 0 0 0 0 1 8 5	T O	BROOKS	AR LIK I	DΖ
ALESMAN	ORDER NO.	RO.	NO.	PHONE		INVOICE DATE	TIME	INVOICE NO		
	15.7	0.0	013597	780.4	36-9375	19N0V20	17:17		04	4455263
32	9.5 / QUANTITIES	00	913387	700.4	30-3375	19110120	And the second se		PRICES	
	SHIPPED B/O	N	PAR	TNUMBER		DESCRIPTION	BIN	LIST	NET	EXTENSION
			MAKE:	חו	MODEL:	S	ERNO:			HRS:
	1	N	T15581				D12N20	454.61	454.61	454.61
	1		T13367				VCF5	4.02	4.02	4.02
	1		24H128		WAS		VKD4	3.42	3.42	3.42
	1		T76833	<b>-</b>	WAS		VCI2	6.24	6.24	6.24
	1		T76832		WAS		VCI2	10.29	10.29	10.29
			** PA ** 24 ** A ** ALL ** AL **	***** RTS HC HOUR E LL ELE RETUF L FABF BF	******** DURS: MO EMERGENC ECTRICAL RNS ARE RICATED RANDT AC GLASS DA	N-THU 7A-S Y ON CALL COMPONENT SUBJECT TO HYDRAULIC CEPTS NO T MAGED DUR	+ * * * * * * * P F R I P A R T S , T S A R E D A 30% H O S E S R E S P O N S I N G T R #	7A-6P SA SERVICE NON RETU RESTOCK ARE FINA SIBILITY	7A-4P & SALES RNABLE ING FEE SALE FOR	* * * * * * * * * * * *
							DE	SCRIPTION	ACCOUNT	AMOUNT
	NET 30 DAYS FI F INVOICE	ROM	SHIP VIA DE	B BROO	к5		PARTS	TAXABLE		
NO GOODS ( RETURNED ACCORDING ON THIS INV OF GOODS. PAST DUE IN	A INVOICE CAN BE RETURNED BY PERMISSION WI TO ORDER ARE SUBJE VOICE WILL BE CON VTEREST   1/2% PER HARGE OF \$1.50	HICH W CT TO A SIDERI	VERE FURNISHE HANDLING CHAR ED AFTER 30 DA	D CORRECTL GE: NO CLAIM	S PURCHASE	LL ITEMS REMAIN WT RACTOR LTD UNT PRICE, INTEREST A RGES ARE FULLY PA	TH TH PARTS ID MISC	NONTAXBI TAXABLE NONTAXAB		478.58



Invoice To Account No : 6111144

			High River, AB Melfort, SK		Rocky View, AB Rosthern, SK	403-280-2200	
Cervus Equipment	Claresholm, AB		Olds, AB			306-933-3303	
Box 760, Highway 873 North Brooks, AB T1R 1B7 Phone: (403) 362-3486	Drumheller, AB	250-431-9002 403-823-8484	Ponoka, AB Prince Albert, SK	403-627-4451 403-783-3337 306-763-6686 403-343-2238	Trochu, AB Vulcan, AB	403-742-4427 403-442-3982 403-485-2231 306-946-3362	JOHN DEERE

Deliver To Account No : 6111144

www.cervusequipment.com

### PARTS INVOICE

invoice io	Account No	0111144	10.	Deliver to Account No	0111144			
EASTER	N IRRIGAT	ION DISTRICT		EASTERN IRRIGATI	ON DISTRICT	Invoice No:	93	30007
P.O. BO	X 128			P.O. BOX 128		Date:	12/16	/2019
	S AB T1R	1B2		BROOKS AB T1R 1	B2	Page:		1 of 1
CA				CA		Payment Type:	Ac	count
Bus Ph: 40	03-362-1400	Prv Ph:		Bus Ph: 403-362-1400	Prv Ph:			
Supplied Quantity	Back Order Quantity	Part Number	•	art Description	Bin Loc	Net Price	Extended Price	Tax Ind
3.00	0.00	R74012	S	EALING WA	DR15-5	3.71	\$11.13	N
1.00	0.00	DZ110617	F	uel Pump	GG14	155.88	\$155.88	Ν

		Parts:	\$167.01
Customer PO No:		Misc:	\$0.00
Tax Exempt No:	ON FILE	Deposit:	\$0.00
Salesperson:	NATHAN	Total:	\$167.01

GST Registration No: 831712963

COPY CHANGON DEC 17 a7 8182 HAS

#### TERMS AND CONDITIONS

Payment is due upon receipt. Late charge of 2% per month(24% per annum). Minimum charge of \$1.50

No goods can be returned without our permission. Goods returned by permission which were furnished correctly according to order are subject to a handling charge. No claims on this invoice will be considered after 30 days of receipt of goods. Titles to all items remain with Cervus Equipment until purchase price, interest and other charges are fully paid. Past due interest 2% per month(14% per annum). Minimum charge of \$1.50

Received by: Entherman Date:





S O L D T O	C / O 2 5 1 0	RMA SP/	ARF	RRIGATIC ROW DRIV T9E 8N5	E		РА <b>GE</b> 1 САЗН СНG. ОТНЕА X АССТ. NO 4 0 0 0 0 1 8 5	S H P T O	EARL 403 550 INDU	IRRIGATI -793-575 STRIAL R AB T1R 1	6 0 A D	IST
SALESMAN	ORDER NO.		RO.	NO.	PHONE		INVOICE DATE	TIME	INVOICE NO			
193	75657		0 0	859747	780-43	86-9375	28JAN19	16:18		04	4413	472
	QUANTITI	ES					1	BIN		PRICES		
ORDERED	SHIPPED	B/0		PARI	NUMBER		DESCRIPTION	DIIN	LIST	NET	EXT	ENSION
	1 1		N	** PAR ** 24 H ** AL ** ALL ** ALL **	TS HOU OUR EN L ELEC RETURN FABRI BR/ GI	BELT STATES BELT STRICAL STRIC	LT CY	P FRI PARTS, S ARE A 30% HOSES ESPONS NG TRA	169.39 251.15 19.00 ******** 7A-6P SAT SERVICE NON RETUF RESTOCKI ARE FINAL IBILITY F NSPORT	7A-4P & SALES NABLE NG FEE SALE OR	2 5 1 *** ** ** ** ** ** **	9.39 1.15 9.00
								DES	CRIPTION	ACCOUNT	A	NOUNT
ERMS: NI		S FRO	M	SHIP VIA BRO	OKS DE	5		PARTS T	AXABLE			
DATE OF		NED WIT	 ног	T OUR PERMISSI	ON. GOODS	TITLES TO ALL	ITEMS REMAIN WITH CTOR LTD. UNTIL			-	4	20.54
ETURNED BY	PERMISSIO ORDER ARE S ICE WILL BE	N WHICH	I WE DAH ERED	RE FURNISHED ( ANDLING CHARGE AFTER 30 DAYS	CORRECTLY NO CLAIMS	BRANDT TRA PURCHASE PR OTHER CHARG	CTOR LTD. UNTI ICE, INTEREST ANI ES ARE FULLY PAID	MISC T	A X A B L E O N T A X A B L			19.00
	2					DATE		PLEASE	PAY THIS TO		4	39.54

PACKING SLIP



	Bassano, AB	403-641-3813	High River, AB	403-652-7797	Rocky View, AB	403-280-2200	
Cervus Equipment	Brooks, AB Claresholm, AB	403-362-3486 403-625-4421	Melfort, SK Olds, AB	306-752-9344 403-556-0901	Rosthern, SK Saskatoon, SK	306-232-4852 306-933-3303	
Box 760, Highway 873 North	Coronation, AB	403-578-3744	Pincher Creek, AB	403-627-4451	Stettler, AB	403-742-4427	
Brooks, AB T1R 1B7	Creston, BC	250-431-9002	Ponoka, AB	403-783-3337	Trochu, AB	403-442-3982	JOHN DEERE
Phone: (403) 362-3486	Drumheller, AB	403-823-8484	Prince Albert, SK	306-763-6686	Vulcan, AB	403-485-2231	
110110. (400) 002-0400	Hanna, AB	403-854-3334	Red Deer, AB	403-343-2238	Watrous, SK	306-946-3362	

www.cervusequipment.com

### PARTS INVOICE

Invoice To	Account No.:	6111144	Deliver To Account	t No.: 6111144	PART	'S INVO	ICE
EASTER	N IRRIGAT	ION DISTRICT	EASTERN IRRI	GATION DISTRICT	Invoice No:	70	08315
P.O. BO)			P.O. BOX 128		Date:	2/6	/2019
	S AB T1R	1B2	BROOKS AB T	TR 1B2	Page:		1 of 1
CA			CA		Payment Type:	Ac	count
Bus Ph: 40	3-362-1400	Prv Ph:	Bus Ph: 403-362-14	00 Prv Ph:			
Supplied Quantity	Back Order Quantity	Part Number	Part Description	Bin Loc	Net Price	Extended Price	Tax Ind
3.00	0.00	TY26532	Shim Kit		8.74	\$26.22	N
1.00	0.00	AT145797	Floodlamp		117.05	\$117.05	Ν
1.00	0.00	AT163950	Floodlamp		117.30	\$117.30	Ν

Invoice Notes:

CALL EARL WHEN IN 793-5756

		Parts:	\$260.57
Customer PO No:	UNIT 457	Misc:	\$0.00
Tax Exempt No:	ON FILE	Deposit:	\$0.00
Salesperson:	NATHAN	Total:	\$260.57
			<b>\$200</b> .07

#### GST Registration No: 831712963

COPY

#### TERMS AND CONDITIONS

Payment is due upon receipt. Late charge of 2% per month(24% per annum). Minimum charge of \$1.50

No goods can be returned without our permission. Goods returned by permission which were furnished correctly according to order are subject to a handling charge. No claims on this invoice will be considered after 30 days of receipt of goods. Titles to all items remain with Cervus Equipment until purchase price, interest and other charges are fully paid. Past due interest 2% per month(14% per annum). Minimum charge of \$1.50

Received by: Calara And Date:



.

KIRK'S TIRE BROOKS LTD. 620 AQUADUCT DRIVE BOX 1769 BROOKS AB T1R 1C5 Phone: (403)362-6647 Fax: (403)362-6680

JAN 3 0 2019

### **INVOICE B143077**

SOLD TO: EASTIR EASTERN IRRIGATION DISTRICT P.O. BOX 128

CONTACT: SHOP --- 3621446--CH565263-19 Jan 29

BROOK T1R 1B		AB	11	NVOICE TO	D:			
TEL: 40	03 362-1400	FAX: 403 36	26206				PAGE	: 1
YEAR	MAKE		MODEL				ENGINE	
PLATE NO	BACKHOE VIN		ODOMETER		UNIT	NO.	WRITTE	N BY
	· · · · · · · · · · · · · · · · · · ·		0		457		BV	
TIME IN	PROMISED	TERMS	GST#		P.O.		TAG	
10:16 AM		NET 30	R86617151					
QTY	ITEM/DESCRIPTION		SIZE	TAX	RETAIL	%	NET	EXT.PRICE
2	GST Exemption UNKN 45T175 GOODYEAR IT525 R-4		21L-24		1105.00	0	1105.00	2210.00
2	TTOTRS				40.00	0	40.00	80.00
2	TIRE RECYCLING FEE CTD CHGOVER TRACTOR 21LX24 CHANGEOVER L *	DRY 19 Jan 2			100.00		100.00	200.00
1	100289				370.00	0	370.00	370.00
1	GALAXY BEEFY BABY I TTI TIRE RECYCLING FEE				4.00	0	4.00	4.00
1	CTD CHGOVER TRACTOR 12.5/80X18 CHANGEOU	R DRY 19 Jan 2	5		40.00		40.00	40.00

Payment Method: OnAccount=2904.00

\*\*PLEASE REMEMBER TO HAVE YOUR TIRES RE-TORQUED AT 100KM'S - IT'S YOUR RESPONSIBILITY\*\*

10-400-56	335	
10-400+56z	PARTS:	2580.00
Electron BFGoodrich UNIROYAL TOVOTIRES Mational	LABOUR:	240.00
LETHBRIDGE CARDSTON TABER BROOKS REDCLIFF CALGARY RED DEER EDMONTON	OTHER:	84.00
403-327-5985 403-653-4914 403-223-3441 403-362-6647 403-548-3941 403-243-8811 403-347-1004 780-488-9911	SUB-TOTAL:	2904.00
Name: Signature:	GST:	N/C
With the above signature Lagree to the terms below and acknowledge indeptedness for the total amount owing as shown hereon, or in the encount of any choose or credit card given in payment and later dishonored. A SERVICE	PST:	N/C
CHARGE OF 26.86% PER ANNUM (2% PER MONTH) WILL BE CHARGED ON PAST DUE ACCOUNTS	TOTAL:	2904.00

		INVOICE	PAGE: 1	
MECHANICAL A DIVISION OF LOGAN INDUSTRIES LTD Phone: 403-362-3884 Fax: 403-501-5300		Invoice# Invoice Date Terms Due Date Sold From Shipped From	MOM8324 01-31-2019 NET 30 3-02-2019 PARAMOUNT MECHANICAL PARAMOUNT MECHANICAL	FEB 0 1 2019 (033) (033)
Bill To 2220252/01	Ship To	2220252/02	Remit To	
EASTERN IRRIGATION DISTRICT PO BOX 128 BROOKS, AB TIR 1B2		IGATION DISTRICT IAL ROAD WEST ERTA	LOGAN INDUSTRIES L PO BOX 970 BROOKS, ALBERTA TIR 1B8 Phone : (403)362-	

	LSD	Well Name	Unit #	PO #
			457	CYLINDER
	Order By	Salesperson	FOB	Trucking Company
e	arl	Richard Deunk		

Item	Description	Ordered	Shipped	UM	Unit Price	Extension
PM REPAIR	REPAIR BACKHOE CYLINDER	1	1	EA	1,090.50	1,090.50
	10 - 400 - 56 305 Eg	FEBO	pq			
	COPY					
						Last Pag
					SUB TOTAL	1,090.50
					GST	
					PST	
		TAX # 80276	5297RT0001		INVOICE TOTAL	1,090.50
Signature:	Date:				CURRENCY	CANADIAN





	C/O RMA 2510 SP NISKU ORDER NO. 75652 QUANTITIES	✓ PAR MAKE: N 40M7166 N 24H1598 N T158183 N T75816 N 24H1679 N AHC1336 N AHC1336 N AHC1953 N AT17953 N AT20686 N FREIGH EARL-UI Tax ID	VE CA PHONE 780-436-9375 NUMBER DD MODEL: SNAP WASH SNAP WASH SNAP WASH S2 HYDR 15 HYDR 15 HYDR 15 HYDR 15 HYDR 15 HYDR 15 UNIV	PRIN HERCY HERCY HER RAULI RAULI	T T TIME 13:42 BIN E R N 0: V G A 2 V K C 4 V J D 1 V J C 4 V A I 5 E 3 0 5	EASTERN 550 INDU BROOKS INVOICE NO LIST 11.01 5.97 15.15 6.62 6.40 192.82 145.73 181.69 159.98 19.00	04 PRICES NET 11.01 5.97 15.15 6.62 6.40 192.82 145.73 181.69 159.98 19.00	A 4 1 2 7 9 8 4 4 1 2 7 9 8 EXTENSION H R S : 4 4 . 0 4 1 1 . 9 4 1 5 . 1 5 6 . 6 2 6 . 4 0 1 9 2 . 8 2 1 4 5 . 7 3 1 8 1 . 6 9 3 1 9 . 9 6 1 9 . 0 0
		** A ** ALL ** AL ** **	*********	COMPONENT SUBJECT TO HYDRAULIC CEPTS NO R HAGED DURI	S ARE A 30% HOSES ESPONS NG TRA *****	RESTOCKI ARE FINAL IBILITY F NSPORT	NG FEE SALE OR	* * * * * * * * * * * * * *
DATE OF NO GOODS C RETURNED I ACCORDING T ON THIS INV OF GOODS. PAST DUE IN	BY PERMISSION WHI TO ORDER ARE SUBJECT OICE WILL BE CONSII TEREST 1 1/2% PER MO	THOUT OUR PERMISS CH WERE FURNISHED TO A HANDLING CHARG DERED AFTER 30 DAYS	ION. GOODS TITLES TO ALL CORRECTLY BRANDT TRA E. NO CLAIMS PURCHASE PR	, ITEMS REMAIN WITH ACTOR LTD. UNTIL RICE, INTEREST AND GES ARE FULLY PAID	PARTS MISC T	AXABLE ONTAXABLE		924.35 19.00
	1ARGE OF \$1.50		DATE		PLEASE	PAY THIS TOT		943.35 P LF-





JOHN DEERE

		SEP 20	ZU1/	INVOICE DATE	BRANCH	INVOICE NO.
				23AUG17	04	4014870
OLD TO:						
	IRRIGATION DIST	RI	PAGE			ION DISTR
C/O AAMD			1	LASIER	USTRIAL	ION DISTR
	RROW DRIVE		SALE TYPE		AB T1R	
NISKU, A	B T9E 8N5		CHARGE CUSTOMER NO.	- T		102
			40000185	0		
PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER N		TE OPENED SALESPR	?N	
73336	780-436-9375	40148	70 01 2	6JUL17		
MAKE MODEL	SERIAL NO.	EQUIP. NO		AUTHORIZED B	IY	
JD 4108			7	330		AMOUNT
	D	ESCRIPTION				AMOUNT
TRAVEL	0.1 D.D.T.	.00 LAB	. 0 0	MSC .00	TOTAL	0 (
"		.VU LAD		n 3 C . V U		
CHECK BR.						
	OVER MACHINE					
	SPECS. ALSO FO				IDE	
	ASSING OIL. AL: NG OIL CAUSING				ĺ.	
DIFASSI			DIVARE TED	AL TOMOTION.		540.0
		ICE ACCESS	ORIES	4	8.60	48.6
>>··> SEG#	02 PRT	.00 LAB	540.00	MSC 48.60	TOTAL	588.6
SERVICE	BRAKES, REAR A	(LE, R&R			1	
SETUP M	ACHINE FOR REP	ATR REMOV	FD WHFFLS	FROM MACHINE		
	OIL FROM REAR					
	ES FROM TOP OF			ED DIFFERENTI		
	CHINE AND CLEA				MBLED	
	NTIAL AND CLEA					
	LE AND REPLACE			ISTONS AND NE		
WITH OT	LATES AND DISC L. INSTALLED D	5. A 5 5 E M B L I E E E D E N T I A	LU DIFFERE	NITAL AND FIL	LEU	
HOOKED	UP HOSES AND D		INSTALLED			
MACHINE	AND LOWERED U	NIT BACK T	O GROUND	REMOVED BRAKE		
VALVE F	ROM MACHINE AN	DISASSEM	IBLED. REPL	ACED ALL SEAL	S	
PISTONS	, CHECK VALVES	AND ORING	S IN VALVE	. INSTALLED B	ACK	
				DESCRI	PTION	AMOUNT
	5% PER MONTH (18% ANNUM). MIN					
completes may operate als cash on delivery of machin	ve repair work to be done along with overmachine for purposes of testing, ias in or on terms satisfactory with you and	pection, or delivery at my until paid in full on expo	risk   surce to one	TOTAL	PARTS	
acting wiceged on above man	nine to secure the amount of repairs thereic outpany assumes no responsibility for los					
v				MISC. CH		
		_		SALES		
31017	TORE		DATE	PLEASE THIS TO		CONTINUED

CUSTOMER COPY





1

INVOICE DATE



INVOICE NO.

BRANCH

									E DATE	DRANON	NTTO OL TO
								23/	NUG17	04	4014870
OLD TO:				-				-	-	_	
		IRRIGATIO	N DISTR	I	PAGE			9	EASTERN	IRRIG	ATION DISTR
	C/O AAMD					_ 2		н	EASTERN	IRRIG	ATION DISTR
		RROW DRIV	E		SALE	TYPE		P	550 INDU	STRIA	L ROAD
1	NISKU, A	B T9E 8N5			CHA	RGE		_	BROOKS,	AB T1	R 1B2
					CUSTO	MER NO.		T O			
					4	00001	85	0			
	SE ORDER NO.	PHONE NUMBER	·	WORK ORDER	NO. 5	EG.	DATE	OPENE	D SALESPRN		
MAKE	3 3 3 6 MODEL	780-43	6 - 9375	40148		03	26J	UL17	7		
JD		SERIAL NO.		EQUIP. N		METER			AUTHORIZED BY		
	410E	10410	EX83034		57		33	0		_	
			DE	SCRIPTION		-					AMOUNT
I	INTO MAC	HINE AND	BLED B	RAKE SYS	STEM.	TEST	RA	N MA	ACHINE TO	Ť	
C	LHECK FO	R FRUPER	UPERAI	ION AND	LEAK	<b>S</b> ,					
		2	T15936			RING	CY		62	. 0 5	124.
		16	T15937			RING			5	. 04	80.
		2 4	Z77164			RING	CY			.35	2.
		4	⊤15940 ⊤16123			ATE	CY		162		648.
		6	AT1795	5		SK	CY		158		1,108.
		3	T15940			AKE D			217		1,306.
		2	L55580			CK-UP	)			. 79	293.
		3	T15940			R I N G A L	v v			.76	9.
		3	T15940			CK-UF	XY			. 49	175.
		2	AT1844			LVE	, ХА СА			.93	116.
		3	R29936			RING	U		310		621.
		2	T15940			AL				. 19	18.
			* LABO						91	.00	182.
		1	FREIGH						17	0.0	2,340.
		1	FREIGH	IT						.00	17.
			SERVIC	E ACCES	SORIE	S			210		12.
>> ;	> SEG#	03 PRT	4,688.	24 140					210		210.
			4,000.	Z4 LAB	2,34	0.00	MS	С	239.60	тот	AL 7.267.
										1	// /.20/.
										1	
										1	
PAST D	UE INTERPOT										
1 hereby	Sauthania	% PER MONTH (18%)	ANNUM). MINIM	UM CHARGE OF \$1.	50.				DESCRIPT	ION	
cmplove	y admortize flue abey	e repair work to he do	ne along with the	114 m 1							AMOUNT
achum	cored on shares	the on terms satisfactor	y with you must up	all maint in the my	TINK LAN	CC 10 DAV			TOTAL	DTC	
I is un	derstood that this co	mpany assumes no room	of repairs therein,	nn paul in full an exp	css mechan	ics lien is			TOTAL PA	RTS	4,688.2
w the the	in for storage, sales, r	mpany assumes no resp open, or while field testing	ensibility for luss o	damage by their or i	lice to machi	ne placed					
			-						TOTAL LA	BOR	2,880.0
											2,000.(
					$\sim$				MISC. CHAI		
x_						P -					288.2
X	SIGNA					100 Yan"					
X	SIGNA	TURE					-		SALES T	~~	0 (
		FURE			DAT	E					0.0
	SIGNA r.20080819	fure			DAT				PLEASE PA THIS TOTAL	Y	0.( 7,856.4



Brandt Tractor Ltd. 10121 Barlow Trail NE Calgary, Alberta T3J 3C6 PH: (403) 248-0018





S O L D	C/O RM 2510 S	A P A R	RRIGATIO ROW DRIV	E	PAGE 1 CASH CHG. OTHER	S H I P	EASTERN 550 INDU	IRRIGATI IRRIGATI JSTRIAL F AB T1R I	ION DIST ROAD
T O	NISKU	ΑB	T9E 8N5	C A	ACCT. NO 4 0 0 0 0 1 8 5	T O			
SALESMAN	ORDER NO.	RO	NO.	PHONE	INVOICE DATE	TIME	INVOICE NO		
32	UNIT457	0	0939047	780-436-9375	17SEP21	08:25		0 4	4475448
	UANTITIES					BIN	1107	For the A	EXTENSION
ORDERED	SHIPPED B/O	N	PART	NUMBER	DESCRIPTION	Sec. 2	LIST	NET	
	1	N		D MODEL: SH Backh BYEARL		É R N O : D 1 1 M 2 O	437.79	437.79	HRS: 437.79
	1	N	FREIGHT Tax ID:		******	* * * * * * *	27.00	27.00	27.00
				TS HOURS: MON					**
			** 21 L	OUR EMERGENCY	ON CALL	PARTS.	SERVICE	& SALES	**
			** ΔI	L ELECTRICAL	COMPONENT	SARE	NON RETUR	NABLE	**
1			** <u>  </u>	RETURNS ARE S	UBJECT TO	A 30%	RESTOCK	NG FEE	**
			** ALL	FABRICATED H	YDRAULIC	HOSES	ARE FINAL	SALE	**
			**	BRANDT ACC	EPTS NO R	ESPONS	IBILITY	OR	* *
			**	GLASS DAM	AGED DURI	NG TRA	NSPORT		**
( in the second s			******	*****	******	******	*******	******	* * *
					in the second se				
		-				DESC		ACCOUNT	AMOUNT
	ET 30 DAYS FR	OM	SHIP VIA DB	BROOKS		PARTS T			
DATE OF	INVOICE n be returned v	UTUO:	T OUR PERMISSI	ON GOODS TITLES TO ALL	ITEMS REMAIN WITH			-	437.79
ETURNED BY	N BE RETURNED V PERMISSION WH ORDER ARE SUBJEC ICE WILL BE CONS	ICH WI I TOAF	ERE_FURNISHED_O IANDLING CHARGE	NO CLAIMS PURCHASE PR	ITEMS REMAIN WITH CTOR LTD. UNTH ICE, INTEREST AND ES ARE FULLY PAID	MISC T	AXABLE ONTAXABLI		27.00
ST DUE INTI	EREST 1 1/2% PER N NRGE OF \$1.50	IONTH	(18% ANNUM).			SALES TA			
IGNATUR	Е			DATE		PLEASE F	ΡΑΥ ΤΗΙς ΤΟΤ		464.79

PACKING SLIP



S

Brandt Tractor Ltd. 3555 - 46th Ave. S.E. Calgary, AB T2B 3B3 (403) 248-0018





S	<b>F h c i</b>																
0	EAS	TERN	IF	RRIGATIO	N DI	ST		PA	GE	S	~						
L		AAM						1		н	E E	AST	ERN	IRR	GATI	0 N [	DIST
D				ROW DRIV				CASH CH		P	E	AST	ERN	IRR	GATI	0 N (	DIST
Т	NISI	ΚU	ΑB	T9E 8N5	,	CA				P					[AL F		
ò						en		ACCI	NO	т	В	R 0 0	KS	AB	「1R 1	B 2	
										o							
ALESMAN	ORDER NO		RO.	NO.	PHONE				185								
32	NEED		0.0	0770201	700					TIME	IN	VOI	CE NO				
	QUANTIT	IES	01	0770291	/80-	436-9	375	01FE	B16	14:3	6			0 4	1	444	2304
	SHIPPED			DAD			- 1 F			BIN					PRICES		2304
					NUMB	ER	1. 1. 1. 1.	DESCRIPT	ION	Unit		LI	ST	N	ET	EX	TENSION
				MAKE: J		MOD	EL:		S	ERNO:							
	1		N	AT30276	52		ТАСН	OMET)				609	.96	600	9.96		RS:
	1		Ν	RE43497	7		SWIT			VDA6			. 11				09.96
	1		Ν	R44165				NUT		VCE3					1.11		71.11
				ORDERE	D B Y	EARL						د	. 25		3.25		3.25
				410E				, , , , , , , ,	150								
	1		Ν	FREIGHT	г												
	_			Tax ID:								9	.00		9.00		9.00
				*****												***	
				** PART	TS H	OURS:	MON -	THU	A.10	P FRI	7 A	- 6 F	SA	7 7 1	1 D	**	
				** 24	HOUR	EMERO	GENCY	ON	CALL	PARTS	, S	ERV	ICE	& S	ALES	**	
				** Al	LL EI	LECTRI	[ C A L	COMPO	DNENT	S ARE	NO	NF	ETU	RNAB	LE	**	
				** ALL	RETU	URNS A	ARE S	UBJE	ст то	A 30	% R	EST	ОСК	ING	FFF	**	
				** All	L FAI	BRICAT	TED H	YDRAI	JLIC	HOSES	AR	FF	τηλι	S A		**	
				*****	* * * * *	*****	****	****	*****	*****	***	***	***	****			
ERMS: N	NET 30 DA	AYS FR	ОМ	SHIP VIA DB	BRO	OKS				D	SCRI	ρτιο	N	ACC	OUNT	A	MOUNT
	FINVOIC			SHIP VIA DU	UNU					PARTS	ТАХ	AP	F				
) GOODS C	AN BE RETU	JRNED W	/ITHO	UT OUR PERMISS	SION. GO	ODS TITL	ES TO ALI	ITEMS RE	MAIN WIT					-		-	04 22
TURNED I	BY PERMISS	ION WHI	CH W	ERE FURNISHED HANDLING CHARG	CORREC	DAG DITD	CHASE DI	LCC INTE	DECT AND					t,		6	84.32
N THIS INV	OICE WILL I	BE CONS	DERE	ED AFTER 30 DAYS	S OF RECI		ER CHAR	GES ARE F	ULLY PAIL	MISC							
F GOODS.	TEDECTIN	0/ DCD +	ONT	1 (100/						MISC			XABL	Ę			9.00
		:% PER N	UNTH	1 (18% ANNUM).						CALEC	ΤΔΧ			1			
	HARGE OF \$1			(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						SALES	177						
				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						SALES					1		
INIMUM CI	HARGE OF \$1	.50				DAT	E			PLEAS					•	6	93.32





S O L D T O	EASTERN C/O AAM 2510 SP NISKU	D & ( A R F	2	/E	РА <b>G</b> E 1 САЗН СНО. ОТНЕВ Х АССТ NO 4 0 0 0 0 1 8 5	S H P T O	EASTERN 550 INDU	IRRIGATI IRRIGATI STRIAL R AB T1R 1	ON DIST OAD
SALESMAN	ORDER NO.	RO.	NO.	PHONE		TIME	INVOICE NO	10 - N	
32	71574	0	0772822	780-436-9375	08MAR16	12:28		04	4444235
	QUANTITIES		UTTE	,		BIN		PRICES	and the second
ORDERED	SHIPPED B/O	V	PAR	TNUMBER	DESCRIPTION	BIN	LIST	NET	EXTENSION
			MAKE: 、	JD MODEL:	S	ERNO:			HRS:
	1	N	AT30910		EL	Г 7 В	712.48	712.48	712.48
	1		FREIGH				28.00	28.00	28.00
				NIT 457					
			Tax ID						
			*****	* * * * * * * * * * * * *	*****	* * * * * *	*******	******	* *
			** PAR	TS HOURS: MON	-THU 7A-10	P FRI	7A-6P SAT	7 A - 4 P	* *
				HOUR EMERGENC					* *
				LL ELECTRICAL					**
			** ALL	RETURNS ARE	SUBJECT TO	A 30%	RESTOCK	ING FEE	**
			** AL	L FABRICATED	HYDRAULIC	HOSES	ARE FINA	SALE	**
			*****	*****	*****	*****	*****	*******	**
								ACCOUNT	AMOUNT
	NET 30 DAYS FI	ROM	SHIP VIA DE	BBROOKS			SCRIPTION		
	OF INVOICE			COLON COTTO TITLES TO	ALL ITEME DEMAIN MUT		TAXABLE		
RETURNED	CAN BE RETURNED BY PERMISSION WI TO ORDER ARE SUBJE VOICE WILL BE CON	HICH CT TO	WERE FURNISHE A HANDLING CHAR		ALL ITEMS REMAIN WIT TRACTOR LTD- UNTI E PRICE, INTEREST AN ARGES ARE FULLY PAIL			. E	712.48
	INTEREST 1-1/2% PER CHARGE OF \$1:50	MON	[H (18% ANNUM).				ΝΟΝΤΑΧΑΒΙ	- É	28.00
SIGNAT	URE			DATE		PLEASE	EPAY THIS TO		740.48







S O L D	EASTERN IRRIGATION DIST C/O AAMD&C 2510 SPARROW DRIVE NISKU AB T9F 8N5 CA						PAG 1 CASH CHO		S H I P	EASTERN EARL UNIT 45	ION DIST	
Т О	NISP	<b>KU</b>	AB	T9E 8N5	C A		ACCT 40000		T O	BROOKS	AB T1R :	l B 2
ALESMAN	ORDER NO		RO.	NO.	PHONE		INVOICE DA		TIME	INVOICE NO		
and and the	70227		0 (	0746971	780-436	5 - 9375	07MA	Y15	14:12		04	4423514
	DUANTIT								1. 1. 1. 1. 1.		PRICES	
RDERED	SHIPPED	B/O	N		NUMBER		DESCRIPTI	ON	BIN	LIST	NET	EXTENSION
	2 1			MAKE: J AT16218 FREIGHT Tax ID: *******	******	* * * * * * *	СН С	Y ****	ERNO:	132.09 9.00	132.09 9.00	HRS: 264.18 9.00
** PARTS HOURS: MO ** 24 HOUR EMERGEN ** ALL ELECTRICA ** ALL RETURNS ARE ** ALL FABRICATED ***********				ERGENCY FRICAL SARE S CATED F	-THU 7A-10 Y ON CALL COMPONENTS SUBJECT TO HYDRAULTC	HU 7A-10P FR DN CALL PART DMPONENTS AR BJECT TO A 3 DRAULTC HOSE		SERVICE NON RETUR RESTOCK	& SALES NABLE NG FEE	**		
DATE OF O GOODS C ETURNED E CCORDING TO N THIS INVO F GOODS.	O ORDER ARE DICE WILL E FEREST   1/2 IARGE OF \$1	E URNED WI ION WHIC SUBJECT DE CONSII	THOU THOU TOAI DERE	SHIP VIA BRO TOUR PERMISSI ERE FURNISHED DAFTER 30 DAYS O AFTER 30 DAYS (18% ANNUM).	ON. GOODS CORRECTLY - NO CLAIMS OF RECEIPT	OTHER CHARG	JES ARE FUI	LY PAID	<b>PARTS<sub>T</sub></b> PARTS MISC T	ONTAXABL		AMOUNT 264.18 9.00
					D	DATE		-	PLEASE F	YAY THIS TOT		272 10
												273.18

### KIRK'S TIRE BROOKS LTD. 620 AQUADUCT DRIVE BOX 1769 BROOKS AB T1R 1C5

Phone: (403)362-6647 Fax: (403)362-6680

### SOLD TO:

### REPAIR ORDER B113125 (Copy)

EASTIR EASTERN IRRIGATION DISTRICT JUN 1 0 2015 P.O. BOX 128

CONTACT: SHOP --- 3621446--CH5652263-Jun 10 15

INVOICE TO: AB BROOKS

T1R 1B2 TEL: 403 362-1400 FAX: 403 3626206

**PAGE:** 1

YEAR		MAKE		MODEL						ENGINE	
				BACKHOE UNI	WRITTEN BY						
PLATE NO	)	VIN		ODOMETER				NO.		NBY	
		DRONICED	TEDMO	0 GST#			457 <b>P.O</b> .			AV TAG	
		PROMISED	TERMS				P.U.				
259 PM		SCRIPTION	NET 30	R866171515	TAX	RET		%	NET		EXT.PRICE
1 60 1* 1 1*	GST E SC SE MIL M USED NONE CTD C VS NONE ORDRE	xemption UNKNOWN RVICE CALL Jun 10 ILEAGE Jun 10 15 USED TIRES HGOVER TRACTOR DRY VALVE STEM 572 D BY THOMAS WALL?	0 15 X Jun 10 15 ACE			50.00 1.50 300	.00	0	50.0 1.5 30	0 0.00	50.00 90.00 300.00 100.00 12.00
		TER	MS AND CO	NDITIONS					P	ARTS:	312.00
									LA	BOUR:	240.00
									0	THER:	N/C
									SUB-TO	OTAL:	552.00
										GST:	N/C
										PST:	N/C
	TUAN	K YOU SIGN							_		
	THAN	Sidn							T	OTAL:	552.00

0         L         DAG S         1         H           BROOKS         AB TIR 1B2         CA         ACCT.NO         T           0         101512         0         T         0           107         00046536         403-362-1400         245EP13         14:15           0         MAKE : JD         MODEL :         SERNO:         NC25           1         N         SE501342         ALTERNATOR         NC25         452.84           10-900-556330         C         SC         SCP 7         2.4           10-900-56330         C         SC         SCRIPTION           PA		Јони 🛙	DEERE
0         слан слан слан слан слан слан слан слан	IRRIGAT	ION DIST	
L         CASH         CHE         CASH         CASH         CHE         T           T         ACCT.NO         T         ACCT.NO         T         T           ACCT.NO         101512         THE         T         T         T           ULISMAN         ORDER NO.         NO.         MONE         THE         THE         INVOICE NC         THE           107         0.0046536         403-362-1400         245EP13         14:15         THE         INVOICE NC         THE           QUANTITIES         PART NUMBER         DESCRIPTION         BIN         LIST         THE         TO         <			
BROOKS       AB TIR 1B2       CA       ACCT.NO       T         ACCT.NO       101512       TIME       INVOICE NC         107       00046536       403-362-1400       24SEP13       14:15         OUANTITIES       00046536       403-362-1400       24SEP13       14:15         OUANTITIES       MAKE: JD       MODEL:       SERNO:       BIN         I       N SE501342       ALTERNATOR       NC25       452.84         I       N SE501342       ALTERNATOR       NC25       452.84         I       I       N SESO1342       ALTERNATOR       NC25       452.84         I       I       I       I       I       PARTSTAXABLE       PARTSTAXABLE         I       I       I       I       I       PARTSTAXABLE       PARTSTAXABLE         I       I       I       I       I       I       PARTSTAXABLE       PARTST NONTAXAB         I       I			
TO         ACCT. NO         T           LESMAN         ORDER NO.         RO. NO.         PHONE         INVOICE PATE         TIME         INVOICE NO.           107         00046536         403-362-1400         24SEP13         14:15         Invoice PATE         INVOICE NO.           107         00046536         403-362-1400         24SEP13         14:15         Invoice PATE         I			
O     101512     O       LESMAN     ORDER NO.     RO. NO.     PHONE     INVOICE DATE     INVOICE NO.       107     00046536     403-362-1400     24SEP13     14:15       OUANTITIES     DESCRIPTION     BIN     LIST       IDERED SHIPPED     BO     V     PART NUMBER     DESCRIPTION       1     N     SE501342     ALTERNATOR     NC25     452.84       1     N     SE501342     ALTERNATOR     NC25     452.84       107     000-400-563300     Cp     Superior     Superior     Superior       1     N     SE501342     ALTERNATOR     NC25     452.84       107     107     000-7663300     Cp     Superior     Zuperior       108     Interesting the superior     Superior     Superior     PARTS       108     Interesting the superior     Superior     Superior     PARTS       109     PARTS     Superior     Superior     Superior       100     Interesting the superior     Superior     PARTS     PARTS       108     Interesting the superior     Superior     PARTS     PARTS       109     Interesting the superior     Superior     PARTS     PARTS       109     Interesting the sup			
LESMAN       ORDER NO.       PO. NO.       PHONE       INVOICE DATE       TIME       INVOICE NO.         107       00046536       403-362-1400       24SEP13       14:15       14:15         OUANTITIES         DECRED SHIPPED B/O       N       PART NUMBER       DESCRIPTION       BIN       LIST         1       N       SE501342       ALTERNATOR       NC25       452.84         1       N       SE501342       ALTERNATOR       NC25       452.84         1/0-400-576330       Cp       SC/A       7.2.4         ETURNED GOODS SUBJECT       SHIP VIA       IHEREBY CERTIFY THAT IAM ENGAGED IN THE BUSINESS       DESCRIPTION         ETURNED GOODS SUBJECT         IHEREBY CERTIFY THAT IAM ENGAGED IN THE BUSINESS         IHEREBY CERTIFY THAT IAM ENGAGED IN THE BUSINESS         OF FARMING AND THAT THE GOODES SNOWN ON THE         IHEREBY CERTIFY THAT IAM ENGAGED IN THE BUSINESS         OF FARMING AND THAT THE GOODES SNOWN ON THE         IHEREBY CERTIFY THAT IAM ENGAGED IN THE BUSINESS         OF FARMING AND THAT THE GOODES SNOWN ON THE         IHEREBY CERTIFY THAT IAM ENGAGED IN THE BUSINESS         OF FARMING AND THAT THE GOODES SNOWN ON THE			
107       00046536       403-362-1400       24SEP13       14:15         OUANTITIES         BORED SHIPPED BO V       PART NUMBER       DESCRIPTION       BIN       LIST         1       N       SE501342       ALTERNATOR       NC25       452.84         1       N       SE501342       ALTERNATOR       NC25       452.84         10-400-56330       C       SC27724       AU         10-700-56330       C       SC27724       AU         10-700-576330       C       SC27724       AU         10-700-700-576330       C       SC27724       AU         10-700-700-576330       C       SC27724       AU         10-700-700-700       SC207724       AU       AU         10-700-700       SC207724       AU       AU         10-700       SC207774       AU       AU	0.		7
OUANTITIES     BIN       INDERED SHIPPED BIO     BIO       IN     MAKE: JD       MAKE: JD     MODEL:       SE501342     ALTERNATOR       IN     SE501342       ALTERNATOR     NC25       452.84       JD-Y00-576330       JD-Y00-576330       JO-Y00-576330		1042540	
DEFED     SHIPPED     B/O     V     PART NUMBER     DESCRIPTION     BIN     LIST       1     N     MAKE : JD     MODEL :     SERNO :     NC25     452.84       1     N     SE501342     ALTERNATOR     NC25     452.84       1     N     SE501342     ALTERNATOR     NC25     452.84       1     D-400-56330     C     SUBPT7     24	0 1 PRICES	1042540	-
1       NAKE: JD       MODEL:       SERN0:         1       N SE501342       ALTERNATOR       NC25         452.84       JD-400-56336       5077244         JD-400-56336       5077244         JD-400-56336       5077244         JD-5005336       5077244         JD-600-56336       5077244         JD-7000-56336       50777244         JD-7000-7724       JD-7000         JD-7000-7724			OFFICE
1     N     SE501342     ALTERNATOR     NC25     452.84       1	NET	EXTENSION	-
TURNED GOODS SUBJECT RESTOCKING CHARGE SHIP VIA HEREBY CERTIFY THAT I AMENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS NVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS. HISC NONTAXABLE		HRS:	
TURNED GOODS SUBJECT DRESTOCKING CHARGE HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT MISC TAXABLE OF THAT BUSINESS.	432.25	432.25	PC
TURNED GOODS SUBJECT D RESTOCKING CHARGE. I HEREBY CERTIFY THAT I AM ENGAGED IN THE BUSINESS OF FARMING AND THAT THE GOODS SHOWN ON THIS INVOICE WILL BE USED EXCLUSIVELY IN THE CONDUCT OF THAT BUSINESS. MISC NONTAXAB			
SECTWSPRGESALES TAX ST DUE INTEREST 2% PER MONTH. (24%) PER ANNUM.		<b>F AMOUNT</b> 432.25	
& Aliant		122 25	_
RECEIVED BY PLEASE PAY THIS TO	OTAL 🕨	432.25	


EQUIPMENT LTD. EQUIPMENT LTD. BO BOX 760 • Brooks, AB T1R 1B7 Eax: (403 Te Te W

Parts Invoice



ORIGINAL COPY







S O L D T O	O EASTERN IRRIGATION DIST L C/O AAMD&C D 2510 SPARROW DRIVE NISKU AB T9E 8N5 CA O							PAGE 1 CASH CHG. 0TM X ACCT.NO 4 0 0 0 0 1 8 5	T O	EASTERN IRRIGATION DIST EASTERN IRRIGATION DIST 550 INDUSTRIAL ROAD BROOKS AB TIR 1B2			
SALESMAN	ORDER NO		RO.	NO.	PHONE			INVOICE DATE	TIME	INVOICE NO	<b>)</b> .		
32	66094		0	0677013	780	436	9375	20MAR13	06:10		04	4468562	
	QUANTIT	IES							BIN		PRICES		
ORDERED	SHIPPED	B/0		PART	NUMB	ER	in the start	DESCRIPTION		LIST	NET	EXTENSION	
				MAKE: J	D	M	DDEL:		SERNO:			HRS:	
	1		N	PG20016	1		FRONT	AXLCY		10160.94	10160.94	10160.94	
	1		Ν	AT16444	2		PIN		H 8 0 2	333.76	333.76	333.76	
	6		Ν	R46973			THRUS	ST WA	VCJ2	4.96	4.96	29.76	
	3		N	T80027 UNIT 45	7		THRUS	ST WA	VCJ5	8.79	8.79	26.37	
	1	9 - 12 - 12 - 12 - 12 - 12 - 12 - 12 - 1	N	T125615 Tax ID: ******* ** P ** 24 H ** ALL ** ALL	**** ARTS OUR L EL RETU FAB	HOU EMER ECTR RNS RICA	PIPE JRS: M RGENCY RICAL ARE S TED H	ION-FRI 7 'ON CALL COMPONEN UBJECT T IYDRAULIC	* * * * * * * * AM - 6 P M P A R T S , T S A R E O A 3 0 % H O S E S	1.18	7AM-4PM & SALES NABLE ING FEE SALE	* * * * * * * *	
RETURNED BY	INVOICE N BE RETURI PERMISSION ORDER ARE SU CE WILL BE REST I 1/2%	NED WIT N WHICH UBJECT TO CONSIDE PER MON	HOUT WEI DA HA	SHIP VIA DIE I OUR PERMISSIO I OUR PERMISHED CO NULLING CHARGE AFTER 30 DAYS O 18% ANNUM).	N. GOOD DRRECTL NO CLAIM	OS TITL Y BRA IS PUR	ES TO ALL I	ITEMS REMAIN WIT CTOR LTD UNTI CE, INTEREST AN ES ARE FULLY PAIL	PARTS T	ONTAXABLE		<b>AMOUNT</b> 10552.01	
SIGNATURE						DAT	E		PLEASE P	PAY THIS TOT	al ► CKING SLIF	10552.01	

PACKING SLIP



## Parts Invoice



	ARROW DRIVE AB T9E 8N5 CA RO.NO. PHONE 00677013 780-436 ✓ PART NUMBER MAKE: JD M N PG200161 N AT164442 N R46973 N T80027 UNIT 457 CALL EARL WHEN N T125615 Tax ID: ************************************	DESCRIPTION IODEL: S FRONT AXLCY PIN THRUST WA	T         Time         06:10         BIN         ERNO:         H802         VCJ2         VCJ5         93-575         ******         M-6PM         PARTS,         SARE         A 30%         HOSES	EASTERN 550 INDU BROOKS INVOICE NO LIST 10160.941 333.76 4.96 8.79 6 1.18 ******* SAT SERVICE NON RETU RESTOCK ARE FINA	IRRIGATI ISTRIAL R AB T1R 1 	4468562 <u>EXTENSION</u> HRS: 10160.94 333.76 29.76 26.37 1.18 ** ** ** ** **
CTURNED BY PERMISSION WHIC	THOUT OUR PERMISSION. GOODS H WERE FURNISHED CORRECTLY TO A HANDLING CHARGE. NO CLAIMS DERED AFTER 30 DAYS OF RECEIPT	SENAU TITLES TO ALL ITEMS REMAIN WITI BRANDT TRACTOR LTD UNTI PURCHASE PRICE, INTEREST ANI OTHER CHARGES ARE FULLY PAIL	PARTS <sub>T</sub> PARTS MISC T	A X A B L E O N T A X A B L		<b>AMOUNT</b> 10552.01
AST DUE INTEREST   1/2% PER MO						

PACKING SLIP







S O L D T O	C / O 2 5 1 0	AAM SP	D& AR	RRIGATIC C ROW DRIV T9E 8N5	E	РАGE 1 САSH СНG. ОТНЕЯ Х АССТ. NO	S H I P T O	EASTERN IRRIGATION DIST EASTERN IRRIGATION DIST 550 INDUSTRIAL ROAD BROOKS AB T1R 1B2					
ALESMAN	ORDER NO		RO.	NO.	PHONE	40000185 INVOICE DATE	TIME	INVOICE NO.					
32	66087		0	0675931	780-436-937	5 01MAR13	07:52		04	4467263			
	QUANTIT	IES					BIN		PRICE	5			
RDERED	SHIPPED	B/O	N	PAR		DESCRIPTION		LIST	NET	EXTENSION			
	1		N	**	03 TIE 57	ROD A *************** MON-FRI 7A	M - 6 P M	SAT	7 A M - 4 P M	***			
				** A ** ALL ** AL	HOUR EMERGEN LL ELECTRICA RETURNS ARE L FABRICATEI	L COMPONENT SUBJECT TO HYDRAULIC	SARE A 30% HOSES	NON RETUR RESTOCKI ARE FINAL	NABLE NG FEE SALE	* * * * * *			
										,			
	NET 30 D. OF INVOIC		юм	SHIP VIA DB	BROOKS			CRIPTION A X A B L E	ACCOUNT	AMOUNT			
O GOODS ETURNED CCORDING N THIS IN F GOODS. AST DUE II	CAN BE RET BY PERMISS TO ORDER AR VOICE WILL	URNED V SION WH E SUBJEC BE CONS 2% PER N	ICH N T TO / IDER	DUT OUR PERMIS WERE FURNISHEL HANDLING CHARG ED AFTER 30 DAY H (18% ANNUM).	JE NO CLAIMS PURCHA	D ALL ITEMS REMAIN WITH TRACTOR LTD. UNTI SE PRICE, INTEREST AND HARGES ARE FULLY PAID	PARTS MISC T	N O N T A X B L E A X A B L E O N T A X A B L E		729.73			
							1						



Brandt Tractor Ltd. 3555 - 46th Ave. S.E. (403) 248-0018



Image: State of INVOICE       SHIP VIA BROOKS DB       DESCRIPTION       ACCOUNT       AMOUNT         NO GOODS CAN BE RETURNED WITHOUT OUR FEMALISSION GOODS ON THIS INVOICE       Interest of INVOICE       Interest of INVOICE       ACCOUNT       AMOUNT         NO GOODS CAN BE RETURNED WITHOUT OUR FEMALISSION GOODS ON THIS INVOICE       Interest of INVOICE       Interest of INVOICE       ACCOUNT       AMOUNT         NO GOODS CAN BE RETURNED WITHOUT OUR FEMALISSION GOODS ON THIS INVOICE       Interest of INVOICE       Interest of INVOICE       ACCOUNT       AMOUNT         NO GOODS CAN BE RETURNED WITHOUT OUR FEMALISSION GOODS ON THIS INVOICE WILL BECKNISHED CORRECTLY ON THIS INVOICE WILL BECKNISHED OF SIGN OF AN OF A RECEIVER TO THE REPORT ON THAT AND THE CHARGES ARE FULLY PAID OT THAT COR ALL UNTER OT ALL TENS REMAIN WITH OT ALL THE ST TO ALL TENS REMAIN WITH OT ALL TENS REMAIN WITH OT ALL TENS REPORT ON THAT AND THE CHARGES ARE FULLY PAID OT THAT COR ALL TO UNTER OT ALL TENS REPORT ON THAT AND THE CHARGES ARE FULLY PAID OT ALL TENS REPORT ON THAT AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGE ARE FULLY PAID OT ALL TENS RETURNED AND THE CHARGES AR	NISKU       AB       T9E       BNS       CA       ACCT.NO       BROOKS       AB       TIR       1B2         O       ACCT.NO       T       ACCT.NO       T       O       BROOKS       AB       TIR       1B2         SALESMAN       ORDER NO       RO.NO.       PHONE       INVOICE DATE       TIME       INVOICE NO.         146       66090       00676227       780.436.9375       05MAR13       08:22       04       446743         ORDERED       SHIPPED       B/O       N       PART NUMBER       DESCRIPTION       IINVOICE NO.         ORDERED       SHIPPED       B/O       N       PART NUMBER       DESCRIPTION       BIN       INVOICE NO.         ORDERED       SHIPPED       B/O       N       PART NUMBER       DESCRIPTION       BIN       INT       PRICES         I       N       171M367080       EDGE, 200X       CE1C       266.67       266.67       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       266.7       270       2.70       2.70       2.	sion : . 6 7 . 6 0 . 6 0
*** ALL ELECTRICAL COMPONENTS ARE NON RETURNABLE       ***         *** ALL RETURNS ARE SUBJECT TO       A 30% RESTOCKING FEE         *** ALL FABRICATED HYDRAULIC HOSES ARE FINAL SALE       ***         WMIT 457       FAMONT EAG LOADEN         GHP VIA BROOKS DB       FAMONT EAG LOADEN         OCODS CAN BE RETURNED WITHOUT OUR PERMISSION GOODS HETUNED BY PERMISSION HOUTH VIEP FEMISSION HOUTH HETUNED BY AND THE CHARGES ARE PLUE PARTS TAND OTHER CHARGES ARE PLUE PARTS AND MITH PURCHASE PRICE, INTEREST AND OTHER CHARGES ARE PLUE PARTS AND MITH PURCHASE PRICE, INTEREST AND OTHER CHARGES ARE PLUE PARTS AND MITH PURCHASE PRICE, INTEREST AND OTHER CHARGES ARE PLUE PARTS AND MITH PURCHASE PRICE, INTEREST AND OTHER CHARGES ARE PLUE PARTS AND	** PARTS HOURS: MON-FRI 7AM-6PM SAT 7AM-4PM **	
TERMS: NET 30 DAYS FROM DATE OF INVOICE       SHIP VIA BROOKS DB       DECOMMANDAL       DECOMMANDAL       DECOMMANDAL         NO GOODS CAN BE RETURNED WITHOUT OUR PERMISSION GOODS RETURNED BY PERMISSION WHICH WERE FURNISHED CORRECTLY ACCORDING TO ARRE SUBJECT TO A HADDING CHARGE NO CLAIMS ON THIS INVOICE WILL BE CONSIDERED AFTER 30 DAYS OF RECEIPT OF GOODS       TITLES TO ALL ITEMS REMAIN WITH BRANDT TRACTOR LTD UNTIL PURCHASE PRICE, INTEREST AND OTHER CHARGES ARE FULLY PAID       PARTS NONTAXBLE       297.87         PAST DUE INTEREST I 1/2% PER MONTH (18% ANNUM) MINIMUM CHARGE OF \$1.50       MISC NONTAXABLE       30.00	** ALL ELECTRICAL COMPONENTS ARE NON RETURNABLE ** ** ALL RETURNS ARE SUBJECT TO A 30% RESTOCKING FEE ** ** ALL FABRICATED HYDRAULIC HOSES ARE FINAL SALE ** *****	
DATE OF INVOICE     PARTS TAXABLE       NO GOODS CAN BE RETURNED WITHOUT OUR PERMISSION GOODS RETURNED BY PERMISSION WHICH WERE FURNISHED CORRECTLY ACCORDING TO ORDER ARE SUBJECT TO A HANDLING CHARGE NO CLAIMS ON THIS INVOICE WILL BE CONSIDERED AFTER 30 DAYS OF RECEIPT OF GOODS.     TITLES TO ALL ITEMS REMAIN WITH BRANDT TRACTOR LTD UNTIL PURCHASE PRICE, INTEREST AND OTHER CHARGES ARE FULLY PAID     PARTS NONTAXBLE     297.87       MISC TAXABLE     30.00       PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50     SALES TAX     327.87		UNT
OF GOODS.     MISC NONTAXABLE     30.00       PAST DUE INTEREST I 1/2% PER MONTH (18% ANNUM).     SALES TAX     327.87	DATE OF INVOICE PARTS TAXABLE NO GOODS CAN BE RETURNED WITHOUT OUR PERMISSION. GOODS RETURNED BY PERMISSION WHICH WERE FURNISHED CORRECTLY ACCORDING TO ORDER ARE SUBJECT TO A HANDLING CHARGE. NO CLAIMS	. 87
	OF GOODS. MISC NONTAXABLE 30. PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). SALES TAX	. 0 0
SIGNATURE DATE PLEASE FATTING TOTAL	SIGNATURE DATE PLEASE PAY THIS TOTAL > 327.	. 87

# **JT Repair**

227 Meadowbrook Dr E Brooks, AB T1R 1N6

### JAN 0 8 2013

### INVOICE

Invoice No.:	307
Date:	21/12/2012
Unit	457
PO	
Hours	N/A

### Sold to:

, **^** 

### Eastern Irrigation District

P.O. Bag 8 550 Industrial Road West Brooks, AB\_T1R 1B2 Ship to: Eastern Irrigation District P.O. Bag 8 550 Industrial Road West Brooks, AB T1R 1B2

Item No.	Unit	Quantity	Description	Unit Price	Amount
Shop Rate	Hour	5.5	Diagnose leakage in steering system,	115.00	632.50
Parts	Each	2.0	remove and reseal steering cylinder. Piston seal	53.96	107.92
			Subtotal:		740.42
			10-400-56305 ED 3	TAN 14	
			GST Number: 814066809RT0001		
Shipped By:	Tracking N	umber:			
Comment: Thar	nk you for your busi	ness!		Total Amount	740.42
Sold By:					



`

Brandt Tractor Ltd 3555 - 46th Ave, S.E. Calgary, AB T2B 3B3 (403) 248-0018 JAN 0 8 2013 Parts Invoice



s O	EASTE P.O.B		RRIGATIC	ON DIST	PAGE	S H	EASTERN	IRRIGAT	ION DIST
D	1.0.01				CASH CHG. OTHER	I P			
Т	BROOK	S A	B T1R 18	32 C A	ACCT. NO	т			
0						o			
SALESMAN	ORDER NO.	RO	. NO.	PHONE	4 0 0 0 2 2 1 1 INVOICE DATE	TIME	INVOICE NO	).	
141	U N I T 4 5 7	0	0670818	403-362-1400	21DEC12	13:05		04	4463345
	QUANTITIES			1		DIN		PRICES	
ORDERED	SHIPPED B/	o√	PAR	TNUMBER	DESCRIPTION	BIN	LIST	NET	EXTENSION
	1	N	MAKE: 3 T153744			E R N O : V H C 1	T0410E83 274.48	274.48	HRS: 274.48
	1	N	FREIGHT	T a			8.00	8.00	8.00
			403-793 Tax ID:						
			*****	*****	*****	*****	******	*******	* * *
			** P	PARTS HOURS:	MON-FRI 7A	M - 6 P M	SAT	7 A M - 4 P M	**
			** 24 H	IOUR EMERGENC	Y ON CALL	PARTS,	SERVICE	& SALES	**
			** AL	L ELECTRICAL	COMPONENT	S ARE	NON RETUR	NABLE	* *
			** ALL	RETURNS ARE	SUBJECT TO	A 30%	RESTOCK	ING FEE	**
			** ALL	FABRICATED	HYDRAULIC	HOSES	ARE FINAI	SALE	**
			*****	****	******	*****	*****	*******	**
			<i>[</i> C	9-400-56	330 E	, JA	n ry		
TERMS: N	ET 30 DAYS F	ROM		OKS DB ATTN .	1058	DESC	RIPTION	ACCOUNT	AMOUNT
DATE OF			SHIP VIA DICO	UND DU ATTA (	50511	PARTS T	XABLE		
RETURNED BY ACCORDING TO	ORDER ARE SUBJE	HICH WE	T OUR PERMISSIC RE FURNISHED C ANDLING CHARGE AFTER 30 DAYS (	NO CLAIMS PURCHASE PE	LITEMS REMAIN WITH ACTOR LTD. UNTIL RICE, INTEREST AND GES ARE FULLY PAID	PARTS 1	IONTAXBLE		274.48
OF GOODS	EREST 1 1/2% PER					MISC N( SALES TA	) N T A X A B L E X		8.00
SIGNATURE	E			DATE		PLEASE P	AY THIS TOT		282.48



Parts Invoice



MAR 0 5 2013

S O L D T O	C 2	/0 51(	AAM SP	D & A R	RRIGATIC C ROW DRIN T9E 8N5	/ E		РАGE 1 САЯН СНВ. ОТНЕЯ X АССТ. NO 4 0 0 0 0 1 8 5	S H I P T O	EASTERN 550 INDU BROOKS	EASTERN IRRIGATION DIST EASTERN IRRIGATION DIST 550 INDUSTRIAL ROAD BROOKS AB T1R 1B2			
SALES	MAN ORDE	R NO.		RO.	NO.	PHONE		INVOICE DATE	TIME	INVOICE NO				
14	16 UNI	T 4 5	57	0	0674286	780-4	36-9375	08FEB13	12:37		04	4466004		
	QUA	ITITI	ES						BIN	and an and a state	PRICES	n - Constantino de la constante	OFFICE	
ORDE	RED SHIP	PED	B/0	V	PAR	NUMBER		DESCRIPTION	lander and a	LIST	NET	EXTENSION	0.32	
		1 1			MAKE: 2 T153744 FREIGHT 403-793	-			ERNO:	† 0 4 1 0 E X 8 3 2 7 4 . 4 8 8 . 0 0	274.48	HRS: 274.48 8.00	P C C L	
					** F ** 24 F ** AL ** ALL ** ALL	ARTS IOUR E L ELE RETUR FABR	HOURS: MERGENC CTRICAL NS ARE ICATED ******	********** MON-FRI 7A Y ON CALL COMPONENT SUBJECT TC HYDRAULIC **********	M-6PM PARTS, SARE A 30% HOSES *****	SAT SERVICE NON RETUI RESTOCK ARE FINA	7 AM - 4 PM & SALES RNABLE ING FEE SALE	* * * * * * * *		
DATE NO GC RETUI	S: NET 30 C OF INVC		'S FRO	PM	SHIP VIA BRO	evi coops	TITLES TO AL	L ITEMS REMAIN WIT LTD UNTI NTEREST AN	PARTS T		ACCOUNT	<b>AMOUNT</b> 274.48		
ACCOF ON TH OF GC PAST I MININ	aam trade - j Patners in Advo	ubile	- / /		recent pur AAMDC Please ma	Membe	hrough yo r account. <b>ues payab</b>	E FULLY PAIL	MISC N SALEST	AXABLE ONTAXABL AX PAY THIS TO		8.00		

	INVOICE	
	Invoice No.:	204
	Date:	19/07/2012
JUL 2 & 2012	Unit	457
	PO	
Ship to:	Hours	N/A
6	ion District	
P.O. Bag 8 550 Industrial Road West Brooks, AB_T1R 1B2		
	Eastern Irrigat P.O. Bag 8 550 Industrial	Invoice No.: Date: JUL 2 & 2012 Unit PO Hours Ship to: Eastern Irrigation District P.O. Bag 8 550 Industrial Road West

### Business No.:

Item No.	Unit	Quantity	Description	Тах	Unit Price	Amount
Shop Rate Shop Rate	Hour Hour		Check A/C Repair hitch pin bolt Subtotal:		115.00 115.00	115.00 57.50 172.50
		10-4	100 - 56330 E, Auc	. 03		
			GST Number: 814066809RT0001			
Shipped By:	Tracking N	lumber:				
Comment: Th Sold By:	ank you for your bus	iness!			Total Amount	172.50

### EID 410E - Unit 457 - 830348

### **ENGINE & POWER TRAIN SEG 1**

PART #

.

•

QTY PRICE

### FUEL INJ NOZZLES

TEE FITTING WASHER TUBE NUT SCREW INJ NOZZLE ROCKER COVER	R71963 R79605 R79604 R116366 RE48786	4 4 4 4 TOTAL	37.84 17.04 16.12 11.76 380.48 463.24
GASKET ORING RADIATOR	R123542 R123575	1 4 TOTAL	21.36 8.96 30.32
NUT WASHER TANK BOLT CLAMP FILLER CAP HOSE HOSE CLIP HOSE	14M7273 24M7298 AN205068 M86877 TY22470 AT173610 T155827 T155826 R56101 TY22566	2 4 1 2 4 1 1 3 10 FEET TOTAL	2.28 13.28 64.96 2.16 11.04 27.4 27.98 29.76 4.14 25.2 208.2
GASKET BOLT BOLT FAN DRIVE	R123352 19M7866 19M8163	1 1 1 TOTAL	16.78 1.86 2.22 <b>20.86</b>
TIGHTENER FAN HOUSING PULLEY BELT WATER PUMP KIT BOLT GASKET	RE518097 RE500538 RE505264 R135194 RE505981 RE508566 19M7796 19M7863 R123417	1 1 1 1 3 5 1 TOTAL	127.4 182 88.16 84.42 336 68.58 6.3 9.9 17.5 <b>920.26</b>

HYDRAULIC SYSTEM - SEG 2

35 Has labour AT<sup>\$135.00</sup>/Ha \$4725 \$16542.44 TOTAL.

OVERALL TOTAL 11817.44

### HYD. PUMP ORINGS

.

ORING ORING HOSE CLAMP HOSE FITTING ORING TEE FITTING ORING BACK CONTROLS	T76938 R29936 AH105968 X601-16 T29747 U13639 38H1325 R26448	5 5 4 27" 1 5 1 5 <b>TOTAL</b>	12.6 16.35 39.4 39.96 23.78 18.45 67.18 12 <b>229.72</b>
BASE NUT SPACER LOCK NUT BALL JOINT PIN PIN YOKE NUT ROD NUT BALL JOINT	AT178686 14H865 T161379 M68954 AT124107 R46528 R65563 T140328 14H913 T158810 14H774 AT169087	2 6 2 4 4 4 4 4 8 4 8 4 TOTAL	102.84 11.52 6.16 12.64 103.36 9.84 16.72 34.96 9.6 19.52 9.6 68.08 404.84
MFWD AXLE GREAS FITTING HOSE NUT AXLE BUSHINGS CAP SCREW WASHER BUSHING	JD7838 AT173254 E12379 19M7488 T119912 T18145	3 3 TOTAL 1 1	13.41 69.3 3.06 85.77 3.03 4.78 6.1
PIN THRUST WASHER THRUST WASHER BUSHING FITTING STEERING CYL.	AT164442 R46973 T80027 T140211 JD7838	1 4 2 2 2 TOTAL	277.2 15.4 24.56 72.12 8.94 412.13
BARREL ROD SEAL KIT	T153742 AT195573 T213801	1 1 1 TOTAL	157.5 630 107.8 <b>895</b> .3

CAB ATTN HYD

HOSE (FABRICATE) HOSE FITTING FITTING PROJECTILE	AT192250 X772TC-16 X1JS71-16-16 X1J971-16-16 UC36	1 13 1 1 2	18.72 77.26 102.32 2.82
ASSEMBLY ORING ADAPTER FITTING	M-3750 T76938 38H1164	2 1	5 5.04 17.5
ORING CAB REPAIR - SEG 3	R29936	2 TOTAL	6. <b>54</b> 235.2

WIPER ASSEMBLY

COVER	T142875	1	52.5
BOLT	M86436	4	8.4
KIT	AT151147	2	41.96
FITTING	AT116970	2	13.6
HOSE	TY25139	15 FEET	270
FITTING	T135764	1	3.52
H77698	30 PACK	90	113.4
GROMMET	N30256	1	2.04
BOLT	19 <b>M</b> 7077	4	5.04
WASHER	24H1287	2	1.8
WASHER	24M7239	2	6
WIPER REAR	TY16304	1	10.51
BRACKET	TY25006	3	16.26
SEAL	AT145688	1	151.2
WIPER ARM	AT151124	2	199.28
WASHER	T142519	2	7.74
NUT	T142519	2	7.74
WIPER LH	AT117254	1	24.16
WASHER	R63667	1	1.08
NUT	R63671	1	6.62
WIPER BLADE	AT117254	1	24.16
		TOTAL	942.85
DASH			0 12:00
BULB	AH108380	2	7.8
	/	TOTAL	7.8
		TOTAL	7.0
HEATER SYSTEM			
LOUVER	AT177227	2	50.22
SCREW	T159945	10	59.32 4.2
BRACKET	AT178892	1	4.2 49.8
RESISTOR	AT182200	1	49.8 25.42
SCREW	19M7774	4	
SCREW	19M7640	4	7.2
MOTOR	AT173906	2	0.64
BLOWER	AT175900 AT175764		264.6
BLOWER	AT175764 AT175763	1	45.34
	A11/3/03	1	45.34

NUT GASKET GROMMET SCREW	N125411 T158856 P41858 M83123	4 2 1 6 TOTAL	7.44 7.04 3.06 5.28 524.68
PINS & BUSHINGS RE	PAIR - SEG 4		
STAB ARMS			
LUBE FITTING SNAP RING PIN WASHER PIN SNAP RING WASHER SPACER PIN KIT BUSHING	JD7798 40M7066 T201909 T161036 T163109 40M7166 T75815 T189080 T127437 AT181327 H154404	4 8 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2	6.24 29.76 123.48 57.6 277.2 11.24 15.76 18.92 224.28 27.68 89.56
BUCKET & LINKS		TOTAL	881.72
PIN WASHER BOLT PIN BUSHING PIN LUBE FITTING SNAP RING WASHER LINK BUSHING BOLT WASHER PIN BUSHING ORING STRUC TUBE LINK BUSHING LUBE FITTING BUSHING BUSHING BUSHING ARM - DIPPERSTICK	AT180470 T29342 19M8017 AT180469 T162108 AT171077 T162396 40M7166 24H1594 AT181714 T166715 19M7872 28H3418 AT324237 T154273 R30916 T187184 AT181715 T166715 JD7798 H180402 H180402	1 4 2 1 2 1 8 3 1 1 1 1 1 1 4 2 1 1 4 1 1 4 1 1 1 1 4 1 1 1 1	201.6 17.04 5.88 144.9 7.04 207.9 28.16 16.86 7.2 196.1 32.9 2.94 3.48 105.84 141.44 8.06 35.7 196.1 32.9 6.24 55.98 55.98 1510.24
BUSHING SNAP RING WASHER PIN	H151820 40M7120 24H1635 AT169831	1 1 1	75.6 8.62 3 170.1

NUT BUSHING SCREW WEAR PLATE SHIM NUT SNAP RING WASHER PIN SPACER SNAP RING WEAR PLATE WASHER PIN SNAP RING BOLT WASHER WEAR PLATE BUSHING BUSHING GUIDE	T148410 T162581 19M7666 T157792 T157796 14M7400 40M7166 24H1594 AT171079 T160384 40M7179 T160300 24H1679 T153567 40M7066 19H2472 24M7240 AT173933 T166715 T166686 AT191241	1 2 12 4 8 12 2 2 1 1 2 4 4 4 1 2 4 4 1 2 6 6 6 2 3 2 1 TOTAL	2.76 123.16 35.28 277.2 82.72 26.64 11.24 4.8 157.5 69.3 9.32 36.56 8.48 105.84 7.44 12.6 23.52 178.92 98.7 100.76 48.5 1678.56
PIN LUBE FITTING BOLT NUT BOLT PIN COLLAR WASHER BOLT THRUST WASHER PIN WASHER PIN BUSHING WASHER BOLT PIN SNAP RING BUSHING BUSHING BUSHING	T153531 T162396 19M8021 14M7328 19M7954 T217548 T159999 24M7047 19M7493 T205875 T159800 24M7097 AT174631 M2649DN 24M7241 19M8035 T200240 N105572 H151328 H180402	2 4 1 2 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2	327.6 14.08 8.62 4.92 7.06 283.5 55.96 2.64 6.32 37.48 27.7 0.74 221.76 18.92 4.44 6.88 111.52 6.32 184.72 111.96 1443.14
BUSHING LUBE FITTING BOLT WASHER WASHER	H151542 T162396 19M7597 T101807 24H1616	1 5 1 1 8	39.56 17.6 3.85 29.92 19.68

BUSHING	T188568	2	13.72	
SHIM	T33376	8	30	
PIN	AT197726	1	371.7	
WASHER	T29342	1	4.26	
BOLT	19M8935	1	1.8	
PIN	T154922	1	226.8	
WASHER	24H1635	2	6	
SNAP RING	40M7120	2	17.24	
BUSHING	T164183	2	130.92	
WASHER	T208510	2	8.56	
		TOTAL	921.61	

.

•



VTI 232



 X
 3555 + 46 AVENUE S.E., CALGARY, ALBERTA T2B 3B3

 TEL. (403) 248-0018
 FAX (403) 273-1340

6511 - 67 STREET, RED DEER, ALBERTA T4P 1A3 TEL. (403) 343-7557 FAX (403) 343-7549

S	EASTERN IRRIGATION DISTRICT PO BAG # 8	S H
т О	BROOKS, AB TIR 1B2	SAMI

DATE OF INVO	DICE: L 30, 199	SHIPPED:	CUSTOMER P.O. NO:	VIA:	SALESMAN: CALVIN	CHECKED BY:
UNIT NO.	SERIAL NO.	MODEL				AMOUNT
N3747	AT181735	BUCKET	ONE (1) ONLY JOHN DEERE 3	6" DITCHING BUCKET		1,850.00
						1,000.00
			1			
			And 45	7		
				/		
				4		
,						
				GST # 8	99544779 (	GST EXEMPT
TRADE INS:						
				<u>1</u> -		
				· ,		
				Es. E		
				ð		
	ENTAL INVOICES PAYA INVOICES PAYABLE BE			Customer Invoice Copy V - Customer File Copy	TOTAL	1,850.00
WARRANTY	N NEW JOHN DEERE AS PER V	WARRANTY AGREEMENT	PINK - A	Accounting Copy		
WAHRANTY O	IN USED MACHINES IF ANY, MU	IST BE STATED ON THIS INVOIC	E GOLD -	Office Copy INVOICE # 940212	TOTAL	1,850.00



relations in the second			
tachne:         Numme         Repair:           Attemport         Repair:         Repair:           Attemport         Science of the second of the s			
Heurs:         Repair:           Apr/11/12         6131         Have Mathen Mach build a may roof for Used grants and consert articly son hardhes and got everything to tak at injection pump leaking and lossiced and relightmed line to get II to stop leaking.           Apr/21/12         6131         Have Mathen Mach build a may roof for Mathen and Son Mathen and got everything to tak at injection pump leaking and lossiced and relightmed line to get II to stop leaking.           Apr/21/12         6132         II Begur replaced MWD bath & resealed (utub packs in transmission. Replaced may line K pipa for the Mathen Machen Mathen and Son Mathen and Son Mathen and Son Mathen and Son Mathen	EID Service L Machine: Serial:	.og	
4pr/11/12         6112         Have Marken Mach huld a new rolf for hucket till cylinder on loader 5486 63. Install new seal kits and reassemth & clean to get them to take greaxe again. Greaxe unit: Cheel several reks on harkhee and got everything to tak at injection pump toking and locoreand an erightmend till to get it to stop leaking.           4pr/2012         6312         The spare regulator rear tress with ones removed from unit 501 which got new ones.           4pr/2012         6312         The spare regulator of ether injection new one found in fact the one working & found unit fauly need to order new one. Found 1 injector leak of Dec/2011           6548         Che complaint of ether injection new sone, found unit fauly need to order new one. Found 1 injector leak of Dec/2011         The spair resealance descreme cylinder           6549         Remote front counterweight & rad gut to get at coeline line leaking. Replace a 1 section of cooler line & remot field/2711         Get a the injection of the spain starting to come. Get pin hammered back in & install on the stall of new or thront windhield waker hose fitting.           6647         Installed new in thront windhield waker hose fitting.         Installed new in thront windhield waker hose fitting.           6647         Installed new in the day reass. Take with the verse windhield waker samebhy.         Che complaint of MFWOL hhub leaking oil & found noise leigod & found on steps type for installed new atternator purchased from Vergreen imp inval 1 104250 for a 5452.84.           6649         Install of new total searass and inter the leaking. Replace a tinking in the step in the step installe interverse in tha st	Unit:		
K i can to get them to take greake again. Greake unit. Orged several resk on backhoe and got everything to tak     apr/2012.     Kits The regulace rear tresk with ones removed from unit 501 which got new ones.     Apr/2012.     Kits The regulace rear tresk with ones removed from unit 501 which got new ones.     Apr/2012.     Cits The space regulace MWD shall. Rescaled future backs in transmission, Reparated eng of licek. Replaced hyd line     Nov /2012.     Cits Comparing of the the injection on working & found unit faulty need to order new one. Exond 1 injector like AV     Leg are resplaced tresk space backs and the space of the order of the AV of the	Date:	Hours:	Repair:
at injection gump leaking and loosened and relightened line to get it to stop leaking. Apr/20/12 6321 IT Repair replaced MIVD shaft & rescaled duch packs in transmission. Repaired engl it eak. Replaced hyd line Nov/20/12 CAL compliant of hetric injection rules in working & found unit faulty need to order new one. Found 1 pinetor leak of Chick compliant of hetric injection rules in working & found unit faulty need to order new one. Found 1 pinetor leak of Port/21/12 IT Repair rescaled steering cylinder 11 Repair rescaled steering cylinder 12 Repair rescaled steering cylinder 13 Rescaled in the steering cylinder 13 Rescaled in the steering cylinder 14 Respair rescaled steering cylinder 14 Respair rescaled steering cylinder 14 Respair rescaled steering cylinder 14 Respair rescaled steering cylinder 15 Rescaled II Section of Coule File Biolet	Apr/11/12	6317	Have Marken Mach build a new rod for bucket tilt cylinder on loader \$486.63. Install new seal kits and reassemble. Re
Apr/2012         Kirk's The replace rear tires with ones removed from unit 501 which got new ones.           Apr/2012         Site replaced MVD bhaft's rescaled ducht packs in transmission. Peparied engo if leak. Replaced Myd then Key Nov.           Nov./3012         Chk complaint of ether injector not working & found unit faulty need to order new one. Found 1 injector leak of the Nov.           Dec/2012         Chk complaint of ether injector not working & found unit faulty need to order new one. Found 1 injector leak of the Nov.           Dec/2012         Chk complaint of ether injector nuit & norige & jon starting to come. Get jon hammered back in & install a new Dir 18 Repair rescaled steering optimedr           Jan 1217         GES         Reinstall UH loader main pin because snag wore out & Broke. Replaced snap ring on RH pin alo.           Jan 1217         GES         Installed new in front windshield wather hose fitting.           Nar(7817)         Installed new in front windshield wather hose fitting.         Narked unit. Greased unit. Had to remove loader end pin tog etit to take greaser. To loader to get the nuit to Newcom Weld. & have eas to kitting unit alo. Narked unit.         Grease there ingo to take stress. To loader to get the nuit to Newcom Weld. & have eas to kitting unit stress to take stress.           Mar/0514         GES         Installed new alternator to take takes. To loader how the stress with one stress to unit stress with one stress with one stress to unit stress.           Narke/S113         GES         Installe new battery built builto to test end takes. Thisten rescale unit stress wit			& clean to get them to take grease again. Grease unit. Chged several zerks on backhoe and got everything to take gre
42(2)/12         632         17 Begaar replaced MKVD shaft & resealed duck packs in transmission. Repaired ong oil tak. Beplaced Myd Ine Nov/30/12           Chk complained of techn ingection row working & Loud in Utalyt need to order new one. Fourth Interform 14: 01 Add 2013 for 5260 59. Greased loader 40 ford Dec/20/12         6548           Dec/20/12         17 Begaar resoled steering cylinder         18 point and the VM 446/213 for 5260 59. Greased loader in the install of new to the bucket. Installed new to the bucket. Installed new to the bucket. Installed new to the dige and to get at cooler line laking. Beplace a 1' section of cooler line & reinst Fe/2/13           Dec/20/13         Semstall HI to new to edge on loader bucket. Installed new time installed new time of the MVD this this Using 01 kB fourth bunking: rack & garaing falid. Disassembed hub & get parts found it is cheaper to get a remand axle. Order remand axle forder remands axle forder remand sole ford on Saft 38.           Mar/05/14         6595         Chged their ingectoris the Newcom Weld & Brance and Sin state in axiety is a state state axiety is a state	1. 120/12		
<ul> <li>Nov/5/12</li> <li>Chk complaint of ether injector not working &amp; found unit faulty need to order new one. Found 1 injector leak of Dec/20/12</li> <li>Cheg et her injector unit &amp; notice purchased from trandit nov 0446/21 for 52630 5. "Created loader &amp; forond lines from tilt og to bucket missing a snap ring &amp; pin starting to come. Get pin hammered back in &amp; installal a new Dec/21/12</li> <li>JF Repar receased stercing cylinder</li> <li>Bernover font cuelters wingh &amp; and guart to get a tocole line leaking. Replace a 1'section of cooler line &amp; renst biolog lines and the stercing cylinder and the order line leaking. Replace a 1'section of cooler line &amp; renst windholed wiper ascembly.</li> <li>Repar Stering on Marci and B. Order remand alse (Tone Transmitta). The stering on larger line line leaking and lines and the order remand alse (Tone Researd mith and the stering of lines.</li> <li>Repar Stering on Marci and Discover Discover Weld &amp; have cars built go on safety latch ion tholds when end pin to get in table grosse. Take unit to fease can built go on safety latch ion tholds when end pin to get in table grosse. Take unit to fease can built go on safety latch ion tholds when end pin to get in table grosse. Take unit to fease can built go on safety latch ion tholds when end pin to get in to table grosse. Take unit to fease can built go on safety latch ion tholds when end pin to get lines to take grosse.</li> <li>Repar leak and the pin do the stering on the stering the stering group start line leaking and the stering on the stering the stering on the stering on the stering on the stering on the stering the stering the stering the stering the stering on the stering the sterense the stering the stering the stering the stering the ste</li></ul>		(22)	5
bc/20/12         654         Cheged their injector unit & nozile purchased from Brandt in 04 46/213 for 5260.99. Greated loader & Brandt           bc/21/12         JT Repair recoded steering sylinder         JT Repair recoded steering sylinder           bc/21/12         JT Repair recoded steering sylinder         JT Repair recoded steering sylinder           bc/21/13         6603         Remove front counterweight & rad guart to get at cooler line leaking. Replace a 1' section of cooler line & reinst           bc/21/13         6603         Remove front counterweight & rad guart to get at cooler line leaking. Replace a 1' section of cooler line & reinst           bc/21/13         6603         Installed new cut edge to no loader bucket. Installed new rad word and is for brandt is in 64468852. Installed new hole by the part end of bucket cylinder. Washed unit. Greased unit. Had to remove loader company to get at mortal and is conter annowable. Conter removes date get and the part end of bucket cylinder. Washed unit. Greased end is a period. To all the part is a second by the part of the second by the part of the part is a second by the part of the part is a second by the part of the part is a second by the part of the part is a second by the part of the part is a second by the part of th		6321	
bill         bill <td< td=""><td>1007/30/12</td><td></td><td></td></td<>	1007/30/12		
Dec(21)12         JT Repair reseled steering cylinder           Jan(23)13         S52           Senstall How with from windwindwid subter hase filting.         The leaking Replace a 1'section of cooler line & reinst Fe/2/713           Senstalled new cut edge on loader bucket. Installed new car windhield wiper assembly.         Chk complain of MWD Ih hub leaking 018 found housing cack & prioring failed. Dissembed hub & get parts found it is cheaper to get a remand axie. Order remand axie. From Brandt & install in will 04 44688562. Installed new installed new atternator purchased from foregreen imp invol 01 104240 for a 5452.84.           Api/05/14         S66         Chack complain to parts and the order remand axie. Order remand axie. Order remand axie. New Yashed hub & get parts found it is cheaper to get a remand axie. Order remand axie. And the aver will be wasted y lack to it holds who installed new atternato purchased from foregreen imp invol 01 104240 for a 5452.84.           Mar/05/14         S56         Chack density in the state of loader. To you consolid hub in the state installed new attern for advert pick and the state of loader. Clain batter postal while they were out to chg hyd lines.           Nov/0714         Travel to den the state of loader. Clain batter postal while they were out to chg hyd lines.           Nov/0717         Travel to den the state regress from distall den with a state regress from distall den with a state regress of a state r	Dec/20/12	6548	
Jan (11)         652         Reinser forta counterweight & radig guard tig at a coler line laxing. Replace a 1 section of cooler line & reari Mar(98/13)           Jan (25)         See         Installed new th front windshield washer hase fitting.           Jan (26)         Installed new th front windshield washer hase fitting.           Jan (26)         Installed new th front windshield washer hase fitting.           Jan (26)         Installed new th front windshield washer hase fitting.           Jan (26)         Installed new th front windshield washer hase fitting.           Jan (26)         Installed new the front washer of a four distributed washer hase fitting.           Jan (26)         Installed new the front washer of the four distributed washer hase fitting.           Jan (26)         Installed new alternator purchased from Vergreen inplived Di Jack Jack 200 for 3 452 kork Nather Alter Vergreen Vergre	Dec/21/12		
<ul> <li>Jan (25) 13</li> <li>G603 Remove front counterweight &amp; and guard to get at cooler line leaking. Replace a 1'section of cooler line &amp; reinst Fe/2/713</li> <li>G664 Installed new cut edge on loader bucket. Installed new car windshield wiper assembly.</li> <li>Chk complaint of MWD Lh hub leaking oil &amp; forum Musing cack &amp; gening failed. Dissembled hub &amp; get parts for und it is cheaper to get a remand axic. Order remand axie. Chear windshield wiper assed unit. Had to remove loader t end pin to get it to take grease. Take unit to Newcom Wid &amp; have assolutin up on stepsy takets to it holds when to have the order windshield wiper assed unit. Had to remove loader t end pin to get it to take grease. Take unit to Newcom Wid &amp; have assolutin up on stepsy takets to it holds when bett. Replaced Takets and the transmitter of the take grease. Take unit to Newcom Wid &amp; have assolutin up on stepsy takets to it holds when to take the great in the stepsy takets to ith olds when to take the great in the stepsy takets to the one working.</li> <li>Mar(25)/14 Build new pin for safety lock for loder in up postion. Had Brain removes some pins on loader to get then to take.</li> <li>Navg/17/14 O88 Installed new battery hold down brackets purchased from Brandt.</li> <li>Navg/17/14 O88 Installed new battery hold down brackets purchased from Brandt.</li> <li>Navg/17/14 O88 Installed new battery hold down brackets purchased from Brandt.</li> <li>Nava Install Sager Heater. Chean out cab heater and change cab air filter. Cheed osniphint of unit not moving &amp; found switch failed &amp; bypassed for now until new line witch were failed to take the assoluting an stepsy take set and out cab heater and change cab air filter. Cheed osniphint of unit not moving &amp; found switch take as the set of the stark found and the stepsy from heater because it may air locking &amp; operater with moving faile for the stepsy found the stark found an etypitate and of them. Retry unit &amp; now is good. Installed new filter and stark fo</li></ul>		6572	
<ul> <li>Feb(27)13 6668 Installed new rh front windshield waber hose fitting.</li> <li>Installed new un elege on loader buckt. Installed new rear windshield wiper assembly.</li> <li>Chk complaint of MFWD Lh hub leaking oil &amp; found housing crack &amp; gearing failed. Disassembet hub &amp; get parts found it is chaper to get a remain date. Ordie remained alls from failed wiper assembly.</li> <li>Apr/05/13 6698</li> <li>Ford all is to lake greater. Take unit to Newcom Wold &amp; have cars build on safety latch so it holds when bett. Chged ether injector bottle &amp; test. Found notzle plugged &amp; replaced also. Retry &amp; now it appears to be working.</li> <li>Build new pin for safety lock for older in up position. Had Brain removes some pins on loader to get them to take.</li> <li>Ney/124/13 6788</li> <li>Installed new alternator: purchased from Evergreen imp Inv&amp; 01.102340 for a 5452.40 (As Neu Parts Ne</li></ul>	Jan/25/13	6603	
Chk complaint of MK*W0 Lh hub leaking oil & found housing crack & gearing failed. Disasembed hub & get parts     found it is charger to get a remand axie. Order remand axie from Brandt & installed new     found its charger to get a remand axie. Order remand axie from Brandt & installed new     hourd its charger to get a remand axie. Order remand axie from Brandt & installed new     hourd its charger to get a remand axie. Order remand axie from Brandt & installed new     hourd its charger to get a remand axie. Order remand axie from Brandt & installed new     hourd its charger to get to take greate. Take unit to Newcom Wold & have ears built up on safety lacts on to holds when     leapt124/13 6748     Hind To get to take greate. Take unit to Newcom Wold & have ears built up on safety lacts on to folds     wer/N3/14     See Charge other safety lact for order in up position. Had Grain removes more pins on loader to get them to take     hug/18/14     Replaced 2 leaking hyd lines on RH side of loader. Clean battery posts while they were out to chg hyd lines.     Nv/0714     708     Seg for with reade up at Paramount hyd. Travel back & install new line & top up hol level. Topue. Topue. Topue.     Install for aw battery hold down brackets purchasing co bain flitter.     Seg for with leaders clean out cab heater and change co bain flitter.     Seg for with leaders.     Install for aw litter, window. Install new EID logos.     Check complaint of the meater, clean out cab heater and hange co bain flitter.     Seg for with leaders.     Install for aw litter, clean out cab heater and hange co bain flitter.     Seg for with leaders.     Install for aw get avert mismit and its with so of the worker go an widshield washer tak.     Sefficient     Install for aw get avert mismit and its with so of the worker go an widshield washer tak.     Sefficient     Install for aw leader, clean out cab heater and hange cob mismit and the set or gain avert     Install forew flitter aw leader and thange cob mismit avert mas where the pa	Feb/27/13	6668	
Apr/05/13         669,         found it is cheaper to get a remand axie. Order remand axie from Brandt & install inv 06 4468652. Unstalled no bet: Chefe oring on fitting on barrel end of bucket cylinder. Watek dunit, Greased unit, Had to remove loader end pin to get it to take grease. Take unit to Nexocom Weld & have ears built up on safety latch so it holds when expeription. Had Brain remove some pins on loader to get them to take unit. Yast 10 402540 for a 54258 44.           Mar/05/14         6598         Cheget ether injector bottle & test. Found notife plugged & replaced also. Retry & now it appears to be working.           Mar/05/14         Build new battery hold down brackets purchased from Wargersen Ips mol to 10 402540 for a 54258 44.           Mar/05/14         Replaced 2 leaking hud lines on RH add of loader. Clean battery ports while they ware out to chg hyd lines.           Nov/0717         Travet to Gen pit & Ark complaint of hyd leak. Tound hyd line to steering valve leaking & removed. Took line bas & get new 1 made up at Paramount hyd. Travel back & install new line & to get new lines. Norma & full mess to hydrawill and they diages and lines to hydrawill and they diages and lines to hydrawill and they diages and lines to hydrawill washer tank & line on train shifter           Dec/15/15         Travet to Ge alges in bottom RH remark widawill and sep at an inter. Cnegd witches for clutch cut on trans shifter retightered all of them. Retry unit & now is good installed new their sep on windshield washer tank & refilied to tank train a locking & operater will monitor & let me know ill works properly now.           Espar is think to working properly. Installed a separate fuel suction table in fuel tank & run a new fuel line to espit fuel to separate set t	Mar/08/13		
Apr/05/13         669,         found it is cheaper to get a remand axie. Order remand axie from Brandt & install inv 06 4468652. Unstalled no bet: Chefe oring on fitting on barrel end of bucket cylinder. Watek dunit, Greased unit, Had to remove loader end pin to get it to take grease. Take unit to Nexocom Weld & have ears built up on safety latch so it holds when expeription. Had Brain remove some pins on loader to get them to take unit. Yast 10 402540 for a 54258 44.           Mar/05/14         6598         Cheget ether injector bottle & test. Found notife plugged & replaced also. Retry & now it appears to be working.           Mar/05/14         Build new battery hold down brackets purchased from Wargersen Ips mol to 10 402540 for a 54258 44.           Mar/05/14         Replaced 2 leaking hud lines on RH add of loader. Clean battery ports while they ware out to chg hyd lines.           Nov/0717         Travet to Gen pit & Ark complaint of hyd leak. Tound hyd line to steering valve leaking & removed. Took line bas & get new 1 made up at Paramount hyd. Travel back & install new line & to get new lines. Norma & full mess to hydrawill and they diages and lines to hydrawill and they diages and lines to hydrawill and they diages and lines to hydrawill washer tank & line on train shifter           Dec/15/15         Travet to Ge alges in bottom RH remark widawill and sep at an inter. Cnegd witches for clutch cut on trans shifter retightered all of them. Retry unit & now is good installed new their sep on windshield washer tank & refilied to tank train a locking & operater will monitor & let me know ill works properly now.           Espar is think to working properly. Installed a separate fuel suction table in fuel tank & run a new fuel line to espit fuel to separate set t			Chk complaint of MFWD Lh hub leaking oil & found housing crack & gearing failed. Disassembed hub & get parts price
belf. Cheed oring on fitting on barrel and of bucket cylinder. Washed unit, Greased unit, Had to remove loader 1           end pin to get it to take greas. Take unit to Newsgreen Imp Inv 0.1 1042540 for a 5452.84.           Mar/05/14         058           Begle Levin for after to take greas. Take unit to Newsgreen Imp Inv 0.1 1042540 for a 5452.84.           Mar/05/14         058           Begle Levin Ipst of Installed new alternator purchased from Branck.         Data State 1000000000000000000000000000000000000	Apr/05/13	6694	found it is cheaper to get a remand axle. Order remand axle from Brandt & install inv# 04 44688562. Installed new fai
sept2(3/13)         67.4         Installed new alternator purchased from Evergreen Imp Inv 01 104256 for a 5452.84.           wurc/18/14         Build new pin for safety lock for loder: in up postion. Had Brain remove some pins on loader to get them to take, Aug/18/14           Replaced 2 leaking hud lines on RH side of loader. Clean Dattery posts while they were out to fully lines.           Nov/0714         7038           Dec/17/14         7038           Dec/17/14         7038           Dec/17/14         7038           Dec/17/14         7038           Travel to Gem pit & Chk complaint of Hyd leak. Found hyd line to steering valve leaking & remouved. Took line bake get new times toom pravel taking hud lines to new until new 1 arrives from Brandt.           Dec/16/15         7100           Travel to J-Am & chk complaint of J. Found loose hose clamps on Hyd creun lines to Hyd tank & Iline on trans shifter resigned all of them. Retry unit & now is good. Installed enew fill arc ap on windhield washe tank & crifield to espin retry lines do go parter will montor & Let me know it it works properly now.           Espar is still not working properly. Installed a separate fuel suction tube in fuel tank & run a new (Let line to espin from enew suction tube. Found it is dorks properly now.           Espar is still not working properly. Installed a separate fuel suction tube in fuel tank.         Run and weilt in the stoem it working properly now.           Espar is still not working properly. Installed as esparate fuel suctin tup where Espar was tied into uses a rubber ge fuel t	, , , = 3		belt. Chged o-ring on fitting on barrel end of bucket cylinder. Washed unit. Greased unit. Had to remove loader cylind
<ul> <li>Mar/05/14 6958 C. Reget ether injector both &amp; test. Found nozze plugged &amp; replaced also. Retry &amp; now it appears to be working, uner/18/14 Build new pin for to bet to for in up postion. Inad Brain remove some pins on loader to get them to take haug/18/14 7082 Function on RH side of Diader. Clean battery posts while they were out to che hyd lines. New/0714 7083 Installed new battery hold down brackets purchased from Brandt.</li> <li>Travel to Gen pil &amp; Ch Koomplaint of hyd leak. Found hyd line to steering valve leaking &amp; removed. Took line battery and up at Paramount hyd. Travel back &amp; install new line do to phyd level. To pup coolant level.</li> <li>Mav/05/15 7160 Install ed wup at Paramount hyd. Travel back &amp; install new Ello Digos. Cheed complaint of unit not moving &amp; found in switch failed &amp; bypassed for now unit new 1 arrives from Brandt.</li> <li>Dec/05/15 N/A Install Espar Heater, clean out cab heater and change cab air filter. Cheed switches for clutch cut on trans shifter Travel to col kale pit &amp; chick Espar eng heater complaint of 572. Remounted fuel plump for heater because it may air locking &amp; operater will monitor &amp; let me know filt avorks properly now.</li> <li>Espar is tall in to working properly. Installed exparate fuel suct to the lin fuel tank &amp; run are registened all of them. Retry unit &amp; now is go col. Install env heater fram switch.</li> <li>Install enve fuel pump for haster on Chaing at charcon firting at fuel transfer pumy where Espar was tied into uses a rubber gif uel to espit fuel to espit found to is gover any to the system stall espit avorks progerly now.</li> <li>Espar is tall in ow bar heater on Diving Bropper Jon stalled explaint and in the stark fuel ner to espit fuel to respit espit and to try to get F52 cole constend.</li> <li>Mar/17/16 7360 Installed new fuel mem to park heater to try to get F52 cole constend.</li> <li>Mar/17/17 7560 Travel to Crawing Valley pit &amp; reinstall new hydraulic line to barrel end of bucket cylinder which ope</li></ul>	Seat /24 /a-	(3)	
unc/13/14         Build new pin for safety lock for loder in up postion. Had Brain remove some pins on loader to get them to take May/13/14           Replaced Leaking by dines on RH side of loader. Clean battery posts while they were out to cgh by dines.           Nov/0714         7038           Dec/17/14         7088           Travel to Gem pit & Chk complaint of hyd leak. Found hyd line to sterring valve leaking & removed. Took line bak & get new 1 made up at Paramount hyd. Travel back & install new line 3 too hyd level. Top up colant level.           May/05/15         7160           Install Expar Heater, clean out cab heater and change cab air filter. Clead switches for clutch cut on trans shifter.           Dec/16/15         7203           Travel to rock lake pit & chk Espar eng heater complaint of F52. Remounted fuel pump for heater because it mai air locking & operater will now it it works properly now.           Jan/27/16         7241           Travel to rock lake pit & chk Espar eng heater complaint of F52. Remounted fuel pump for heater because it mai air locking doperater will montor & lit et me how if it works properly now.           Jan/27/16         7259           from new suction tube. Found the factory fitting at fuel trans for pum phere. Spar was tied into uses a rubber git not tha start becking and pump on Espar heater to try to get F52 code repaired.           Mar/11/16         7350           from new suction tube. Found the factory fitting at fuel trans for answitch.           reb/02/16         Installed new			Installed new alternator purchased from Evergreen Imp Inv# 01 1042540 for a \$452.84
Aug/18/14         Replaced 2 leaking hyd lines on RH side of loader. Clean battery posts while they were out to chig hyd lines.           New/0714         7038         Installed new battery hold down brackets purchased from Brand.           Travel to Gem JK & chk complaint of hyd leak. Found hyd line to steering valve leaking & removed. Took line bak get new 1 made up at Paramount hyd. Travel back & install new Elio Bogs. Chked complaint of unit not moving & found is which failed & bygassed for now until new 1 install new Elio Bogs. Chked complaint of unit not moving & found is which failed & bygassed for now until new 1 arrives from Brandt.           Dec/16/15         N/A         Install new Elio Bogs. Chked complaint of unit now is good. Installed new fillar cap on windshield washer tank & refiled to Tarwel to col kale pit & chk Ek Spar eng hearter complaint of Ts2. Remounted fuel pump for heart because it may air locking & operater will monitor & let me know if it works properly now.           Stapari S11 not working properly. Installed as separate fuel suction tube in fuel tank & run a new fuel line to exp from mex suction tube. Found the factory fitting at fuel transfer pump where Espar was tied into uses a rubber a fuel/02/16           0         Install new fuel pump on the meter not working properly for poor connections but everthing looks ok. Will ord install new fuel pump on Espar heater to try to get F32 code repaired.           1/11/16         7360         Install new tach hour meter. Old 1 had about 7300hrs on it. Install new heater fan switch.           1/20/21/16         O Lesk pit & chy dus by at Ravel to Kitsim dirt pit and install.           1/20/21/17         7560         <		6928	Criged etner injector bottle & test. Found nozzle plugged & replaced also. Retry & now it appears to be working prope
Nov(0712         7038         Installed new battery hold down brackets purchased from Brandt.           Dec/17/14         7082         & get new 1 made up at Paramount hyd. Travel back & install new line & top up hyd level. Top up coolant level.           May(05/15         7160         Install new glass in bottom RH rear window. Install new EID logos. Cheed complaint of unit not moving & found varines from Brandt.           Dec/15/15         7160         Install new glass in bottom RH rear window. Install new EID logos. Cheed complaint of unit not moving & found in the new fills reago no windshield washer tank & refilled ta switch failed & hypased for new unit lew at virkes from Brandt.           Dec/16/15         7203         Travel to rock lake pit & che K Espar eng heater complaint of f52. Remounted fuel pump for heater because it mai air locking & operater will monitor & let me know if it works properly now.           Sparp is still not working properly. Installed as separate fuel suction tube in fuel tank & run a new fuel line to espar is still not working properly now.           Sparp is still not working properly now.         Espar vas till not working properly now.           Sparp is still not working properly now.         Espar vas till not working properly now.           Sparp is still not working properly now.         Espar vas till not working properly now.           Sparp is still not working properly now.         Espar vas till not working properly now.           Sparp is still not working properly now.         Espar vas till ont working properly now.			Benlaced 2 leaking byd lines on PH side of lander flags have
Dec/17/14         Travel to Gem pit & chk complaint of hyd leak. Found hyd line to steering valve leaking & removed. Took line bak & get new 1 made up at Paramount hyd. Travel back & install new line & top up hyd level. Top up coolant tevel.           May/05/15         7160         switch failed & bypassed for now until new 1 nrives from Brandt.           Dec/15/15         N/A         Install new on topso. Check complaint of unit now ing & found switch alided & bypassed for now until new 1 arrives from Brandt.           Dec/15/15         N/A         Install expert Heater, clean out cab heater and change cab air filter. Chged switches for clutch cut on trans shifter reightened all of them. Retry unit & now is good. Installed new fillar cap on windshield washer tank & refiled to Travel to rack lake pit & chk Espar eng heater complaint of 152. Remounted fulle pump for heater because it may air locking & operater will monitor & let me know if it works properly now.           Espar is tall not working properly for poor connections but everthing looks ok. Will ord fuel to salk it may be letting air in suction line oor goor connections but everthing looks ok. Will ord fuel to salk it may be letting air in suction line oor goor connections but everthing looks ok. Will ord Install new fuel pump for heating to Espar heater to try to get 152 code repaired.           Mar/11/16         7560         Install expert & chk to try to get 152 code repaired.           Mar/11/16         7560         Install expert expert to try to get 152 code repaired.           Mar/11/16         7560         Install expert expert hout to try to get 152 code repaired.           Mar/11/16         7		7038	
Beget new 1 made up at Paramount hyd. Travel back & install new line & top up hyd newl. Top up coolant level.           Way/05/15         7160         Install new glass in bottom MH rear window. Install new BLD logos. Chked complaint of unit not moving & found is witch failed & bypassed for now until new 1 arrives from Brandt.           Dec/05/15         N/A         Install Espar Heater, clean out cab heater and change cab air filter. Chged switches for clutch cut on trans shifter Dec/16/15           7003         Travel to Jam & chk complaint of all. Found loose hose clams on hyd returm lines to hyd tank & Iline on trans is post and the set on the set of the set on trans of the trans is post and the set on the set of the set of the set on the set of the set of the set on the set of the set			
<ul> <li>May/05/15 7160 Install new glass in bottom RH rear window. Install new EID logos. Chked complaint of unit not moving &amp; found switch failed &amp; bypassed for now unit new tarrives from Brandt.</li> <li>Dec/05/15 N/A Install Espar Heater, clean out cab heater and change cab air filter. Chged switches for clutch cut on trans shifter retightened all of them. Retry unit &amp; now isgod. Installed new filtar cap on windshield washer tank &amp; retiliget can tak &amp; retiliget can an are type feed all of them. Retry unit &amp; now isgod. Installed new filtar cap on windshield washer tank &amp; retiliget can are tak in a retightened all of them. Retry unit &amp; now isgod. Installed new filtar cap on windshield washer tank &amp; retilidet as a practice in the integration on windshield washer tank &amp; retilidet as a practice in the integration on windshield washer tank &amp; retilidet as espara feuls suction tube in fuel tank &amp; run a new fuel line to espatian (ching properly. Installed a separa feuls suction tube. Found the factory fitting at fuel transfer pump where Espar was teid into uses a rubber of feel to seal &amp; it may be letting air in suction line over night when temperatures are below freezing. Greased unit tach hour meter combo for h meter not working properly for poor connections but everthing looks ok. Will or to be fee/02/16 0 Installed new tied pump on Espar haeter to try to get FS2 code repaired.</li> <li>Mar/11/16 7360 Installed new tied pump on Espar haeter to try to get FS2 code repaired.</li> <li>Mar/11/17 7560 Grease unit.</li> <li>Travel to Crawling Valley pit &amp; reinstall new hydraulic line to barrel end of bucket cylinder which operator removes the most and any properd up hydraulic level. Greased unit Wash oil of of windshield.</li> <li>Maz JG Grease unit.</li> <li>Travel to Crawling Valley pit &amp; reinstall new hydraulic line to have red replaced for chrome damage &amp; for AC clutch Aug/11/17 7568 Travel to Crawling Valley pit &amp; reinstall new hydraulic lines to sort closes bette.</li> <li>Pick up</li></ul>	Dec/17/14	7082	& get new 1 made up at Paramount byd. Travel back & install new line 8 top up byd level. Top up poplast level of the
switch failed & bypassed for now until new 1 arrives from Brandt. bec/lb/15 N/L Install Espar Heater, clean out cab heater and change cab air filter. Chegd switches for clutch cut on trans shifter Chegt/b/15 N/L Travel to 1-dam & chk complaint of oil. Found loose hose clamps on hyd return lines to hyd tank & 1 line on trans retightened all of them. Retry unit & now is good. Installed new filtar cap on windshield washer tank & refilled t lan/21/15 Tavel to rock lake pit & Ch Espar eng heater complaint of 52. Remounted fuel pump for heater because it may in locking & operater will monitor & let me know if it works properly now. Espar is till not working properly. Installed a separate fuel suction tube in fuel tank & run a new fuel line to esp from new suction tube. Found the factory fitting at fuel transfer pump where Espar was tied into uses a rubber g fuel to seal & it may be letting air in suction line over night when temperatures are below freezing. Greased unit tach hour meter comb of nr meter now horking properly for poor connections but everthing looks ok. Will ord feb/02/16 Installed new fuel pump on Espar heater to try to get F52 code repaired. Mar/11/16 Toso Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC cor out. Reinstalled seat. Readjusted rear window latches so it closes better. Dec/05/16 Toso Grease unit. Travel to crawing Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remo mew made up. Topped up hydraulic level. Greased unit: 40and 10870 for a total of 578.64.4.1 removed ba forks & straightened. Reinstalled on weith our whiche source and the regulated. Reinstall when the sour weith of Dundwiting to sourch ensiting & found and is grean. Had // 17 Toso Travel to jobsite west of Brooks. Check complaint of unit ver heating & found cal of 578.64.4. I removed ba forks & straightened. Reinstalled on weither on Jame Adjusted Syna prozeles on front windo Replaced flord subcet tristes to 50 PSI & rear to 38P			Install new glass in bottom RH rear window. Install new FID logos. Chked complaint of unit not moving & found clutch
Dec/05/15       N/A       Install Espar Heater, clean out cab heater and change cab air filter. Cheed switches for clutch cut on trans shifter retightened all of them. Retry unit & now is good. Installed new filter cap on windshield waher tank & refilted ta retightened all of them. Retry unit & now is good. Installed new filter cap on windshield waher tank & refilted ta an i locking & operator will monitor & lear mesh you works properly now.         1an/21/16       7241       Travel to rock lake pit & chk Espar eng heater complaint of F52. Remounted fuel pump for heater because it may air locking & operator will monitor & lear heaver it works properly now.         1an/21/16       7259       from new suction tube. Found the factory fitting at fuel transfer pump where Espar was tied into uses a rubber grup table table sitting air usuition line over night when temperatures are below freezing. Greased unit tach hour meter combo for hr meter not working properly for poor connections but everthing looks ok. Will ord install ed new fuel pump on Espar heater to try to get F52 code repaired.         Mar/11/16       7360       Installed new fuel pump on Espar heater to try to get F52 code repaired.         Mar/11/17       7506       Check complaint of cab heater not blowing & found fain is working. Removed seat base to get at heater & A C cor out. Reinstalled seat. Readjusted rear window latches so it closes better.         Dec/05/16       7540       Pick up new batteries at Napa & travel to Kisim dirt pit and install.         Mar/11/17       7568       Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator removnew made up. Topped up Hydrualic level. Greased u	May/05/15	7160	switch failed & bypassed for now until new 1 arrives from Brandt
Dec/16/15         7203         Travel to J-dam & chk complaint of oil. Found loose hose clamps on hyd return lines to hyd tark & line on trant retightened all of them. Retry unit & now is good. Installed new fillar cap on windshield washer tark & refilled to a sparter will monitor & let me know if it works properly now.           Espari is till not working properly. Installed a separate fuel suction tube in fuel tark & run a new fuel line to espir from new suction tube. Found the factory fitting at fuel transfer pump where Espar was tied into uses a rubber g fuel to seal & it may be letting air in suction line over night when temperatures are below freezing. Greased unit tach hour meter cmbb of hr meter not working properly for poor connections but everthing looks ok. Will ord tach hour meter (mb of hr meter not working properly for poor connections but everthing looks ok. Will ord installed new fuel pump on Espan heater to try to get FS2 code repaired.           Mar/11/16         7250         Installed new rim on LH front tire to replaced the old cracked rim.           Nov/08/16         7500         Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC cor out. Reinstalled seat. Readjusted rear window latches so it closes better.           Dec/05/16         7540         Pick up new batteries at Napa & travel to Kitsim dirip it and install.           Mar/11/17         7568         Travel to Crawling Valley pit & reinstall new hydraulic line to barcel and bucket cylinder which operator remoner made up. Topped up hydralic level. Greased unit. Wash oil off of windshield.           Mar/11/17         7608         Travel to crawling Valley pit & reinstall new hydraulic line to bare cl	Dec/05/15	N/A	
Integration         Treightened all of them. Retry unit & now is good. Installed new fillar cap on windhield washer tank & refilled ta           Jan/21/16         7241         Travel to rook lake pit & chk Espar eng heater complaint of F52. Remounded fuel pump for heater because it may air locking & operater will monitor & let me know if it works properly now.           Espar is still not working properly. Installed a separate fuel suction tube in fuel tank & run a new fuel line to espirate the suction tube. Found the factory fitting at fuel transfer pump where Espar was tied into uses a rubber g fuel to seal & it may be letting air in suction line over night when temperatures are below freezing. Greased unit tach hour meter combo for hr meter not working properly for poor connections but everthing looks ok. Will ord installed new fuel pump on Espar heater to try to get F52 code repaired.           Feb/02/16         Installed new tach hour meter. Old 1 had bout 7300hrs on it. Install new heater fan switch.           Feb/03/17         Foso         Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC con out. Reinstalled seat. Readjusted rear window latches so it closes better.           Pec/05/16         Fost une winteries at Napa & travel to Kitsim dirt pit and install.           Feb/01/17         7560         Fick up unp on Espar leader the bydraulic line to barrel end of bucket cylinder which operator remorenew made up. Topped up hydraulic leud. Greased unit. Wash oil off of windshield.           Mar/11/17         7603         Fick up hydraulic leud. Greased unit over heating & found losse contenegar Split oil cooler & AC           M	Dec/16/15	7202	Travel to J-dam & chk complaint of oil. Found loose hose clamps on hyd return lines to hyd tank & 1 line on transmiss
Jan/21/16       7241       Travel to rock lake pit & chk Espar eng heater complaint of F52. Remounted fuel pump for heater because it may air locking & operater will monitor & let me know if it works properly now.         Jan/27/16       7259       from new suction tube. Found the factory fitting at fuel transfer pump where Espar was tied into uses a rubberg fuel to sale & it may built buil	Dec/16/15	/203	retightened all of them. Retry unit & now is good. Installed new fillar cap on windshield washer tank & refilled tank
air locking & Operater will monitor & let me know if it works properly now.         Espar is still not working properly. Installed a separate fuel suction tube in fuel tank & run a new fuel line to esparate still not working properly. Installed a separate fuel suction tube in fuel tank & run a new fuel line to esparate still not working properly for poor connections but everthing looks ok. Will ord         ifeb/02/16       0       Install new tach hour meter. Old 1 had about 7300hrs on it. Install new heater fan switch.         ifeb/02/16       0       Install enew tach hour meter. Old 1 had about 7300hrs on it. Install new heater fan switch.         ifeb/02/16       0       Installe new tim on LH front tire to replaced the old cracked rim.         0x/08/16       7520       Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC cor         0x/08/17       750       Grease unit.       Travel to Crawing Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remornew made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.         4Aug/09/17       7603       Travel to Crawing Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remornew made up. Topped up hydrualic level. Greased unit over heating & found rap lugged. Split oil cooler & AC 40x0/01/17         7608       Travel to jobsit west of Brooks. Check complaint of unit over heating & found rap lugged. Split oil cooler & AC 40x0/01/17         7609       Freek complaint of lights not working & found rim is or rear diff. Replaced	lan/21/16	7241	Travel to rock lake pit & chk Espar eng heater complaint of F52. Remounted fuel pump for heater because it may have
Jan/27/16       7259       from new suction tube. Found the factory fitting at fuel transfer pump where £spar was tied into uses a rubber g fuel to seal & it may be letting air in suction line over night when temperatures are below freezing. Greased unit tach hour meter combo for hr meter not working properly for poor connections but everthing looks ok. Will ord feb/05/16         feb/02/16       0       Installed new fuel pump on Espar heater to try to get F52 code repaired.         Mar/11/16       7360       Installed new fuel pump on Espar heater to try to get F52 code repaired.         Mar/11/16       7360       Installed new rim on LH front tire to replaced the old cracked rim.         Nov/08/16       7520       Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC cor         out. Reinstalled seat. Readjusted rear window latches so it closes better.       Dec/05/16       7540         Pick up new batteries at Napa & travel to Kitsim dirt pit and install.       Grease unit.       Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remornev made up. Topped up hydraulic level. Greased unit. Wash oil off of windshield.         Aug/09/17       7603       Travel to Crawling Valley pit & reinstall end no Luck. Tested AC circuit & found loase connection under seat for AC clutch         Aug/11/17       7660       Check complaint of lights not working & found wiring to switches unhooked & reconneted.         Aug/01/17       7680       Check complaint o	3011/21/10	/241	air locking & operater will monitor & let me know if it works properly now.
fuel to seal & it may be letting air in suction line over night when temperatures are below freezing. Greased unit tach hour meter comb for hr meter not working properly for poor connections but everthing looks ok. Will ord Installed new fuel pump on Espar heater to try to get F32 code repaired.           Feb/05/16         Installed new fuel pump on Espar heater to try to get F32 code repaired.           Nar/11/16         7360           Feb/05/16         Installed new fuel pump on Espar heater to try to get F32 code repaired.           Nov/08/16         7520           Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC cor out. Reinstalled seat. Readjusted rear window latches so it closes better.           Dec/05/16         7540           Pick up new batteries at Napa & travel to Kitsim dirt pit and install.           Feb/01/17         7566           Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remo- new made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.           Aug/09/17         7668           Fravel to iboits west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC           Nov/01/17         7660           Grease unit. Topped up hydrualic level. Grease da walke. Unon loose connection under seat for AC clutch           Nov/01/17         7660           Check complaint of lights not working & found wiring to switches unhooked & reconnected. <td></td> <td></td> <td>Espar is still not working properly. Installed a separate fuel suction tube in fuel tank &amp; run a new fuel line to espar hea</td>			Espar is still not working properly. Installed a separate fuel suction tube in fuel tank & run a new fuel line to espar hea
Intel to seal & it may be letting air in suction line over night when temperatures are below freezing. Greased unit tach hour meter comb for hr meter not working properly for poor connections but eventhing looks ok. Will ord Installed new fuel pump on Espar heater to try to get F32 code repaired.           Mar/11/16         7360         Installed new fuel pump on Espar heater to try to get F32 code repaired.           Mar/11/16         7360         Installed new fuel pump on Espar heater to try to get F32 code repaired.           Nov/08/16         7520         Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC cor out. Reinstalled seat. Readjusted rear window latches so it closes better.           Dec/05/16         7540         Pick up new batteries at Napa & travel to Kitsim dirt pit and install.           Feb/01/17         7566         Grease unit.         Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remo- new made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.           Aug/09/17         7608         Had J8 from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of \$7856.44. I removed ba forks & straightened. Reinstalled on bucket. Tested AC circuit & found losse connection under seat for AC clutch Nov/01/17         F680           Check complaint of lights not working & found wiring to switches unhooked & reconnected.         Ecylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & cylinder. Reinstall when repaired. Ordered new Eng oil filler spout & caf from Cervus Equip & repla	Jan/27/16	7259	from new suction tube. Found the factory fitting at fuel transfer pump where Espar was tied into uses a rubber gaske
Feb/02/16       0       Install new tach hour meter. Old 1 had about 7300hrs on it. Install new hater fan switch.         Feb/05/16       Installed new fuel pump on Espar heater to try to get F52 code repaired.         Mar/11/16       7360       Installed new rim on LH front tire to replaced the old cracked rim.         Nov/08/16       7520       Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC cordination out. Reinstalled seat. Readjusted rear window latches so it closes better.         Dec/05/16       7540       Pick up new batteries at Napa & travel to Kitsim dirt pit and install.         Feb/01/17       7560       Grease unit.       Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remomew made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.         Aug/09/17       7603       Had JB from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of 57856.44. I removed ba forks & straightened. Reinstalled on bucket.Tested AC circuit & found loose connection under seat for AC clutch fors 0         Aug/11/17       7608       Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC 00/0/17         7608       Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.         Perc/18/18       8002       Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.         Perc/18/18       Removed bucket tylinder for back hoe & take to Param	, . ,		fuel to seal & it may be letting air in suction line over night when temperatures are below freezing. Greased unit, Chk
Feb/05/16       Installed new fuel pump on Spar heater to try to get F52 code repaired.         Mar/11/16       7360       Installed new fuel pump on Spar heater to try to get F52 code repaired.         Vov/08/16       7520       Installed new fuel pump on Spar heater to try to get F52 code repaired.         Vov/08/16       7520       Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC corout. Reinstalled seat. Readjusted rear window latches so it closes better.         Dec/05/16       7540       Pick up new batteries at Napa & travel to Kitsim dirt pit and install.         Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator removnew made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.         Mar/11/17       7608       Travel to Crawling Valley pit & reinstalled on bucket. Tested AC circuit & found loose connection under seat for AC clutch         Aug/09/17       7600       Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC         Nov/01/17       7680       Reaver to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC         Vov/01/17       7680       Grease unit. Topped up front tires to SD PSI & rear to 38PSI.         Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & trylinder. Reinstall when repaired. Ordered new fare windows. Adjusted spray nozzles on front windo Replace	Fab /02 /16	-	tach hour meter combo for hr meter not working properly for poor connections but everthing looks ok. Will order ne
Mar/11/16       7360       Installed new rim on LH front tire to replaced the old cracked rim.         Nov/08/16       7520       Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC con out. Reinstalled seat. Readjusted rear window latches so it closes better.         Dec/05/16       7540       Pick up new batteries at Napa & travel to Kitsim dirt pit and install.         Feb/01/17       7550       Grease unit.         Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remonex meade up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.         Aug/09/17       7603       Had 18 from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of \$7856.44. I removed ba forks & straightened. Reinstalled on bucket. Tested AC circuit & found loose connection under seat for AC clutch Aug/11/17         Aug/09/17       7600       Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC 0x/0/117         7680       Check complaint of lights not working & found wiring to switches unhooked & reconnected.         Ovo/01/17       7680       Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.         Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Thang & found Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new bitk bett		0	
Nov/08/16         7520         Check complaint of cab heater not blowing & found fan is working. Removed seat base to get at heater & AC cor out. Reinstalled seat. Readjusted rear window latches so it closes better.           Dec/05/16         7540         Pick up new batteries at Napa & travel to Kitsim dirt pit and install.           Geb/01/17         7556         Grease unit.         Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remo- new made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.           Mar/13/17         7568         Travel to Crawling Valley pit & reinstall new brakes & reseal brake valve. INV# 401870 for a total of \$7856.44. I removed ba forks & straightened. Reinstalle on bucket. Tested AC circuit & found loose connection under seat for AC clutch           Aug/09/17         7603         Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC           Nov/01/17         7608         Grease unit. Topped up front tires to S0 PSI & rear to 38PSI.           Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & relylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced bucket belt, beit t           Jan/17/19         8013         idler pulley. Install new tires on rear of onft & Rh front tire. The LH front was new recently. Replaced missing sna ing & washer on LH side of main pin on front end loader lift arms. Install new bick, bet t		7360	
out. Reinstalled seat. Readjusted rear window latches so it closes better.           Dec/05/16         7540         Pick up new batteries at Napa & travel to Kitsim dirt pit and install.           Feb/01/17         7550         Grease unit.           Mar/13/17         7568         Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remores new made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.           Aug/09/17         7603         Had J8 from Brandt install new brakes & reseal brake valve. INV4 #014870 for a total of \$7856.44. I removed ba forks & straightened. Reinstalled on bucket.Tested AC circuit & found loose connection under seat for AC clutch           Aug/11/17         7608         Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC           Nov/01/17         7680         Check complaint of lights not working & found wiring to switches unhooked & reconnected.           Dec/18/18         8002         Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.           Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt t           Jan/17/19         8013         Inkage to loader bucket tilt. Install new wipers on front & rear windows. Adjusted spray nozzles on front windo Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off o		/300	Check complaint of cab beater not blowing & found for is working. Personal work is a second second
Dec/05/16         7540         Pick up new batteries at Napa & travel to Kitsim dirt pit and install.           reb/01/17         7550         Grease unit.           Vlar/13/17         7568         Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remonew made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.           Aug/09/17         7603         Had J8 from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of \$7856.44. I removed ba forks & straightened. Reinstalled on bucket.Tested AC circuit & found loose connection under seat for AC clutch Aug/11/17           7608         Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC (ov/01/17           7680         Check complaint of lights not working & found wiring to switches unhooked & reconnected.           Dec/18/18         8002         Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.           Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change driveline from trans to rear dift. Replace input shaft seal on rear diff. Replaced bucket tylinder process on front tire. The LH front was new recently. Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt tiller pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing snap ring & ushers on front windows. Adjusted spray nozzles on front windo Replaced hydrualic lines	Nov/08/16	7520	Out. Reinstalled seat. Readiusted rear window latches so it closes better
Feb/01/17       7550       Grease unit.         Vlar/13/17       7568       Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remonew made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.         Aug/09/17       7603       Had JB from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of \$7856.44. I removed ba forks & straightened. Reinstalled on bucket. Tested AC circuit & found loose connection under seat for AC clutch Aug/11/17         7603       Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC vov/01/17         7680       Check complaint of lights not working & found wiring to switches unhooked & reconnected.         Oper/18/18       8002       Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.         Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & review of working sense on trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of gra Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt tiller pulley. Install new tires on rear of unit & Reh front tire. The LH front was new recently. Replaced missing snap ring & washer on LH side of main pin on front ad coolers & unit. Found mount pla rad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstallin back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing & cooling at mouse plotes	Dec/05/16	7540	
Mar/13/17       7568       Travel to Crawling Valley pit & reinstall new hydraulic line to barrel end of bucket cylinder which operator remonew made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.         Aug/09/17       7603       Had J8 from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of \$7856.44. I removed baforks & straightened. Reinstalled on bucket.Tested AC circuit & found loose connection under seat for AC clutch         Aug/11/17       7608       Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC         Nov/01/17       7680       Check complaint of lights not working & found wiring to switches unhooked & reconnected.         Dec/18/18       8002       Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.         Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change drivieline from trans to rear diff. Replaced niput shaft seal on rear diff. Replaced beacon with used 1 from 1 of gra Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new biel, belt till inkage to loader bucket till. Install new wipers on front & rear windows. Adjusted spray nozzles on front windo Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount plair rad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstalliba         lu			
new made up. Topped up hydrualic level. Greased unit. Wash oil off of windshield.         Aug/09/17       7603       Had J8 from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of \$7856.44. I removed ba forks & straightened. Reinstalled on bucket. Tested AC circuit & found loose connection under seat for AC clutch         Aug/11/17       7608       Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC         Nov/01/17       7680       Check complaint of lights not working & found wring to switches unhooked & reconnected.         Dec/18/18       8002       Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.         Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reviewed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reviewed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reviewed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reviewed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reviewed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reviewed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced beacon with used 1 from 1 of gras         Jan/17/19       8013       idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing snatinkage to loader bucket tilt. Install new wipers on front & rear windows. Adjusted spray nozzles on front windo Replaced hydrualic lines to LH loader lift cyl			
Aug/09/177603Had J8 from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of \$7856.44. I removed ba forks & straightened. Reinstalled on bucket.Tested AC circuit & found loose connection under seat for AC clutch Aug/11/177608Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC Oxo/01/177608Check complaint of lights not working & found wiring to switches unhooked & reconnected.Dec/18/188002Grease unit. Topped up front tires to 50 PSI & rear to 38PSI. Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & cylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of gra Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt ti idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing sna linkage to loader bucket till. Install new wipers on front & rear windows. Adjusted spray nozzles on front windo Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacun Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hi moving breaking voke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts c corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig Dec/17/19812Pick up new tranfer pump at Cervus Equip &	Mar/13/17	7568	new made up. Topped up hydrualic level. Greased unit. Wash oil off of windchield
Interpretation         Interpretation           Aug/11/17         7608         Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & AC           Aug/11/17         7608         Check complaint of lights not working & found wiring to switches unhooked & reconnected.           Dec/18/18         8002         Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.           Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & cylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of gra Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt ti idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing snap linkage to loader bucket till. Install new wipers on front & rear windows. Adjusted spray nozzles on front windo Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount pla rad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstallibus back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hig moving breaking voke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts cororrer. Loosen bolts off & try to put silicone on gasket & tighte	Aug 100 /1-	7662	Had J8 from Brandt install new brakes & reseal brake valve. INV# 4014870 for a total of \$7956 44. Lower at the f
Aug/1/177608Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler & ACNov/01/177680Check complaint of lights not working & found wiring to switches unhooked & reconnected.Dec/18/188002Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reclinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of grasJan/17/198013idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt ti idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing snap linkage to loader bucket tilt. Install new wipers on front & rear windows. Adjusted spray nozzles on front windo Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount pla rad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstallir back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacunJuly/16/198070moving breaking voke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. TigDec/16/198174Repair the keeper stud for buck	MUR/03/11	7603	forks & straightened. Reinstalled on bucket. Tested AC circuit & found loose connection under seat for AC clutch. Poet
Nov/01/17         7680         Check complaint of lights not working & found wiring to switches unhooked & reconnected.           Dec/18/18         8002         Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.           Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & review.         Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & review.           Jan/17/19         8013         Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt t           Jan/17/19         8013         idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing sna           Jan/17/19         8013         idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing sna           Jan/17/19         8013         idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing sna           Jan/17/19         8013         idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing sna           Jan/17/19         8013         idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing sna           Jan/17/19         8013         idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced nount pla           Jan/17/19	Aug/11/17	7608	Travel to jobsite west of Brooks. Check complaint of unit over heating & found rad plugged. Split oil cooler 8 40 and
Dec/18/18         8002         Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.           Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & reylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of gra Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt tilder pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing snap linkage to loader bucket tilt. Install new wipers on front & rear windows. Adjusted sprav nozzles on front windo Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount pla rad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstallir back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hig moving breaking yoke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig Dec/17/19           8174         Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transfile neutral when it is hot. Bypassed both switchs to see if unit still has problem. Operators will let me know. Change neutral when it is hot. Bypassed both switches to see if unit still has problem. Operators will let me know. Chang	Nov/01/17	7680	Check complaint of lights not working & found wiring to switches unhooked & reconnected.
Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & cylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of gra Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt ti idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing snap linkage to loader bucket tilt. Install new wipers on front & rear windows. Adjusted spray nozzles on front window Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount platrad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstallit back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hit moving breaking yoke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig Dec/16/198174Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transfile neutral when it is hot. Bypassed both switchs to see if unit skill. Inv# 930007.8252/208318Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is go neutral when it is hot. Bypassed both switchs to see if unit skill has problem. Operators will let me know. Change Nov/26/208355Installe	Dec/18/18	8002	Grease unit. Topped up front tires to 50 PSI & rear to 38PSI.
<ul> <li>cylinder. Reinstall when repaired. Ordered new Eng oil filler spout &amp; cap from Cervus Equip &amp; replaced. Change driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of gra Replaced missing snap ring &amp; washer on LH side of main pin on front end loader lift arms. Install new belt, belt till inkage to loader bucket tilt. Install new wipers on front &amp; rear windows. Adjusted spray nozzles on front windo Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank &amp; repair broken rung &amp; reinstall. Wash out rad &amp; coolers &amp; unit. Found mount pla rad screen on was broken &amp; removed nose cone repaired. Installed a fine screen on rad screen before reinstallir back up alarm was not working &amp; tested circuit &amp; found speaker failed &amp; replaced. Remove floor matts &amp; vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing &amp; coming off diff &amp; falling on hig moving breaking yoke off trans end &amp; bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts of corner. Loosen bolts off &amp; try to put silicone on gasket &amp; tighten back up. Retry &amp; now leak appears ok now. Tig Dec/17/19 8182</li> <li>Pick up new tranfer pump at Cervus Equip &amp; take out to Rainier &amp; install. Inv# 930007.</li> <li>Travel to unit check wiring to Clutch cut outs on loader control &amp; shifter. Both appear ok but unit acts like it is go neutral when it is hot. Bypassed both switchs to see if unit still has problem. Operators will te me know. Change Sept/02/20 8323</li> <li>Check levels &amp; added 10 litres to hydraulic. Inest on Hoader lift cylinder w cab circulating fan purchased from Mapa. Topped up / Installed new hydraulic lines to RH loader lift cylinder &amp; bucket tilt cylinder purchased from Mapa. Topped up / Installed new hydraulic lines to RH loader lift cylinder &amp; bucket tilt cylinder purchased from Napa. Topped up / Installed new hydraulic lines to RH load</li></ul>			Removed bucket cylinder for back hoe & take to Paramount Mech to have rod replaced for chrome damage & resea
<ul> <li>driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of gra Replaced missing snap ring &amp; washer on LH side of main pin on front end loader lift arms. Install new belt, belt tider pulley. Install new tires on rear of unit &amp; Rh front tire. The LH front was new recently. Replaced missing snap linkage to loader bucket tilt. Install new wipers on front &amp; rear windows. Adjusted spray nozzles on front window Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank &amp; repair broken rung &amp; reinstall. Wash out rad &amp; coolers &amp; unit. Found mount pla rad screen on was broken &amp; removed nose cone repaired. Installed a fine screen on rad screen before reinstallin back up alarm was not working &amp; tested circuit &amp; found speaker failed &amp; replaced. Remove floor matts &amp; vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing &amp; coming off diff &amp; falling on hig moving breaking yoke off trans end &amp; bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts corner. Loosen bolts off &amp; try to put silicone on gasket &amp; tighten back up. Retry &amp; now leak appears ok now. Tig Dec/16/19 8174 Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting &amp; found fuel transfile Dec/17/19 8182 Pick up new tranfer pump at Cervus Equip &amp; take out to Rainier &amp; install. Inv# 930007.</li> <li>Aug/25/20 8318 Travel to unit check wiring to Clutch cut outs on loader control &amp; shifter. Both appear ok but unit acts like it is go neutral when it is hot. Bypassed both switchs to see if unit still has problem. Operators will let me know. Change Nov/26/20 8353</li> <li>Check levels &amp; added 10 litres to hydraulics. Installed new cab circulating fan purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder w cab circulating fan purchased from Brooks Bearing. Installed new hydraulic lines to RH loade</li></ul>			cylinder. Reinstall when repaired. Ordered new Eng oil filler spout & cap from Cervus Equip & replaced. Change U-joi
Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt tJan/17/198013Jan/17/19idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing sna linkage to loader bucket tilt. Install new wipers on front & rear windows. Adjusted spray nozzles on front window Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount plai rad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstalli back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hit moving breaking voke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts c corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig Dec/16/19B174Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel trans pick up new tranfer pump at Cervus Equip & take out to Rainier & install. Inv# 930007.Aug/25/208318Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is go neutral when it is hot. Bypassed both switchs to see if unit still has problem. Operators will let me know. Chang Nev/26/20Nov/26/208355Installed new hydraulic lines to RH loader lift cylinder ew cab circulating fan purchased from Brooks Bearing. Installed neutral when it is hot. Bypassed both switches to see if unit still h			driveline from trans to rear diff. Replace input shaft seal on rear diff. Replaced beacon with used 1 from 1 of gravel tr
Jan/17/19       8013       Idler pulley. Install new tires on rear of unit & Rh front tire. The LH front Was new recently. Replaced missing snathinkage to loader bucket tilt. Install new wipers on front & rear windows. Adjusted spray nozzles on front window Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount platrad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstallit back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hit moving breaking yoke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig Dec/16/19         8174       Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transf Dec/17/19         8182       Pick up new tranfer pump at Cervus Equip & take out to Rainier & install. Inv# 930007.         Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is go neutral when it is hot. Bypassed both switches to see if unit sy prohem. Operators will let me know. Chang Sept/02/20         8325       Check levels & added 10 litres to hydraulics. Installed new cab circulating fan Bruchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder w cab circulating fan Bruchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder we cab circulating fa			Replaced missing snap ring & washer on LH side of main pin on front end loader lift arms. Install new belt, belt tensic
<ul> <li>Inikage to loader bucket tilt. Install new wipers on front &amp; rear windows. Adjusted spray nozzles on front windo Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b Remove step off of fuel tank &amp; repair broken rung &amp; reinstall. Wash out rad &amp; coolers &amp; unit. Found mount plai rad screen on was broken &amp; removed nose cone repaired. Installed a fine screen on rad screen before reinstallir back up alarm was not working &amp; tested circuit &amp; found speaker failed &amp; replaced. Remove floor matts &amp; vacum Check output shaft of Trans for HFWD and found it is bent from driveline failing &amp; coming off diff &amp; falling on hi moving breaking voke off trans end &amp; bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts c corner. Loosen bolts off &amp; try to put silicone on gasket &amp; tighten back up. Retry &amp; now leak appears ok now. Tig Dec/16/19 8174 Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting &amp; found fuel transfor Dec/17/19 8182 Pick up new tranfer pump at Cervus Equip &amp; take out to Rainier &amp; install. Inv# 930007. Travel to unit check wiring to Clutch cut outs on loader control &amp; shifter. Both appear ok but unit acts like it is go neutral when it is hot. Bypassed both switches to see if unit still has problem. Operators will let me know. Chang Sept/02/20 8323 Check levels &amp; added 10 litres to hydraulics. Installed new cab circulating fan purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder w cab circulating fan Brockased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder wisch on trans gear shift lever.</li> </ul>	Jan/17/19	8013	idler pulley. Install new tires on rear of unit & Rh front tire. The LH front was new recently. Replaced missing space right
Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader b         Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount platrad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstallin back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum         Duty/16/19       8070       Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hij         Duty/16/19       8070       moving breaking voke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig         Dec/16/19       8174       Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transf         Dec/17/19       8182       Pick up new tranfer pump at Cervus Equip & take out to Rainier & install. Inv# 930007.         Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is go neutral when it is hot. Bypassed both switches to see if unit still has problem. Operators will let me know. Chang         Sept/02/20       8325       Check levels & added 10 litres to hydraulics. Installed new cab circulating fan purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder w cab circulating fan purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder wichon trans gear shift lever. </td <td> , = 0</td> <td></td> <td>inkage to loader bucket tilt. Install new wipers on front &amp; rear windows. Adjusted spray nozzles on front window wa</td>	, = 0		inkage to loader bucket tilt. Install new wipers on front & rear windows. Adjusted spray nozzles on front window wa
Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount platrad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstallined back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum         Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hit moving breaking yoke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig Dec/16/19         B174       Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transf         Dec/17/19       8182         Pick up new tranfer pump at Cervus Equip & take out to Rainier & install. Inv# 930007.         Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is goneutral when it is hot. Bypassed both switches to see if unit still has problem. Operators will let me know. Chang         Sept/02/20       8325         Nov/26/20       8355         Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new restored row switch on trans gear shift lever.			Replaced hydrualic lines to LH loader lift cylinder purchased from Brooks Brearing. Flip cutting edge on loader busket
Nov/26/20       8355         Nov/26/20       8355			Remove step off of fuel tank & repair broken rung & reinstall. Wash out rad & coolers & unit. Found mount plates to
Dack up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacum           Check output shaft of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on hi           July/16/19         8070           Dec/16/19         8174           Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transf           Dec/17/19         8182           Pick up new tranfer pump at Cervus Equip & take out to Rainie & install. Inv# 930007.           Aug/25/20         8318           Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is got neutral when it is hot. Bypassed both switches to see if unit still has problem. Operators will let me know. Chang Sept/02/20           8323         Check levels & added 10 litres to hydraulics. Installed new cab circulating fan purchased from Napa. Topped up / Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to not valve handle. Rehook switch on trans gear shift lever.			rad screen on was broken & removed nose cone repaired. Installed a fine screen on rad screen before reinstalling. For
Nov/26/20       8355       Check butput shart of Hawb for Hawb and found it is bent from driveline failing & coming off diff & falling on highly found it is bent from driveline failing & coming off diff & falling on highly found it is bent from driveline failing & coming off diff & falling on highly found it is bent from driveline failing & coming off diff & falling on highly found it is bent from driveline failing & coming off diff & falling on highly found it is bent from driveline failing & coming off diff & falling on highly found found it is bent from driveline failing & coming off diff & falling on highly found found it is bent from driveline failing & coming off diff & falling on highly found found it is bent from driveline failing & found to leak at mount bolts of corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tight found for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transfor from driveline failing and transfor from driveline failing and transform driveline failing and transfore failing and transfore failing and transfo			back up alarm was not working & tested circuit & found speaker failed & replaced. Remove floor matts & vacumm ou
Nov/26/20         8355         Intoking breaking yoke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount bolts of corner. Loosen bolts off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig           Dec/16/19         8174         Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transf           Dec/17/19         8182         Pick up new tranfer pump at Cervus Equip & take out to Rainie & install. Inv# 930007.           Aug/25/20         8318         Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is gas           Sept/02/20         8323         Check levels & added 10 litres to hydraulics. Installed new cab circulating fan purchased from Napa. Topped up /           Nov/26/20         8355         Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new r.	hub/16/10	0070	check output shart of Trans for HFWD and found it is bent from driveline failing & coming off diff & falling on high wa
Corner, Lossen Boits off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tig           Dec/16/19         8174         Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transf           Dec/17/19         8182         Pick up new tranfer pump at Cervus Equip & take out to Rainier & install. Inv# 930007.           Aug/25/20         8318         Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is go           Sept/02/20         8323         Check levels & added 10 litres to hydraulics. Installed new cab circulating fan purchased from Napa. Topped up /           Nov/26/20         8355         Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new and cut switch on loader control valve handle. Rehook switch on trans gear shift lever.	July/16/19	8070	moving breaking yoke off trans end & bending shaft. Shaft also hit eng oil pan causing it to leak at mount holts on fro
Bit         Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transf           Dec/17/19         8174         Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transf           Dec/17/19         8182         Pick up new tranfer pump at Cervus Equip & take out to Rainier & install. Inv# 930007.           Aug/25/20         8318         Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is goneutral when it is hot. Bypassed both switches to see if unit still has problem. Operators will let me know. Chang           Sept/02/20         8323         Check levels & added 10 litres to hydraulics. Installed new cab circulating fan purchased from Napa. Topped up /           Nov/26/20         8355         Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new cab circulating fan gear shift lever.	Dec/16/10	0174	corner. Loosen boits off & try to put silicone on gasket & tighten back up. Retry & now leak appears ok now. Tighten
Aug/25/20         B318         Travel to unit check wiring to Clutch cut outs on loader control & shifter. Both appear ok but unit acts like it is gone utral when it is hot. Bypassed both switches to see if unit still has problem. Operators will let me know. Change           Sept/02/20         8323         Check levels & added 10 litres to hydraulics. Installed new cab circulating fan purchased from Napa. Topped up /           Nov/26/20         8355         Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new to trave to the cut out switch on loader control valve handle. Rehook switch on trans gear shift lever.			Repair the keeper stud for bucket to arm pin on dig bucket. Check complaint of hard starting & found fuel transfer pu
Nov/26/20         8323         Check levels & added 10 litres to hydraulics. Installed new cab circulating fan purchased from Napa. Topped up /           Nov/26/20         8355         Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new to		7	Pick up new tranter pump at Cervus Equip & take out to Rainier & install. Inv# 930007
Sept/02/20         8323         Check levels & added 10 litres to hydraulics. Installed new cab circulating fan purchased from Napa. Topped up A           Nov/26/20         8355         Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to rotto valve handle. Rehook switch on trans gear shift lever.	Aug/25/20	8318	neutral when it is hot. Bypassed both switcher to con if unit still has each an a sub-
Nov/26/20 8355 Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder purchased from Brooks Bearing. Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder bearing.	Sept/02/20	8323	Check levels & added 10 litres to hydraulics. Installed new cab circulating for purchased for any cability of the purchased for any cability o
clutch cut out switch on loader control valve handle. Rehook switch on trans gear shift lever.			Installed new hydraulic lines to RH loader lift cylinder & bucket tilt cylinder symptoms i for Napa. Topped up AC ch
	Nov/26/20	8355	clutch cut out switch on loader control valve handle. Rebook switch on trace does able to
May/03/21 8383 Rebolt cut edge on loader bucket.			

Nov/01/21 Installed new window on LH side front half.

٠