

Japa Equipment Rentals Inc.

10397 - 267 Street
Acheson, Alberta T7X 6A2
Canada

INVOICE

Invoice No.: 19942
Date: Jan 05, 2026
Page: 1
Vendor No:
Work Order No: 012262

Sold to:

Force Civil Solutions Ltd. (Service)
Accounts Payable
11122 - 255 Street
Acheson, Alberta T7X 6C9
Canada

Ship to:

Force Civil Solutions Ltd. (Service)
Accounts Payable
11122 - 255 Street
Acheson, Alberta T7X 6C9
Canada

Business No.: 872244207

Quantity	Unit	Description	Tax	Unit Price	Amount
		PO T017JD	G		
		To Charge Your Account			
		UNIT T-017			
		FOR WORK PERFORMED ON: 12/15/25			
		FOR WORK PERFORMED AT: Japa Shop			
		ON MAKE/MODEL: Western Star Tandem			
		S/N: 5KKHAXCY7GPHM1923			
		DESCRIPTION OF WORK Blower motor not functioning			
4.5	H	LABOUR For JAPA Shop Mechanic	G	145.00	652.50
1.0		PARTS Parts	G	2,804.48	2,804.48
1.0		Fluids	G	35.69	35.69
1.0		Shop Supplies	G	174.63	174.63
		Full Repair / Service Details Attached			
		Subtotal:			3,667.30
		G - GST 5% GST			183.36
Terms: Net 30. Due Feb 04, 2026.				Total Amount	3,850.66
Comment: REMIT TO: 10397 - 267 St. Acheson, AB T7X 6A2. 1.5% interest/month charged on overdue accounts.				Amount Paid	0.00
Sold By:				Amount Owing	3,850.66

NORTHERN ALBERTA

10397 - 267 Street
 Acheson, AB T7X 6A2
 780-962-5272
 admin@japaequipment.com

Toll Free: 888-489-1626 / 780-489-1626

JAPA EQUIPMENT RENTALS INC.

www.japamachinery.com

SOUTHERN ALBERTA

5735 - 53 Street SE
 Calgary, AB T2C 4V1
 403-300-5272
 calgaryadmin@japaequipment.com

Fax: 780-960-0541

Customer Work Order

Work Order: 012262

Customer Details				Machine Details			
Company Name:		Force Civil Solutions Ltd. (Service)		Machine Make:		Western Star	
Site Contact Name:				Machine Model:		Tandem	
Customer PO:		T017JD *Required		Machine S/N:		5KKHAXCY7GPHM1923	
Hour Reading:		428,051.0		Machine Unit #:		T-017	
Work Requested							
Blower motor not functioning							
Location:		Shop				002	
Record Of Work							
Mechanic	Date	Repair Description					
Devon Rhude	12/11/25	Tested Voltage to fan motor 12v. Forces mechanic also checked it and said it was dead. Ordered new motor and installed/tested. Did not work. Found control box for fan behind the glove back was damaged, it had gotten hot and burned the board. was putting out 12v but must not have had the amps to run fan motor Ordered new box to replaced damaged one.					
Devon Rhude	12/12/25	Unit has a pretty bad oil leak, removed and checked the crank case breather filter and think it might need to be changed, will run it by FORCE. Checked the final breather, found some loose clamps on an oil line running from it and tightened them all up. Cleaned the entire truck, front to back and underneath and the engine bay. Will be able to check for leaks properly now, will let them use the unit and monitor for further oil leaks. Topped up low engine oil.					
Devon Rhude	12/15/25	Installed new fan control ECM, tested and everything worked fine. Put the interior/dash back together and parked the unit outside.					
Hour Totals							
Shop	4.5	Shop Overtime	Field	Field Overtime	Field Two Mechanics	Field Two Mechanics Overtime	Wash Bay
						Labour Total	\$652.50
Parts							
Quantity	Part Number	Description				Unit Price	Price
1	A22-67724-000	ELECTRONIC CONTROL UNIT				\$2,566.91	\$2,566.91
1	ABP N83 301771	12V MOTOR KIT				\$237.57	\$237.57
						Parts Total	\$2,804.48
Fluids							
Quantity	Unit	Fluids Used				Unit Price	Price
4.5	Litre	5W40 ENGINE OIL				\$7.93	\$35.69
						Fluids Total	\$35.69

*Total does not include Shop Supplies or GST