

Truck Doctor Inc.
 3952 52 St SE
 Calgary AB T2B 3H1
 5879716444
 rob@truckdoctor.ca

Invoice



BILL TO

Rock
 Force Civil Solution Ltd.
 20910 100 Ave NW
 Edmonton AB T5T5X8

INVOICE #	DATE	TOTAL DUE	DUE DATE		ENCLOSED
TD5269	25/04/2025	\$5,630.74	25/05/2025		

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
		Reference to Shop Management invoice # 5269 Vehicle Info:2016, License: CNP4211, Mileage: 0, Unit: T017, VIN: 5KKHAXCY7GPHM1923			
	SALES-Parts & Materials Sales	330-3106 - Gasket 8 Hole 5/8	1	5.41	5.41
	SALES-Parts & Materials Sales	75W90 - Gear Oil 75W90	12	14.69	176.28
	SALES-Parts & Materials Sales	CB-1550 - Center Bolt	1	3.40	3.40
	SALES-Parts & Materials Sales	71928-001 - Side Signal	1	229.08	229.08
	SALES-Parts & Materials Sales	Windshield - Windshield	2	245.00	490.00
	SALES-Parts & Materials Sales	K061831 - Dash Valve	1	397.35	397.35
	SALES-Parts & Materials Sales	330-3009 - Gasket-Hubcap	1	4.83	4.83
	SALES-Parts & Materials Sales	nsf01 - FOG LIGHTS SAE/DOT APPROVED	1	221.84	221.84
	SALES-Parts & Materials Sales	93600 - BRAKE DRUM 16.5 X 7	4	133.40	533.60
	SALES-Parts & Materials Sales	KITFR4707-501FFA - Shoe Kit New Q+ Shoes/HDW	4	79.68	318.72
	SALES-Parts & Materials Sales	F3030P - Premium 3030 Piggyback Kit	1	66.63	66.63
	SALES-Parts & Materials Sales	F3030LSP - S PREM LONG STROKE 3030 PKIT	1	75.33	75.33
	SALES-Parts & Materials Sales	1050 - 2 1/2 13 DIODE RED LED LAMP	1	13.42	13.42

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	SALES-Parts & Materials Sales	F24SC - T24 Service Chamber Steer Axle	1	53.58	53.58
	SALES-Parts & Materials Sales	392-9131 - Seal Kit-ABS 2106	1	100.53	100.53
	SALES-Parts & Materials Sales	361-468K - U-bolt kit	1	80.61	80.61
	SERVICES-Labour Income	CVIP Repairs	15	120.00	1,800.00
		- Replaced both front mudflaps. Supplied by customer			
		- Replaced tarp. Supplied by customer			
		- Replaced all 4 rear brake drums			
		- Replaced all 4 rear brake shoes			
		- Applied silver tape to gate			
		- Adjusted and tightened left hood guide			
		- Replaced fog lights			
		- Replaced left rear upper box marker			
		- Replaced right front fender marker light			
		- Replaced #2 and #3 left brake pots			
		- Replaced left steer brake pot			
		- Adjusted left steer wheel bearings			
		- Replaced dash valve			
	SERVICES-Labour Income	Inspect Vehicle	2.50	120.00	300.00
	SERVICES-Labour Income	Remove WheelsInspect Brakes	2	150.00	300.00
	SALES-Shop Supplies	Shop Supplies	1	192.00	192.00
	GST/HST Payable - MIT	SALES TAX - GST	1	268.13	268.13

BALANCE DUE

\$5,630.74