

Truck Doctor Inc.

3952 52 St SE

Calgary AB T2B 3H1

5879716444

rob@truckdoctor.ca

GST Registration No.: 813974169RT0001

Invoice**BILL TO**

11122 - 255 Street
Acheson, AB
T7X 6C9

INVOICE #	DATE	TOTAL DUE	DUE DATE		ENCLOSED
TD5596	08/09/2025	\$7,138.06	08/10/2025		

DATE	ACTIVITY	DESCRIPTION	TAX	QTY	RATE	AMOUNT
		Reference to Shop Management invoice # 5596				
		Vehicle Info:2016, License: CNP4211, Mileage: 178718, Unit: T017, VIN: 5KKHAXCY7GPHM1923				
	SALES-Parts & Materials Sales	MER-EAS9781 - Air Spring	G	2	185.21	370.42
	SALES-Parts & Materials Sales	1 - Mounting Hardware Kit	G	1	116.00	116.00
	SALES-Parts & Materials Sales	CS-46-1307 - Taper Spring	G	2	378.00	756.00
	SALES-Parts & Materials Sales	CS-46-1309 - Taper Spring	G	2	378.00	756.00
	SALES-Parts & Materials Sales	361-468K - U-Bolt Kit	G	4	80.61	322.44
	SALES-Parts & Materials Sales	FRT - FREIGHT	G	1	116.00	116.00
	SALES-Parts & Materials Sales	500.016 - Wear PL MFL176 334-1994	G	4	9.61	38.44
	SALES-Parts & Materials Sales	M1833 - Hanger Freightliner	G	4	407.32	1,629.28
	SALES-Parts & Materials Sales	2 - Driveline Repair	G	1	1,018.11	1,018.11
	SALES-Parts & Materials Sales	ATC - Toe Set / Check Alignment	G	1	264.71	264.71
	SALES-Parts & Materials Sales	ATA1 - Adjust Front / Rear Drive Axles	G	1	117.65	117.65
	SALES-Parts & Materials Sales	36021 - Alignment Shim	G	4	29.62	118.48

DATE	ACTIVITY	DESCRIPTION	TAX	QTY	RATE	AMOUNT
	SALES-Parts & Materials Sales	422.34 - SAE FLT WASHER F436 YZ 3/4	G	16	0.80	12.80
	SALES-Parts & Materials Sales	500.015 - Wear PL 16-16456-000	G	4	9.61	38.44
	SERVICES-Labour Income	- Check front end for shake	G	1.50	125.00	187.50
		- Take for test drive truck does have a minor vibration but was informed by driver it does get worse when loaded				
		- Jack up front end check tie rods and drag link and kingpins everything is tight				
		- inspect drive line everything is tight				
		- Found loose bolts on right side front drive axle spring bushings tried to tighten bolts would not tight cut off and installed new hardware				
		- found left rear airbag bolt was loose tightened up				
		- left rear spring could possible have broken center pin as bag has a lean to it wouldn't be able to tell until disassembled				
		- Recommend all 4 spring bushings to be replaced				
		- not guaranteed to fix vibration but its a good start				
	SERVICES-Labour Income	Check Rear For Vibration	G	20	125.00	2,500.00
		- Jaked up truck and ran with brakes released				
		- Found 6 tires were out of round				
		- Pulled wheels and removed all 4 rear springs				
		- Found all 4 spring hangar spring mounting holes were worn out				
		- Found both left spring center bolts were broken				
		- Found 1 right spring center bolt broken				
		- Found both #2 axle air bags were worn to the belt				
		- Checked driveline				
		- Found rear shaft slip joint was worn out				
	SALES-Shop Supplies	Shop Supplies	G	1	215.00	215.00

SUBTOTAL	8,577.27
GST @ 5%	428.86
TOTAL	9,006.13
PAYMENT	1,868.07
BALANCE DUE	\$7,138.06

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	428.86	8,577.27