

PATTISON AGRICULTURE LIMITED
Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 306566209

Deliver To:

LYLE OLSON
BOX 237
TISDALE SK S0E 1T0

Bus Phone: (306)921-7552
Prv Phone:

LYLE OLSON
BOX 237
TISDALE SK S0E 1T0

Bus Phone: (306)921-7552
Prv Phone:

Invoice Number:	3583839
Invoice Date	05/19/2026
Location:	09
Work Order Number:	535203
Payment Type:	Credit Card
Authorization Number:	DB163491/161531
Page:	1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
John Deere Misc	8234	0000009	W000009	

Service Reminders:

JGEN01- Retail

COMPLAINT:

01 REPLACE U JOINTS

CORRECTION:

ATTEMPTED TO REMOVE SNAP RINGS FROM U JOINTS TO DISASSEMBLE.
GOT OUT 2 SNAP RINGS.
ALL OTHER SNAP RINGS BROKE.
HAD TO USE TORCH TO CUT ALL U JOINTS OUT.
ONCE ALL U JOINTS CUT OUT.
REMOVED CAPS STILL IN HOUSINGS.
THEN USED HAMMER AND CHISEL TO REMOVE REMAINING BITS OF SNAP RINGS FROM GROOVES.
CLEANED OUT ALL U JOINT CUP PORTS.
DRAINED OIL.
REMOVED PLANETARY HUB FROM KNUCKLE.
ATTEMPTED TO REMOVE STUB SHAFT SNAP RING.
SNAP RING BROKE WHILE REMOVING.
USED SCREW DRIVERS AND PICKS TO SHIMMY REMAINDER OF SNAP RING OFF OF STUB SHAFT.
REMOVED SEALS FROM REAR OF STEERING KNUCKLE.
REMOVED INNER HUB FROM STEERING KNUCKLE.
REMOVED WHEEL SEAL FROM INNER HUB.
REMOVED BELLOW SEAL FROM AXLE SHAFT.

INSTALLED NEW WHEEL SEAL IN INNER HUB AND OILED LIPS OF SEAL.
INSTALLED RING GEAR AND HOLD DOWN CAP NUT.
TORQUED TO SPEC AND FOLLOWED TORQUE PROCEDURE.
INSTALLED ALL NEW U JOINTS IN STUB SHAFT AND AXLE SHAFT.
INSTALLED NEW STUB SHAFT SEAL AND BELLOW SEAL.
INSTALLED STUB SHAFT AND INSTALLED NEW SNAP RING.
INSTALLED HUB ENSURING TO LINE UP THRUST WASHER.
TORQUED HUB WITH 2 BOLTS.
FILLED WITH OIL.

REPEATED FOR BOTH FRONT STEERING KNUCKLES.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
40M7166	M50 External Snap Ring	2.00	11.03	\$22.06	Y
RE154869	SEAL	2.00	110.73	\$221.46	Y
RE193099	SEAL	2.00	45.91	\$91.82	Y
TA46467	SEAL	3.00	57.93	\$173.79	Y
TY6296	80W90 946ml GL5	4.00	15.85	\$63.40	Y

LOEFFELHOLZ TRACTOR AND COMBINE SALVAGE**CUDWORTH SK SOK IBO
BOX 367****Sales Receipt**

Date	Sale No.
2025-09-08	46604

Invoice To

Olson, Lyle
Box 237
Tisdale Sk.

Cheque No.	Payment Method	ship via
------------	----------------	----------

Visa

Item	Qty	Description	Rate	Amount	Tax
Used Parts	1	R101177 carrier	600.00	600.00	G

No return after 30 days
No cash refund, credit note only.
No return on special order parts.
30 day warranty on all parts unless otherwise stated.
Warranty on parts only, not labour!
if parts are tampered with there will be no return or refund.
Original invoice must accompany returns.
20% restocking charge on all returned goods.
Cores must be returned within 30 days or no refund.

Subtotal	\$600.00
GST/HST	\$30.00
Total	\$630.00

Phone #

Fax #

E-mail

306-256-7107

306-256-3941

ltp@sasktel.net

GST/HST No.

103372371