## Fleet Heavy Duty Box 324 Castor, Ab TOC 0X0

Invoice To		
4132		

## Invoice

Date	Invoice #
14-May-2020	11-12

Ph. 403-741-5736 E-mail mjvan68@gmail.com

P.O. No.	Terms	Project
Super B #2		

Description	Qty	Rate	Amount
Lead - Rear Axle L&R - new s-cams, bushings, slack adjusters, wheel bearings, wheel seals and shoes.  Front and center axle - wheels and brakes pulled, free up sticking and dry s-cam bushings make sure everything taking grease and everything functioning properly. Install all new brake pots, reset all slack adjusters with new reaction pins. New shoes on center axle left side. R&R 2 service relay valves and any worn air lines R&R 2 ball valves for air shut off between lead and pup. R&R 3 air bags. R&R worn wheel studs Check fifth wheel.  Pup - Rear axle L&R, New s-cams, bushings, shoes, wheel bearings, wheel seals, brake pots. Front axle - wheels and brakes pulled, free up dry /sticking s-cams, ensure bushings are taking grease, install new pots, reset slack adjusters with new reaction pins, install new brake shoes. R&R service relay valve and any worn air lines, R&R			
rear right air bag.		-200	
new pots, reset slack adjusters with new reaction pins, install new brake shoes. R&R service relay valve and any worn air lines, R&R			
		Total	
la de la companya de		Payments/Credit	S
· ·		Balance Due	

## Fleet Heavy Duty Box 324 Castor, Ab TOC 0X0

Invoice To		
ing fields		

## **Invoice**

Date	Invoice #
14-May-2020	Esa

Ph. 403-741-5736 E-mall mjvan68@gmail.com

P.O. No.	Terms	Project
Super B #2		,

Description	Qty	Rate	Amount
uclid 5526 s-cams		1 10	78.2
ıclid 5527 s-cams m bushing kit		1115	
m busning kit 0010212 Slack adjuster		3 339	
aldex 427-10558 reaction pin kit			
8 rubber air line		6.4	
2 relay valve		9	
Snpt- 3/8 rubber airline fitting			
2 ball valve		- 32	
op supplies, 5% of labour to max \$85		2010	
ST On Sales		10000	
		1	
	1		
	1		
T/		Total	
		Payments/Credits	
		Balance Due	