



# DEERLAND EQUIPMENT

8926 - 120 Street  
Fort Saskatchewan, AB T8L 0Z7  
Phone: (780) 998-3249 Fax: (780) 998-7075  
www.deerland.ca



JOHN DEERE

Ship To: IN STORE PICKUP

Invoice To: DEERE WARRANTY CLAIMS  
8599 112street  
FORT SASKATCHEWAN AB T8L 3V3

Branch FT SASKATCHEWAN *REPRINT*		
Date 06/08/22	Time 20:04:05 (B)	Page 01
Account No WAR01	Phone No	Inv No W38238
Ship Via		Purchase Order
Tax ID No		
		Salesperson 108

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
F031806	TRACTOR	8024	RW9520T901154	05/01/05	2000
	9520T				3000

SEGMENT# 1 C F37 N/A 05/30/22 05/30/22

fan belt\*\*\*sub jun 2\*\*

COMPLAINT:

fan belt failed prematurely

CAUSE:

fan belt r131083 faulty was only used for 2 hours

3- broke

CORRECTION:

went to the unit

raised hood, checked to ensure that everything was aligned  
and it was.

unbolted fan and viscous clutch

installed another new belt and reinstalled fan and clutch

ran unit

all ok

ADDITIONAL DESCRIPTION:

fan belt failed prematurely

R131083	BELT	RETAIL	169.78	
		1	109.20	109.20
		PARTS		109.20
		LABOR		487.83
10500001 46001201		SEGMENT TOTAL==>		597.03

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

	INTERNAL	CUSTOMER
--	----------	----------

PARTS	109.20	
-------	--------	--

LABOR	487.83	
-------	--------	--

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purpose of testing, inspection or delivery at my risk. I agree to pay cash on delivery or machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By



# DEERLAND EQUIPMENT

8926 - 120 Street  
Fort Saskatchewan, AB T8L 0Z7  
Phone: (780) 998-3249 Fax: (780) 998-7075  
www.deerland.ca



JOHN DEERE

Ship To: IN STORE PICKUP

Invoice To: DEERE WARRANTY CLAIMS  
8599 112street  
FORT SASKATCHEWAN AB T8L 3V3

Branch FT SASKATCHEWAN		
Date 06/08/22	Time 20:04:05 (B)	Page 02
Account No WAR01	Phone No	Inv No W38238
Ship Via		Purchase Order
Tax ID No		
		Salesperson 108

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
F031806	TRACTOR	8024	RW9520T901154	05/01/05	2000
	9520T				3000
INTERNAL TOTAL					597.03



I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purpose of testing, inspection or delivery at my risk. I agree to pay cash on delivery or machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By



# DEERLAND EQUIPMENT

8926 - 120 Street  
Fort Saskatchewan, AB T8L 0Z7  
Phone: (780) 998-3249 Fax: (780) 998-7075  
www.deerland.ca



JOHN DEERE

Ship To: IN STORE PICKUP

Invoice To: JEFF PASEMKO  
BOX 126  
57208 RR 221  
REDWATER AB T0A 2W0

Branch		
FT SASKATCHEWAN *REPRINT*		
Date	Time	Page
09/22/25	21:31:28 (B)	01
Account No	Phone No	Inv No
PASEM003	7808194864	W49707
Ship Via	Purchase Order	
Tax ID No		
		Salesperson
		182

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
F031806	TRACTOR	9239	RW9520T901154	05/01/05	2000
	9520T			01/01/75	3000

SEGMENT# 1 C F55 N/A 09/18/25 09/18/25

Engine will turn but not fire

### REPAIR:

- Went out to unit
- Talked with randy about issue on tractor
- Secondary fuel filter had been changed
- Felt hand primer and it was soft
- Pumped hand primer multiple times till it was more solid
- Tried started tractor but it would not go
- Pumped primer again and opened fuel filter cap
- Had a burst of air come out followed by fuel
- Closed lid tight
- Pumped hand primer again till it was solid
- Tried starting tractor and it sounded like it wanted to go
- Primed it again
- Cranked over tractor and it fired up
- Let unit run for a bit and varied the throttle on it
- Ran it t higher rpm to make sure fuel was through the whole system
- Shut unit down and let sit for 15-20 mins
- Cranked tractor over and it fired up right away
- Shut unit down
- Decided to pull the transfer pump on the back of the head and look at the coupler
- Coupler is still intact but is pretty worn, Recommend replacing
- There is also a check valve on the fuel filter outlet that could be causing the fuel to leak back to tank,

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purpose of testing, inspection or delivery at my risk. I agree to pay cash on delivery or machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By



# DEERLAND EQUIPMENT

8926 - 120 Street  
Fort Saskatchewan, AB T8L 0Z7  
Phone: (780) 998-3249 Fax: (780) 998-7075  
www.deerland.ca



JOHN DEERE

Ship To: IN STORE PICKUP

Invoice To: JEFF PASEMKO  
BOX 126  
57208 RR 221  
REDWATER AB T0A 2W0

Branch FT SASKATCHEWAN		
Date 09/22/25	Time 21:31:28 (B)	Page 02
Account No PASEM003	Phone No 7808194864	Inv No W49707
Ship Via		Purchase Order
Tax ID No		
		Salesperson 182

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
F031806	TRACTOR	9239	RW9520T901154	05/01/05	2000
	9520T			01/01/75	3000

Recommend replacing the check valve

- Talked to customer and he said he would replace the coupler and the check valve
- Started tractor back up and it ran good
- Cleaned up tools and headed back to the shop

### ADDITIONAL DESCRIPTION:

Jeff-780-819-4864  
57208 RR 221, 2 miles South of Redwater  
Unit started odd the other day, no will only turn but no fire. Customer hand pumped and changed fuel filter.

10400000

LABOR	765.90
SEGMENT TOTAL==>	765.90

### \*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

LABOR	765.90
SERV VEH #2	226.59
SUB TOTAL==>	992.49
#836926121 GST 5%	49.63
CHARGE SALE	1042.12

IC

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purpose of testing, inspection or delivery at my risk. I agree to pay cash on delivery or machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By