0434 119 12st N Nobleford, AB

Section I

Customer: Whitelake Colony

Address:

Vehicle VIN: # 3

YMG244755

Date work Begins April 4/23

Odometer 732/560

Section II

Complaint: Field ready inspection.

Labour Instructions: Completed full inspection + run machine Repair list below. Ran all machine functions.

All functions worked at time of inspection.

Complaint and Labor Instructions	Labour Hours	Date:

Section III

Parts and Supplies

S	Vendor Invoice # or Commodity Code	Qty.	Part Description	Price
			SHOP SUPPLIES	

- Change hydraulic + Air filters. Change oil (engine) + filter. Change unloading gear box oil. Clean out cab air filter box. Replace chopper blades. Remove half link from bottom unloading auger chain. Remove link from upper unloading chain. Rear shaker rollers need to be adjusted closer to frame. Rear straw hood bolts loose. RAS blade tip rubbers worn. Pto + Hyd oil levels low. Tighten clean grain chain. Dents on 30ft auger. 2 broken auger fingers + guides. Ladder into cab bent.

Total Parts & Supplies Cost

Total Labour Hours

Section IV

Complaint:

Vendor's Name:

Invoice #: FPO#:

Outside Repairs	Price
Parts	
Labour	
Tax	
Total	

Work Order Totals	
Total Shop Labour Cost (Sect. II)	
Total Parts & Supplies Cost (Sect.III)	
Total Outside Repairs Cost (Sect. IV)	
Grand Total	

Work Completed by: Signature

April 4/23 #

Date Work Completed

Picked up by: Signature

Work Order #: