

 <p>Canada's Tournament Capital</p>	<p>City of Kamloops Inspection: 21598 FLEET_Decommission Inspection Parent Work Order <u> 4090178 </u></p>
----------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------

Inspection Summary

Object Inspected	FLEETEQUIPMENT 0
Location	84075
Status	Overall Pass
Inspected By	SINCLAIR, TAYLOR
Date	6/16/2023 10:00:00 AM
Summary	2013 Peterbilt 320 cab over style front load tandem axle refuse truck. Unit has surface rust.
Repairs Made	
Recommendations	

Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	White	
Colour - Interior	grey/black	
Wheel Drive	2x4	
Body Style	2 Door	
Engine Size	Cummins 15L9 345HP	
Damage Declaration over \$2,000	No	
Estimated Damage Amount		
Body Condition	Fair	
Body Damage	Yes	
Mechanical	Unknown	
Transmission Operable	No	
Interior	Fair	
Interior Dirty	Yes	
Tires	Fair	
Windshield	Good	
Jack Assembly	No	
Spare Tire	No	

Check all Vehicle Options that apply		
Hours or Odometer (Blank if N/A)	13012	

Add Signature and Date Fields Here?

Work Order Details

Assigned To: Supervisor: Work Status: WORK IN PROGRESS Scheduled Start: 4/4/2023 1:47:52 PM Scheduled Finish: 4/4/2023 1:47:52 PM	Location: 84075 [Instructions: [WOInstructions]Accomplishment Units to be recorded as Requested By: Project Name: Account: 7401Receiving Account (IPTs): Asset Details: