

# City of Kamloops Inspection: 24006 FLEET\_Decommission Inspection

**Parent Work Order** 

109200

# **Inspection Summary**

,	
Object Inspected	FLEETEQUIPMENT 4271
Location	82172
Status	Overall Pass
Inspected By	SINCLAIR, TAYLOR
Date	6/16/2023 10:00:00 AM
Summary	Single axle chassis with Nahanni dump box and underbelly plow with Drive products hydraulics and controls.
Repairs Made	
Recommendations	

# Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	white	
Colour - Interior	grey/black	
Wheel Drive	2x4	
Body Style	2 Door	
Engine Size	International	
	Maxxforce	
	DT 255HP	
Damage	No	
Declaration over		
\$2,000		
Estimated		
Damage Amount		
Body Condition	Fair	
Body Damage	No	
Mechanical	Unknown	
Transmission	No	
Operable		
Interior	Fair	
Interior Dirty	Yes	
Tires	Fair	
Windshield	Good	
Jack Assembly	No	
Spare Tire	No	

Check all Vehicle		
Options that		
apply		
Hours or	10188	
Odometer (Blank		
if N/A)		

# Add Signature and Date Fields Here?

\_\_\_\_\_

## Work Order Details

Assigned To: Supervisor:

Work Status: WORK IN

**PROGRESS** 

Scheduled Start: 5/10/2023 9:02:24 AM Scheduled Finish: 5/10/2023 9:02:24 AM Location: 82172

[Instructions: [WOInstructions]Accomplishment Units to be recorded as Requested By: Project Name: Account: 7401Receiving Account (IPTs): Asset Details:

FLEETEQUIPMENT				
Name	Value			
OBJECTID	203			
ASSETID	4271			
UNITNO	82172			
MAKE	INTERNATIONAL			
MODEL				
MODELYEAR	2009			
VIN	1HTZZAARX9J11838			
DESCRIPTION	SINGLE AXLE DUMP TRUCK			
EQUIPMENTTYPE	HEAVY DUTY TRUCK			
FUELTYPE	DIESEL			
METERTYPE	HOURS			
FLEETSTATUS	OUT OF SERVICE (SALE PENDING)			
NSCCLASSIFICATION	NSC CVIP			
LINKEDUNITNO	85107			
AXELCOUNT				
LICENSEPLATE	LD8640			
GVW				
LICENSEDGVW	24000			
ACQUIREDATE	1/12/2009 12:00:00 AN			
ACQUIRECOST	153556			
DEPARTMENT	CIVIC OPERATIONS			
DIVISION	STREETS & ENVIRONMENT			
SUBDIVISION	STREETS			
LOCATION	82172			
ADDRESS				
WARRANTYDATE				
WARRANTYODOMETERHRS				
WARRANTYNOTES				
CONDITION	6			
CONDITIONDATE				

CONDITIONCOMMENT	REPLACEMENT ON ORDER - BL
SECURELINK	
DOCUMENTATIONLINK	
ODOMETER	
HOURSMETER	
AGE	13
USEFULLIFE	10
REMAININGLIFE	-5
DISPOSALDATE	
DISPOSALVALUE	
DEPRECIATIONLIFE	10
REPLACEMENTYEAR	2022
CURRENTREPLACEMENTCOST	275000