

City of Kamloops Inspection: 35499 FLEET_Decommission Inspection

Parent Work Order

Inspection Summary

mspection summary	
Object Inspected	FLEETEQUIPMENT 83145
Location	83145
Status	
Inspected By	
Date	
Summary	
Repairs Made	
Recommendations	

Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	Orange	
Colour - Interior	Grey	
Wheel Drive	4x4	
Body Style	2 Door	
Engine Size		
Damage	No	
Declaration over		
\$2,000		
Estimated		
Damage Amount		
Body Condition	Fair	
Body Damage	No	
Mechanical	Fair	
Transmission	Yes	
Operable		
Interior	Fair	
Interior Dirty	Yes	
Tires	Fair	
Windshield	Good	
Jack Assembly		
Spare Tire		
Check all Vehicle		
Options that		
apply		

Hours or	2556	
Odometer (Blank		
if N/A)		

Add Signature and Date Fields Here?

Work Order Details

Assigned To: Supervisor:

Work Status: WORK IN

PROGRESS

Scheduled Start: 4/22/2024 11:03:12 AM Scheduled Finish: 4/22/2024 11:03:12 AM **Location:** 83145

[Instructions: [WOInstructions]Accomplishment Units to be recorded as Requested By: Project Name: Account: 7401Receiving Account (IPTs): Asset Details:

OBJECTID	278
ASSETID	83145
UNITNO	83145
MAKE	HOLDER
MODEL	11022211
MODELYEAR	2013
VIN	53400302
DESCRIPTION	MUNICIPAL TRACTOR
EQUIPMENTTYPE	PARKS/FACILITIES EQUIPMENT
FUELTYPE	DIESEL
METERTYPE	HOURS
FLEETSTATUS	OUT OF SERVICE (SALE PENDING)
NSCCLASSIFICATION	NON NSC
LINKEDUNITNO	
AXELCOUNT	
LICENSEPLATE	X79775
GVW	
LICENSEDGVW	2450
ACQUIREDATE	1/1/2014 12:00:00 AM
ACQUIRECOST	148065
DEPARTMENT	CIVIC OPERATIONS
DIVISION	PARKS & CIVIC FACILITIES
SUBDIVISION	UNKNOWN
LOCATION	83145
ADDRESS	
WARRANTYDATE	
WARRANTYODOMETERHRS	0
WARRANTYNOTES	
CONDITION	6
CONDITIONDATE	
CONDITIONCOMMENT SECURELINK	2022 FMW

Print Preview - Cityworks

DOCUMENTATIONLINK	
ODOMETER	
HOURSMETER	
AGE	8
USEFULLIFE	10
REMAININGLIFE	2
DISPOSALDATE	
DISPOSALVALUE	
DEPRECIATIONLIFE	10
REPLACEMENTYEAR	2024
CURRENTREPLACEMENTCOST	200000