

City of Kamloops Inspection: 35503 FLEET_Decommission Inspection

Parent Work Order

Inspection Summary

mspection summary	
Object Inspected	FLEETEQUIPMENT 85123
Location	85123
Status	
Inspected By	
Date	
Summary	
Repairs Made	
Recommendations	

Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	Orange	
Colour - Interior	N/A	
Wheel Drive		
Body Style		
Engine Size		
Damage		
Declaration over		
\$2,000		
Estimated		
Damage Amount		
Body Condition	Good	
Body Damage	No	
Mechanical	Good	
Transmission		
Operable		
Interior		
Interior Dirty		
Tires		
Windshield		
Jack Assembly		
Spare Tire		
Check all Vehicle		
Options that		
apply		

Hours or		
Odometer (Blank		
if N/A)		

Add Signature and Date Fields Here?

Work Order Details

Assigned To: Supervisor:

Work Status: WORK IN

PROGRESS

Scheduled Start: 4/22/2024 11:04:01 AM Scheduled Finish: 4/22/2024 11:04:01 AM Location: 85123

[Instructions: [WOInstructions]Accomplishment Units to be recorded as Requested By: Project Name: Account: 7401Receiving Account (IPTs): Asset Details:

FLEETEQUIPMENT		
OBJECTID	351	
ASSETID	85123	
UNITNO	85123	
MAKE	HOLDER	
MODEL		
MODELYEAR	2018	
VIN	45516	
DESCRIPTION	SANDER	
EQUIPMENTTYPE	ATTACHMENT STREETS/UTILITIES	
FUELTYPE	N/A	
METERTYPE	N/A	
FLEETSTATUS	OUT OF SERVICE (SALE PENDING)	
NSCCLASSIFICATION	NON NSC	
LINKEDUNITNO		
AXELCOUNT		
LICENSEPLATE		
GVW		
LICENSEDGVW		
ACQUIREDATE	11/13/2018 12:00:00 AM	
ACQUIRECOST	36647	
DEPARTMENT	CIVIC OPERATIONS	
DIVISION	STREETS & ENVIRONMENT	
SUBDIVISION	STREETS	
LOCATION	85123	
ADDRESS		
WARRANTYDATE		
WARRANTYODOMETERHRS		
WARRANTYNOTES		
CONDITION	6	
CONDITIONDATE		
CONDITIONCOMMENT		
SECURELINK		
DOCUMENTATIONLINK		
ODOMETER		

AGE	4
JSEFULLIFE	10
REMAININGLIFE	6
DISPOSALDATE	
DISPOSALVALUE	
DEPRECIATIONLIFE	10
REPLACEMENTYEAR	2028
CURRENTREPLACEMENTCOS	T 0