



## Custom Track Service Percent Worn

FINNING INTERNATIONAL INC.

LINCOLN COUNTY OILFIELD SERVICES  
drayton

Prepared By: Shahir Rahman

<b>Model</b>	329FL	<b>Inspection Date</b>	06May25
<b>Manufacturer</b>	Caterpillar	<b>Next Inspection Date</b>	16May35
<b>Serial Number</b>	ERL00512	<b>Next Inspection Hours</b>	9847
<b>Reference Number</b>	BH512	<b>Underfoot Conditions</b>	
<b>Hour Meter Reading</b>	8488	<b>Impact</b>	Moderate
<b>Hours Per Week</b>	5.8	<b>Abrasion</b>	Moderate
<b>Total Odometer Reading</b>	--	<b>Moisture</b>	Moderate
<b>Forward Odometer</b>	--	<b>Packing</b>	Moderate
<b>Reverse Odometer</b>	--	<b>Bushing Allowable Wear</b>	Greater
<b>Distance Per Week</b>	--	<b>Link Allowable Wear</b>	Greater

Track System	Acceptable Range (mm)		Measurement (mm)		Condition	
	Min	Max	Left	Right	Left	Right
<b>Link Roller System</b>						
					26%	30%

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (mm)		Percent Worn		
Component	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	
<b>Link Assembly</b>		<b>Left: 3411417</b>				<b>Right: 3411417</b>				<b>Pitch: 8 In (203.2 Mm)</b>				<b>Sections: 50</b>	
<b>Track Links</b>	6Y1607	6Y1607	Replaced	Replaced	09Jan23	09Jan23	6927	6927	1561	1561	114.5 (D)	114.5 (D)	4%	4%	
<b>Bushing (Int)</b>	6071451	6071451	Replaced	Replaced	09Jan23	09Jan23	6927	6927	1561	1561	815.0 (T)	818.0 (T)	18%	40%	
<b>Bushing (Ext)</b>	6071451	6071451	Replaced	Replaced	09Jan23	09Jan23	6927	6927	1561	1561	65.0 (C)	64.5 (C)	29%	44%	
<b>Track Shoes</b>		<b>Left Width: 800mm</b>						<b>Right Width: 800mm</b>							
	6Y2126	6Y2126	Original	Original	26May20	26May20	5316	5316	3172	3172	26.0 (D)	25.5 (D)	16%	20%	
<b>Idlers</b>															
	4492305	4492305	Original	Original	26May20	26May20	5316	5316	3172	3172	20.5 (D)	21.0 (D)	18%	30%	
<b>Carrier Rollers</b>															
<b>Front</b>	3004545	3004545	Original	Original	26May20	26May20	5316	5316	3172	3172	158.0 (C)	159.0 (C)	12%	6%	
<b>2</b>	3004545	3004545	Original	Original	26May20	26May20	5316	5316	3172	3172	159.0 (C)	159.0 (C)	6%	6%	
<b>Track Rollers</b>															
<b>Front</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	20.0 (D)	19.5 (D)	40%	32%	
<b>2</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	19.5 (D)	20.0 (D)	32%	40%	
<b>3</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	--	--	--	--	
	<b>Condition: Guarded</b>						<b>Condition: Guarded</b>								
<b>4</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	19.5 (D)	20.5 (D)	32%	48%	
<b>5</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	--	--	--	--	
	<b>Condition: Guarded</b>						<b>Condition: Guarded</b>								
<b>6</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	20.0 (D)	21.0 (D)	40%	56%	
<b>7</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	--	--	--	--	
	<b>Condition: Guarded</b>						<b>Condition: Guarded</b>								
<b>8</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	19.5 (D)	21.0 (D)	32%	56%	
<b>9</b>	4315267	4315267	Original	Original	26May20	26May20	5316	5316	3172	3172	20.5 (D)	21.0 (D)	48%	56%	
<b>Sprockets</b>															
	4492308	4492308	Replaced	Replaced	09Jan23	09Jan23	6927	6927	1561	1561	--	--	--	--	
	<b>Condition: Good</b>						<b>Condition: Good</b>								

## Recommendations