



Commercial Vehicle Inspection Report

Decal Number: GL21735
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21549237

Inspection Result:

PASS

FACILITY:	DUN RITE TRUCK AND TRAILER REP / S15260	INSP. TYPE:	Complete	INSP. START:	2025-Oct-23 02:30 PM PDT
INSPECTOR:	ADAMS, TREY JUSTIN / 114796	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Oct-29 04:30 PM PDT
WORK ORDER #:	3003	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	12805590	VIN:	3ALPGND16JDJC8276
PLATE #:		UNIT/FLEET#:	527	OWNER/LESSEE NAME:	ROD & DOUG, WEBBER LOGGING L
LICENCED GVW(kg):	63500	BODY STYLE:	Logging Truck	ADDRESS:	2988 GLENROSA RD West Kelowna, British Columbia
VEHICLE YEAR:	2018	ODOMETER:	606663 KM		V4T1H8, Canada
MAKE:	FREIGHTLIN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Repaired (same day)	REAR AXLE TORQUE ROD BUSH WORN AT DIFF END, BOTH STEER REAR UPPER HANGER BUSHINGS STARTING TO SHOW WEAR(PWC)
Section 3 - Brake System	Not Applicable	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day)	R/WASHER SPRAYER NOT IN PLACE
Section 6 - Lamps	Repaired (same day)	R/REVERSE LAMP MISSING, L/SIDE DOOR SKIRT ONE MARKER IN/OP
Section 7 - Electrical System	Repaired (same day)	CHECK ENG LAMP ON, ABS LAMP ON
Section 8 - Frame and Body	Repaired (same day)	L/MIRROR AND CONVEX MIRROR GLASS CRACKED
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	NO SLACK PINTLE IN/OP
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Tire Tread Depth (mm)						
				Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24LL	Automatic	44	41	11.1			11.1	✓
2	Clamp	30L	Automatic	51	54	10.3	6.4	10.3	10.3	
3	Clamp	30L	Automatic	57	54	16.7	16.7	13.5	18.3	
4	Clamp	30L	Automatic	44	51	7.1	4.8	4.8	7.9	

Comment:

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

10/30/2025 8:23:43 AMPDT



Commercial Vehicle Inspection Report

Decal Number: GL21736
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21549269

Inspection Result:

PASS

FACILITY:	DUN RITE TRUCK AND TRAILER REP / S15260	INSP. TYPE:	Complete	INSP. START:	2025-Oct-23 04:10 PM PDT
INSPECTOR:	ADAMS, TREY JUSTIN / 114796	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Oct-29 05:00 PM PDT
WORK ORDER #:	3004	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	10648673	VIN:	2A9L43041DV147005
PLATE #:	18507K	UNIT/FLEET#:	Q104	OWNER/LESSEE NAME:	ROD & DOUG, WEBBER LOGGING L
LICENCED GVW(kg):	999999	BODY STYLE:	LOGGING TRAILER	ADDRESS:	2988 GLENROSA RD West Kelowna, British Columbia V4T 1H8, Canada
VEHICLE YEAR:	2013	ODOMETER:			
MAKE:	ANSER	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) REACH LOCK POT LEAKS WHEN ACTIVATED, #2 L/BRAKE POT AIR LEAK AT EMERG FITTING, MULTIPLE GLAD HAND RUBBERS TORN/WORN
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) R/REAR SIDE MARKER IN/OP, REAR TRI LAMPS DANGLING/PUSHED IN
Section 7 - Electrical System	Repaired (same day) ABS LAMP ON
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) L/#3 INSIDE TIRE BULGED/CORD OUT
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Tire Tread Depth (mm)						
				Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	47	41	18.3	12.7	11.9	15.9	
2	Clamp	30	Automatic	51	44	4	6.4	14.3	14.3	
3	Clamp	30	Automatic	44	41	15.9	18.3	20.6	19.1	
4	Clamp	30	Automatic	38	41	20.6	20.6	13.5	19.8	

Comment:

Comment: L/#3 INSIDE TIRE NEW TREAD DEPTH 12/32"

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

10/30/2025 8:36:22 AM PDT